CDCU877GQLT

Manufacturer Part Number:	CDCU877GQLT
Manufacturer / Brand	N/A
Part of Description:	IC PLL CLOCK DRIVER 1.8V 52-BGA
Datasheets:	
Lead Free Status / RoHS Status:	Contains lead / RoHS non-compliant
Stock Condition:	New original, 2746 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

GET A QUOTE

CDCU877GQLT 100% New Original 2746pcs in Stock, Find CDCU877GQLT Price, Stock, datasheet at IC Components Ltd Online, buy CDCU877GQLT with warrantied. 100% guarantee confidence. RFQ CDCU877GQLT: Info@IC-Components.com

The specifications of CDCU877GQLT

Part Number	CDCU877GQLT	Manufacturer / Brand	N/A
Voltage - Supply	1.7 V ~ 1.9 V	Supplier Device Package	56-BGA MICROSTAR JUNIOR (7.0x4.5)
Series	-	Ratio - Input:Output	1:10
Packaging	Original-Reel®	Package / Case	56-VFBGA
PLL	Yes	Output	SSTL-18
Other Names	296-16758-6	Operating Temperature	-40°C ~ 85°C
Number of Circuits	1	Mounting Type	Surface Mount
Moisture Sensitivity Level (MSL)	2 (1 Year)	Main Purpose	Memory, DDR2
Input	SSTL-18	Frequency - Max	400MHz
Differential - Input:Output	Yes/Yes	Base Part Number	CDCU877
Stock Quantity	2746 pcs Stock	Category	Integrated Circuits (ICs) > Clock/Timing - Application Specific
Description	IC PLL CLOCK DRIVER 1.8V 52-BGA	Lead Free Status / RoHS Status	Contains lead / RoHS non-compliant

Keywords realted to CDCU877GQLT

CDCU877GQLT	CDCU877GQLT part	CDCU877GQLT Price	CDCU877GQLT Distributor
CDCU877GQLT Technical	CDCU877GQLT Stock	CDCU877GQLT Inventory	CDCU877GQLT Supplier
CDCU877GQLT Online Order	CDCU877GQLT Inquiry	CDCU877GQLT Image	CDCU877GQLT Picture
CDCU877GQLT pdf	CDCU877GQLT datasheet	CDCU877GQLT data sheet	CDCU877GQLT pdf datasheet
Download CDCU877GQLT datasheet	Manufacturer		

You May Be Also Be interested In:

CDCU877GQLR
Description: IC PLL CLOCK DRIVER 1.8V 52-BGA
Manufacturers: N/A
In Stock: New original, 2749 pcs Stock Available.
Quote: RFQ

CDCU877AGQLR
Description: IC PLL CLOCK DRIVER 1.8V 52-BGA
Manufacturers: N/A
In Stock: New original, 2609 pcs Stock Available.
Quote: RFQ

CDCV304PWG4
Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP
Manufacturers: N/A
In Stock: New original, 2800 pcs Stock Available.
Quote: RFQ

CDCV304TPWREP
Description: IC CLX BUFFER 1:4 200MHZ 8TSSOP
Manufacturers: N/A
In Stock: New original, 2690 pcs Stock Available.
Quote: RFQ

CDCU877A
Description: CDCU877A TI DALL
Manufacturers: TI
In Stock: New original, 2654 pcs Stock Available.
Quote: RFQ

CDCU877ZQLT
Description: IC PLL CLOCK DRIVER 1.8V 52-BGA
Manufacturers: N/A
In Stock: New original, 2805 pcs Stock Available.
Quote: RFQ

CDCR83DBQ
Description: IC DIRECT RAMBUS CLK GEN 24-QSOP
Manufacturers: N/A
In Stock: New original, 5000 pcs Stock Available.
Quote: RFQ

CDCS501PWR
Description: IC CLOCK GEN/BUFFER SSC 8TSSOP
Manufacturers: N/A
In Stock: New original, 3200 pcs Stock Available.
Quote: RFQ

CDCU877AZQLT
Description: IC PLL CLOCK DRIVER 1.8V 52-BGA
Manufacturers: N/A
In Stock: New original, 2645 pcs Stock Available.
Quote: RFQ

CDCR83DBQR
Description: IC DIRECT RAMBUS CLK GEN 24-QSOP
Manufacturers: N/A
In Stock: New original, 2500 pcs Stock Available.
Quote: RFQ

CDCU877AZQLR
Description: IC PLL CLOCK DRIVER 1.8V 52-BGA
Manufacturers: N/A
In Stock: New original, 2788 pcs Stock Available.
Quote: RFQ

CDCUA877ZQLR
Description: IC PLL CLOCK DRIVER 1.8V 52-BGA
Manufacturers: N/A
In Stock: New original, 17000 pcs Stock Available.
Quote: RFQ

CDCS503PWR
Description: IC CLK BUFFER 1:1 108MHZ 8TSSOP
Manufacturers: N/A
In Stock: New original, 2834 pcs Stock Available.
Quote: RFQ

CDCV850DGGR
Description: IC PLL CLOCK DRVR 2.5V 48-TSSOP
Manufacturers: N/A
In Stock: New original, 2855 pcs Stock Available.
Quote: RFQ

CDCU877ZQLR
Description: IC PLL CLOCK DRIVER 1.8V 52-BGA
Manufacturers: N/A
In Stock: New original, 5000 pcs Stock Available.
Quote: RFQ

CDCUA877ZQLT
Description: IC PLL CLOCK DRIVER 1.8V 52-BGA
Manufacturers: N/A
In Stock: New original, 2858 pcs Stock Available.
Quote: RFQ

CDCV304PWR
Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP
Manufacturers: N/A
In Stock: New original, 56000 pcs Stock Available.
Quote: RFQ

CDCU877ARHAR
Description: IC PLL CLOCK DRIVER 1.8V 40VQFN
Manufacturers: N/A
In Stock: New original, 2749 pcs Stock Available.
Quote: RFQ

CDCV304PWRG4
Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP
Manufacturers: N/A
In Stock: New original, 13000 pcs Stock Available.
Quote: RFQ

CDCU877RHAR
Description: IC PLL CLOCK DRIVER 1.8V 40VQFN
Manufacturers: N/A
In Stock: New original, 2735 pcs Stock Available.
Quote: RFQ

CDCS503PW
Description: IC CLK BUFFER 1:1 108MHZ 8TSSOP
Manufacturers: N/A
In Stock: New original, 2783 pcs Stock Available.
Quote: RFQ

CDCV304PWR-TR
Description: TI TSSOP-8
Manufacturers: TI
In Stock: New original, 6000 pcs Stock Available.
Quote: RFQ

CDCU877RHAT
Description: IC PLL CLOCK DRIVER 1.8V 40VQFN
Manufacturers: N/A
In Stock: New original, 2823 pcs Stock Available.
Quote: RFQ

CDCV304PW
Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP
Manufacturers: N/A
In Stock: New original, 6600 pcs Stock Available.
Quote: RFQ

CDCU877ARHARG4
Description: IC PLL CLOCK DRIVER 1.8V 40VQFN
Manufacturers: N/A
In Stock: New original, 2656 pcs Stock Available.
Quote: RFQ

CDCV304
Description: CDCV304 TEXAS TPSO8
Manufacturers: TEXAS
In Stock: New original, 2736 pcs Stock Available.
Quote: RFQ

CDCS503TPWRQ1
Description: IC CLK BUFFER 1:1 108MHZ 8TSSOP
Manufacturers: N/A
In Stock: New original, 2685 pcs Stock Available.
Quote: RFQ

CDCS502PWR
Description: JC OSC CLOCK GENERATOR 8-TSSOP
Manufacturers: N/A
In Stock: New original, 2770 pcs Stock Available.
Quote: RFQ

CDCU1208LPRH8T
Description: IC CLK BUFFER 2:8 400MHZ 32QFN
Manufacturers: N/A
In Stock: New original, 2792 pcs Stock Available.
Quote: RFQ

CDCU2A877ZQLR
Description: IC PLL CLOCK DRIVER 1.8V 52-BGA
Manufacturers: N/A
In Stock: New original, 23600 pcs Stock Available.
Quote: RFQ

IC Components Limited
WWW.IC-COMPONENTS.COM

Email: Info@IC-Components.com
TEL: 00 852 - 30501935
FAX: 00 852 - 30501945
Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong