

2595FB39A0050E

Manufacturer Part Number:	2595FB39A0050E
Manufacturer / Brand	Johanson Technology
Part of Description:	BALUN DUAL 50/50 1008 6 PC PAD
Datasheets:	2595FB39A0050E.pdf
Lead Free Status / RoHS Status:	Lead free by exemption / RoHS Compliant
Stock Condition:	New original, 13500 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

2595FB39A0050E 100% New Original 13500pcs in Stock, Find 2595FB39A0050E Price, Stock, datasheet at IC Components Ltd Online, buy 2595FB39A0050E Johanson Technology with warrantied. 100% guarantee confidence. RFQ 2595FB39A0050E: Info@IC-Components.com































The specifications of 2595FB39A0050E

Part Number	2595FB39A0050E	Manufacturer / Brand	Johanson Technology
Series	-	Return Loss (Min)	11.7dB, 9.5dB
Phase Difference	180° ±10°	Packaging	Original-Reel®
Package / Case	1008 (2520 Metric), 6 PC Pad	Other Names	712-1405-6
Mounting Type	Surface Mount	Moisture Sensitivity Level (MSL)	1 (Unlimited)
Insertion Loss (Max)	3.2dB, 3.3dB	Impedance - Unbalanced/Balanced	50 / 50 Ohm
Frequency Range	2.5GHz ~ 2.69GHz, 2.469GHz ~ 2.69GHz	Detailed Description	RF Balun 2.5GHz ~ 2.69GHz, 2.469GHz ~ 2.69GHz 50 / 50 Ohm 1008 (2520 Metric), 6 PC Pad
Stock Quantity	13500 pcs Stock	Category	RF/IF and RFID > Balun
Description	BALUN DUAL 50/50 1008 6 PC PAD	Lead Free Status / RoHS Status	Lead free by exemption / RoHS Compliant

Keywords realted to 2595FB39A0050E

Johanson Technology 2595FB39A0050E	2595FB39A0050E part	2595FB39A0050E Price	2595FB39A0050E Distributor
2595FB39A0050E Technical	2595FB39A0050E Stock	2595FB39A0050E Inventory	2595FB39A0050E Supplier
2595FB39A0050E Online Order	2595FB39A0050E Inquiry	2595FB39A0050E Image	2595FB39A0050E Picture
2595FB39A0050E pdf	2595FB39A0050E datasheet	2595FB39A0050E data sheet	2595FB39A0050E pdf datasheet
Download 2595FB39A0050E datasheet	Johanson Technology Manufacturer	Johanson Technology 2595FB39A0050E	Johanson 2595FB39A0050E
Johanson Technology Inc. 2595FB39A0050E			

You May Be Also Be interested In:

 <p>RFBLN1608050AM8T62 Description: BALUN 2.4GHZ-2.5GHZ 50/50 6SMD Manufacturers: Walsin Technology In Stock: New original, 2500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>MABA-009594-CF18A0 Description: BALUN 5MHZ-200MHZ 1:1 6SMD GW Manufacturers: Aeroflex (MACOM Technology Solutions) In Stock: New original, 4500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p>  <p>2597M-3.3 Description: 2597M-3.3 NS SOP8 Manufacturers: NS In Stock: New original, 2606 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>2593A20 Description: SKYWORKS Manufacturers: SKYWORKS In Stock: New original, 5000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>HHM1524B1 Description: BALUN 880MHZ-960MHZ 50/150 0805 Manufacturers: TDK Corporation In Stock: New original, 6700 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>2450BM15A0015E Description: BALUN 2.4GHZ-2.5GHZ 0805 Manufacturers: Johanson Technology In Stock: New original, 2800 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>3700BL15B100E Description: BALUN 3.4GHZ-4GHZ 50/100 0805 Manufacturers: Johanson Technology In Stock: New original, 3200 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>HHM1526 Description: BALUN 1.71-1.99GHZ 50/100 0805 Manufacturers: TDK Corporation In Stock: New original, 6700 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>RFBLN2012090A1T Description: BALUN 2.4GHZ-2.5GHZ 50/100 6SMD Manufacturers: Walsin Technology In Stock: New original, 106000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p>  <p>259A9872P2 Description: 259A9872P2 DIP 99 Manufacturers: DIP In Stock: New original, 2677 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p>  <p>2594HM-ADJ Description: NS SOP8 Manufacturers: NS In Stock: New original, 2868 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>C6058NL Description: IC CHIP Manufacturers: Pulse Electronics Corporation In Stock: New original, 2657 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>RFXF6553-TR13 Description: SMT TRANSFORMER 10MHZ-1.9GHZ Manufacturers: RFMD In Stock: New original, 2602 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>2595FB16A0100E Description: BALUN 2.3GHZ-2.69GHZ 50/100 0806 Manufacturers: Johanson Technology In Stock: New original, 8100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>BAL-CW1250D3 Description: BALUN 2.4GHZ-2.5GHZ 5UFBGA FCBGA Manufacturers: STMicroelectronics In Stock: New original, 5000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>HHM1906A1 Description: BALUN 4.9GHZ-5.95GHZ 50/75 0402 Manufacturers: TDK Corporation In Stock: New original, 10000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>259A9871P3 Description: 259A9871P3 INTERSIL ZIP9 Manufacturers: INTERSIL In Stock: New original, 2859 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>MABA-007681-CT2010 Description: BALUN 5MHZ-1.2GHZ 1:2 4SMD Manufacturers: Aeroflex (MACOM Technology Solutions) In Stock: New original, 2720 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>2595FB39A0050T Description: 2595FB39A0050T JOHANSON SMD Manufacturers: JOHANSON In Stock: New original, 96000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>ATB2012-75011-T000 Description: BALUN 50MHZ-1.2GHZ 75/75 0805 Manufacturers: TDK Corporation In Stock: New original, 51500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>BD0826J50200AHF Description: BALUN 800MHZ-2.6GHZ 50/200 0805 Manufacturers: Anaren In Stock: New original, 4700 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>2345FB39A0050E Description: BALUN 2.3GHZ-2.39GHZ 50/50 1008 Manufacturers: Johanson Technology In Stock: New original, 11100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>HHM1726P1 Description: BALUN 880MHZ-960MHZ 50/100 0603 Manufacturers: TDK Corporation In Stock: New original, 9900 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>BALF-NRG-01D3 Description: BALUN 2.4GHZ-2.5GHZ 50/50 4WFBGA Manufacturers: STMicroelectronics In Stock: New original, 14900 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>2500BL14M100T Description: BALUN 2.3GHZ-2.7GHZ 50/100 0603 Manufacturers: Johanson Technology In Stock: New original, 11000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>HHM1520A2 Description: BALUN 2.3GHZ-2.5GHZ 50/100 0805 Manufacturers: TDK In Stock: New original, 74000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>MABACT0063 Description: BALUN 5MHZ-1GHZ 1.5:1 6SMD FLAT Manufacturers: Aeroflex (MACOM Technology Solutions) In Stock: New original, 2789 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>HHM1711E1 Description: BALUN 2.3GHZ-2.7GHZ 50/100 0603 Manufacturers: TDK Corporation In Stock: New original, 12000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p>  <p>259A9873P4 Description: 259A9873P4 TO-11P 99 Manufacturers: TO-11P In Stock: New original, 2810 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>HHM1521 Description: BALUN 2.4GHZ-2.5GHZ 50/200 0805 Manufacturers: TDK Corporation In Stock: New original, 21500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>



IC Components Limited
WWW.IC-COMPONENTS.COM

Email: Info@IC-Components.com

TEL: 00 852 - 30501935

FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong