



DXP18BN5014HL

Manufacturer Part Number:	DXP18BN5014HL
Manufacturer / Brand	Murata Electronics
Part of Description:	BALUN 470MHZ-790MHZ 50/200 0603
Datasheets:	DXP18BN5014HL.pdf
Lead Free Status / RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	New original, 3600 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

DXP18BN5014HL 100% New Original 3600pcs in Stock, Find DXP18BN5014HL Price, Stock, datasheet at IC Components Ltd Online, buy DXP18BN5014HL Murata Electronics with warrantied. 100% guarantee confidence. RFQ DXP18BN5014HL: Info@IC-Components.com

The specifications of DXP18BN5014HL

Part Number	DXP18BN5014HL	Manufacturer / Brand	Murata Electronics
Series	-	Return Loss (Min)	-
Phase Difference	-	Packaging	Original-Reel®
Package / Case	0603 (1608 Metric)	Other Names	490-7983-6
Mounting Type	Surface Mount	Moisture Sensitivity Level (MSL)	1 (Unlimited)
Insertion Loss (Max)	1.2dB	Impedance - Unbalanced/Balanced	50 / 200 Ohm
Frequency Range	470MHz ~ 790MHz	Detailed Description	RF Balun 470MHz ~ 790MHz 50 / 200 Ohm 0603 (1608 Metric)
Stock Quantity	3600 pcs Stock	Category	RF/IF and RFID > Balun
Description	BALUN 470MHZ-790MHZ 50/200 0603	Lead Free Status / RoHS Status	Lead free / RoHS Compliant

Keywords realted to DXP18BN5014HL

Murata Electronics DXP18BN5014HL	DXP18BN5014HL part	DXP18BN5014HL Price	DXP18BN5014HL Distributor
DXP18BN5014HL Technical	DXP18BN5014HL Stock	DXP18BN5014HL Inventory	DXP18BN5014HL Supplier
DXP18BN5014HL Online Order	DXP18BN5014HL Inquiry	DXP18BN5014HL Image	DXP18BN5014HL Picture
DXP18BN5014HL pdf	DXP18BN5014HL datasheet	DXP18BN5014HL data sheet	DXP18BN5014HL pdf datasheet
Download DXP18BN5014HL datasheet	Murata Electronics Manufacturer	Murata Electronics DXP18BN5014HL	MURATA DXP18BN5014HL
Murata Electronics North America DXP18BN5014HL	TOKO / Murata DXP18BN5014HL		

You May Be Also Be interested In:

<p>3600BL14M100T Description: BALUN 3.3GHZ-3.9GHZ 50/100 0603 Manufacturers: Johanson Technology In Stock: New original, 13000 pcs Stock Available. Quote: RFQ</p>	<p>LDB212G4005C-001 Description: BALUN 2.3GHZ-2.5GHZ 50/50 0805 Manufacturers: Murata Electronics In Stock: New original, 52000 pcs Stock Available. Quote: RFQ</p>	<p>DXP18BN5014TL Description: BALUN 50MHZ-870MHZ 50/200 0603 Manufacturers: Murata Electronics In Stock: New original, 32000 pcs Stock Available. Quote: RFQ</p>
<p>HHM1752A2 Description: BALUN 4.9GHZ-5.95GHZ 50/200 0603 Manufacturers: TDK Corporation In Stock: New original, 111000 pcs Stock Available. Quote: RFQ</p>	<p>HHM1726P1 Description: BALUN 880MHZ-960MHZ 50/100 0603 Manufacturers: TDK Corporation In Stock: New original, 9900 pcs Stock Available. Quote: RFQ</p>	<p>LDB182G4505C-110 Description: BALUN 2.4GHZ-2.5GHZ 50/50 0603 Manufacturers: Murata Electronics In Stock: New original, 17500 pcs Stock Available. Quote: RFQ</p>
<p>BALF-2690-02D3 Description: BALUN 2.4GHZ-2.5GHZ 4UFBGA FCBGA Manufacturers: STMicroelectronics In Stock: New original, 5000 pcs Stock Available. Quote: RFQ</p>	<p>HHM1534 Description: BALUN DUAL 50/200 0805 Manufacturers: TDK Corporation In Stock: New original, 2674 pcs Stock Available. Quote: RFQ</p>	<p>BD2425J50100AHF Description: BALUN 2.4GHZ-2.5GHZ 50/100 0805 Manufacturers: Anaren In Stock: New original, 3100 pcs Stock Available. Quote: RFQ</p>
<p>HHM1711D1 Description: BALUN 2.4GHZ-2.5GHZ 50/100 0603 Manufacturers: TDK Corporation In Stock: New original, 28500 pcs Stock Available. Quote: RFQ</p>	<p>BD0826J50200AHF Description: BALUN 800MHZ-2.6GHZ 50/200 0805 Manufacturers: Anaren In Stock: New original, 4700 pcs Stock Available. Quote: RFQ</p>	<p>HHM1733B1 Description: BALUN 4.9GHZ-5.95GHZ 50/50 0603 Manufacturers: TDK Corporation In Stock: New original, 16000 pcs Stock Available. Quote: RFQ</p>
<p>5400BL15B050E Description: BALUN 4.9GHZ-5.9GHZ 50/50 0805 Manufacturers: Johanson Technology In Stock: New original, 28500 pcs Stock Available. Quote: RFQ</p>	<p>5512BL15B100E Description: BALUN 5.15-5.875GHZ 50/100 0805 Manufacturers: Johanson Technology In Stock: New original, 4000 pcs Stock Available. Quote: RFQ</p>	<p>HHM1562B Description: BALUN 5.15-5.875GHZ 50/100 0805 Manufacturers: TDK Corporation In Stock: New original, 9900 pcs Stock Available. Quote: RFQ</p>
<p>DXP18CN7510TL Description: RF DIR COUPLER 50MHZ-870MHZ 0603 Manufacturers: Murata Electronics In Stock: New original, 4800 pcs Stock Available. Quote: RFQ</p>	<p>MABA-007681-CT2010 Description: BALUN 5MHZ-1.2GHZ 1:2 4SMD Manufacturers: Aeroflex (MACOM Technology Solutions) In Stock: New original, 2720 pcs Stock Available. Quote: RFQ</p>	<p>MABA-010125-TC1113 Description: E-SERIES TRANSFORMER 4.5-3000MHZ Manufacturers: M/A-COM Technology Solutions In Stock: New original, 2807 pcs Stock Available. Quote: RFQ</p>
<p>DXP252690DT-5031A3 Description: TDK SMD Manufacturers: TDK In Stock: New original, 2800 pcs Stock Available. Quote: RFQ</p>	<p>HHM1932A2 Description: BALUN 862MHZ-894MHZ 50/100 0402 Manufacturers: TDK Corporation In Stock: New original, 20000 pcs Stock Available. Quote: RFQ</p>	<p>RFXF8553-TR13 Description: SMT TRANSFORMER 500MHZ-2.5GHZ Manufacturers: RFMD In Stock: New original, 3900 pcs Stock Available. Quote: RFQ</p>
<p>HHM1517 Description: BALUN 2.4GHZ-2.5GHZ 50/50 0805 Manufacturers: TDK Corporation In Stock: New original, 124000 pcs Stock Available. Quote: RFQ</p>	<p>DXP2ABN7514TL Description: BALUN 50MHZ-870MHZ 75/300 0804 Manufacturers: Murata Electronics In Stock: New original, 3900 pcs Stock Available. Quote: RFQ</p>	<p>3600BL14M050T Description: BALUN 3.3GHZ-3.9GHZ 50/50 0603 Manufacturers: Johanson Technology In Stock: New original, 4000 pcs Stock Available. Quote: RFQ</p>
<p>DXW21BN7511TL Description: BALUN 50MHZ-870MHZ 75/75 0805 Manufacturers: Murata Electronics In Stock: New original, 58800 pcs Stock Available. Quote: RFQ</p>	<p>HHM1715E1 Description: BALUN 3.3GHZ-3.9GHZ 50/100 0603 Manufacturers: TDK Corporation In Stock: New original, 8000 pcs Stock Available. Quote: RFQ</p>	<p>2450BL15B200E Description: BALUN 2.4GHZ-2.5GHZ 50/200 0805 Manufacturers: Johanson Technology In Stock: New original, 10800 pcs Stock Available. Quote: RFQ</p>
<p>DXP18CN7510T Description: DXP18CN7510T MURATA SMD Manufacturers: MURATA In Stock: New original, 2758 pcs Stock Available. Quote: RFQ</p>	<p>2345FB39A0050E Description: BALUN 2.3GHZ-2.39GHZ 50/50 1008 Manufacturers: Johanson Technology In Stock: New original, 11100 pcs Stock Available. Quote: RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>DXP18BN5014T Description: DXP18BN5014T MUARATA SMD Manufacturers: MUARATA In Stock: New original, 2752 pcs Stock Available. Quote: RFQ</p>



IC Components Limited
WWW.IC-COMPONENTS.COM

Email: Info@IC-Components.com
TEL: 00 852 - 30501935
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong