



**LDM181G9310CC001**

|                                 |  |
|---------------------------------|--|
| Manufacturer Part Number:       | LDM181G9310CC001                         |
| Manufacturer / Brand:           | Murata Electronics                       |
| Part of Description:            | BALUN 1.71-2.155GHZ 50/100 0603          |
| Datasheets:                     | LDM181G9310CC001.pdf                     |
| Lead Free Status / RoHS Status: | Lead free / RoHS Compliant               |
| Stock Condition:                | New original, 67100 pcs Stock Available. |
| Ship From:                      | Hong Kong                                |
| Shipment Way:                   | DHL/Fedex/TNT/UPS                        |

[GET A QUOTE](#)

LDM181G9310CC001 100% New Original 67100pcs in Stock, Find LDM181G9310CC001 Price, Stock, datasheet at IC Components Ltd Online, buy LDM181G9310CC001 Murata Electronics with warrantied. 100% guarantee confidence. RFQ LDM181G9310CC001: [Info@IC-Components.com](mailto:Info@IC-Components.com)































The specifications of LDM181G9310CC001

|                                |                              |                                  |   |
|--------------------------------|------------------------------|----------------------------------|---|
| Part Number                    | LDM181G9310CC001             | Manufacturer / Brand             | Murata Electronics  |
| Series                         | LDM18                        | Moisture Sensitivity Level (MSL) | 1 (Unlimited)   |
| Package / Case                 | 0603 (1608 Metric), 6 PC Pad | Packaging                        | Tape & Reel (TR)  |
| Mounting Type                  | Surface Mount                | Detailed Description             | RF Balun 1.71GHz ~ 2.155GHz 50 / 100 Ohm 0603 (1608 Metric), 6 PC Pad |
| Frequency Range                | 1.71GHz ~ 2.155GHz           | Impedance - Unbalanced/Balanced  | 50 / 100 Ohm  |
| Phase Difference               | -                            | Insertion Loss (Max)             | 0.95dB  |
| Return Loss (Min)              | -                            | Stock Quantity                   | 67100 pcs Stock   |
| Category                       | RF/IF and RFID > Balun       | Description                      | BALUN 1.71-2.155GHZ 50/100 0603                                       |
| Lead Free Status / RoHS Status | Lead free / RoHS Compliant   |                                  |   |

Keywords realted to LDM181G9310CC001

|                                     |                                 |                                     |                                |
|-------------------------------------|---------------------------------|-------------------------------------|--------------------------------|
| Murata Electronics LDM181G9310CC001 | LDM181G9310CC001 part           | LDM181G9310CC001 Price              | LDM181G9310CC001 Distributor   |
| LDM181G9310CC001 Technical          | LDM181G9310CC001 Stock          | LDM181G9310CC001 Inventory          | LDM181G9310CC001 Supplier      |
| LDM181G9310CC001 Online Order       | LDM181G9310CC001 Inquiry        | LDM181G9310CC001 Image              | LDM181G9310CC001 Picture       |
| LDM181G9310CC001 pdf                | LDM181G9310CC001 datasheet      | LDM181G9310CC001 data sheet         | LDM181G9310CC001 pdf datasheet |
| Download LDM181G9310CC001 datasheet | Murata Electronics Manufacturer | Murata Electronics LDM181G9310CC001 | MURATA LDM181G9310CC001        |
| Murata Electronics North America    | TOKO / Murata LDM181G9310CC001  |                                     |                                |
| LDM181G9310CC001                    |                                 |                                     |                                |

You May Be Also Be interested In:

|  |  |  |
|--|--|--|
|  <p><b>LFB182G45BG5D920</b><br/>Description: BALUN 2.4GHZ-2.5GHZ 6SMD<br/>Manufacturers: Murata Electronics<br/>In Stock: New original, 10800 pcs Stock Available.<br/>Quote: <input type="button" value="RFQ"/></p>         |  <p><b>2450FB15K0005E</b><br/>Description: BALUN 2.4GHZ-2.5GHZ 0805<br/>Manufacturers: Johanson Technology<br/>In Stock: New original, 24400 pcs Stock Available.<br/>Quote: <input type="button" value="RFQ"/></p>         |  <p><b>HHM1526</b><br/>Description: BALUN 1.71-1.99GHZ 50/100 0805<br/>Manufacturers: TDK Corporation<br/>In Stock: New original, 7400 pcs Stock Available.<br/>Quote: <input type="button" value="RFQ"/></p>                           |
|  <p><b>BAL-NRF01D3</b><br/>Description: BALUN 2.4GHZ-2.54GHZ 5WFBGA<br/>Manufacturers: STMicroelectronics<br/>In Stock: New original, 2100 pcs Stock Available.<br/>Quote: <input type="button" value="RFQ"/></p>            |  <p><b>LDB182G4510C-110</b><br/>Description: BALUN 2.4GHZ-2.5GHZ 50/100 0603<br/>Manufacturers: Murata Electronics<br/>In Stock: New original, 28000 pcs Stock Available.<br/>Quote: <input type="button" value="RFQ"/></p> |  <p><b>BALF-NRG-01D3</b><br/>Description: BALUN 2.4GHZ-2.5GHZ 50/50 4WFBGA<br/>Manufacturers: STMicroelectronics<br/>In Stock: New original, 14900 pcs Stock Available.<br/>Quote: <input type="button" value="RFQ"/></p>               |
|  <p><b>LDM185G4210CC001</b><br/>Description: BALUN 4.9GHZ-5.95GHZ 50/100 0603<br/>Manufacturers: Murata Electronics<br/>In Stock: New original, 14500 pcs Stock Available.<br/>Quote: <input type="button" value="RFQ"/></p> |  <p><b>2450FB39B100E</b><br/>Description: BALUN 2.4GHZ-2.5GHZ 50/100 1008<br/>Manufacturers: Johanson Technology<br/>In Stock: New original, 32200 pcs Stock Available.<br/>Quote: <input type="button" value="RFQ"/></p>   |  <p><b>C2042.001NL</b><br/>Description: IC CHIP<br/>Manufacturers: Pulse Electronics Corporation<br/>In Stock: New original, 1400 pcs Stock Available.<br/>Quote: <input type="button" value="RFQ"/></p>                                |
|  <p><b>RFXF8553-TR13</b><br/>Description: SMT TRANSFORMER 500MHZ-2.5GHZ<br/>Manufacturers: RF Solutions<br/>In Stock: New original, 3900 pcs Stock Available.<br/>Quote: <input type="button" value="RFQ"/></p>              |  <p><b>HHM1906A1</b><br/>Description: BALUN 4.9GHZ-5.95GHZ 50/75 0402<br/>Manufacturers: TDK Corporation<br/>In Stock: New original, 10000 pcs Stock Available.<br/>Quote: <input type="button" value="RFQ"/></p>           |  <p><b>2595FB16A0100E</b><br/>Description: BALUN 2.3GHZ-2.69GHZ 50/100 0806<br/>Manufacturers: Johanson Technology<br/>In Stock: New original, 8100 pcs Stock Available.<br/>Quote: <input type="button" value="RFQ"/></p>              |
| <p>IMAGE NOT AVAILABLE</p>  <p><b>LDM300-48S3V3</b><br/>Description: IGBT Modules<br/>Manufacturers:<br/>In Stock: New original, 1800 pcs Stock Available.<br/>Quote: <input type="button" value="RFQ"/></p>                 |  <p><b>HHM1907B1</b><br/>Description: BALUN 4.9GHZ-5.95GHZ 50/50 0402<br/>Manufacturers: TDK Corporation<br/>In Stock: New original, 89000 pcs Stock Available.<br/>Quote: <input type="button" value="RFQ"/></p>           |  <p><b>BAL-2690D3U</b><br/>Description: BALUN 2.402GHZ-2.48GHZ 4WFBGA<br/>Manufacturers: STMicroelectronics<br/>In Stock: New original, 11800 pcs Stock Available.<br/>Quote: <input type="button" value="RFQ"/></p>                    |
|  <p><b>RFXF6553-TR13</b><br/>Description: SMT TRANSFORMER 10MHZ-1.9GHZ<br/>Manufacturers: RF Solutions<br/>In Stock: New original, 100 pcs Stock Available.<br/>Quote: <input type="button" value="RFQ"/></p>                |  <p><b>BD0826J50200AHF</b><br/>Description: BALUN 800MHZ-2.6GHZ 50/200 0805<br/>Manufacturers: Anaren<br/>In Stock: New original, 4700 pcs Stock Available.<br/>Quote: <input type="button" value="RFQ"/></p>               | <p>IMAGE NOT AVAILABLE</p>  <p><b>LDM182G4505EC015</b><br/>Description: LDM182G4505EC015 0603<br/>Manufacturers: Original<br/>In Stock: New original, 28000 pcs Stock Available.<br/>Quote: <input type="button" value="RFQ"/></p>      |
|  <p><b>0896BM15A0001E</b><br/>Description: BALUN 863MHZ-928MHZ 0805<br/>Manufacturers: Johanson Technology<br/>In Stock: New original, 41200 pcs Stock Available.<br/>Quote: <input type="button" value="RFQ"/></p>          | <p>IMAGE NOT AVAILABLE</p>  <p><b>LDM75-48S5</b><br/>Description: IGBT Modules<br/>Manufacturers:<br/>In Stock: New original, 1600 pcs Stock Available.<br/>Quote: <input type="button" value="RFQ"/></p>                   |  <p><b>ATB2012-75011-T000</b><br/>Description: BALUN 50MHZ-1.2GHZ 75/75 0805<br/>Manufacturers: TDK Corporation<br/>In Stock: New original, 51500 pcs Stock Available.<br/>Quote: <input type="button" value="RFQ"/></p>                |
|  <p><b>LDM182G5010CC001</b><br/>Description: LDM182G5010CC001 murata SMD<br/>Manufacturers: Murata Electronics<br/>In Stock: New original, 25700 pcs Stock Available.<br/>Quote: <input type="button" value="RFQ"/></p>      | <p>IMAGE NOT AVAILABLE</p>  <p><b>LDM75-110S05S</b><br/>Description: IGBT Modules<br/>Manufacturers:<br/>In Stock: New original, 1500 pcs Stock Available.<br/>Quote: <input type="button" value="RFQ"/></p>                | <p>IMAGE NOT AVAILABLE</p>  <p><b>LDM182G1410LB002</b><br/>Description: LDM182G1410LB002 MRUATA 0603<br/>Manufacturers: MRUATA<br/>In Stock: New original, 20000 pcs Stock Available.<br/>Quote: <input type="button" value="RFQ"/></p> |
| <p>IMAGE NOT AVAILABLE</p>  <p><b>LDM75-11055S</b><br/>Description: IGBT Modules<br/>Manufacturers:<br/>In Stock: New original, 1500 pcs Stock Available.<br/>Quote: <input type="button" value="RFQ"/></p>                  |  <p><b>HHM1902B1</b><br/>Description: BALUN 2.4GHZ-2.5GHZ 50/50 0402<br/>Manufacturers: TDK Corporation<br/>In Stock: New original, 89000 pcs Stock Available.<br/>Quote: <input type="button" value="RFQ"/></p>            |  <p><b>5512BL15B100E</b><br/>Description: BALUN 5.15-5.875GHZ 50/100 0805<br/>Manufacturers: Johanson Technology<br/>In Stock: New original, 4000 pcs Stock Available.<br/>Quote: <input type="button" value="RFQ"/></p>                |
|  <p><b>LDM182G5010YC025</b><br/>Description: LDM182G5010YC025 MURATA SMD<br/>Manufacturers: Murata Electronics<br/>In Stock: New original, 130100 pcs Stock Available.<br/>Quote: <input type="button" value="RFQ"/></p>     |  <p><b>LDM182G4503XA013</b><br/>Description: LDM182G4503XA013 MURATA 0603<br/>Manufacturers: Murata Electronics<br/>In Stock: New original, 19700 pcs Stock Available.<br/>Quote: <input type="button" value="RFQ"/></p>    |  <p><b>HHM1517</b><br/>Description: BALUN 2.4GHZ-2.5GHZ 50/50 0805<br/>Manufacturers: TDK Corporation<br/>In Stock: New original, 124000 pcs Stock Available.<br/>Quote: <input type="button" value="RFQ"/></p>                         |



**IC Components Limited**  
WWW.IC-COMPONENTS.COM

Email: [Info@IC-Components.com](mailto:Info@IC-Components.com)  
TEL: 00 852 - 30501935  
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong