



CDCU877ZQLR

Manufacturer Part Number:	CDCU877ZQLR
Manufacturer / Brand	N/A
Part of Description:	IC PLL CLOCK DRIVER 1.8V 52-BGA
Datasheets:	
Lead Free Status / RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	New original, 5000 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

CDCU877ZQLR 100% New Original 5000pcs in Stock, Find CDCU877ZQLR Price, Stock, datasheet at IC Components Ltd Online, buy CDCU877ZQLR with warranted. 100% guarantee confidence. RFQ CDCU877ZQLR: Info@IC-Components.com

The specifications of CDCU877ZQLR

Part Number	CDCU877ZQLR	Manufacturer / Brand	N/A
Voltage - Supply	1.7 V ~ 1.9 V	Supplier Device Package	52-BGA MICROSTAR JUNIOR (7x4.5)
Series	-	Ratio - Input:Output	1:10
Packaging	Tape & Reel (TR)	Package / Case	52-VFBGA
PLL	Yes	Output	SSTL-18
Operating Temperature	-40°C ~ 85°C	Number of Circuits	1
Mounting Type	Surface Mount	Moisture Sensitivity Level (MSL)	2 (1 Year)
Main Purpose	Memory, DDR2	Input	SSTL-18
Frequency - Max	400MHz	Differential - Input:Output	Yes/Yes
Base Part Number	CDCU877	Stock Quantity	5000 pcs Stock
Category	Integrated Circuits (ICs) > Clock/Timing - Application Specific	Description	IC PLL CLOCK DRIVER 1.8V 52-BGA
Lead Free Status / RoHS Status	Lead free / RoHS Compliant		

Keywords related to CDCU877ZQLR

CDCU877ZQLR	CDCU877ZQLR part	CDCU877ZQLR Price	CDCU877ZQLR Distributor
CDCU877ZQLR Technical	CDCU877ZQLR Stock	CDCU877ZQLR Inventory	CDCU877ZQLR Supplier
CDCU877ZQLR Online Order	CDCU877ZQLR Inquiry	CDCU877ZQLR Image	CDCU877ZQLR Picture
CDCU877ZQLR pdf	CDCU877ZQLR datasheet	CDCU877ZQLR data sheet	CDCU877ZQLR pdf datasheet
Download CDCU877ZQLR datasheet	Manufacturer		

You May Be Also Be interested In:

<p>IMAGE NOT AVAILABLE</p> <p>CDCU877AZQLR Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2788 pcs Stock Available. Quote: RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCU877RHAR Description: IC PLL CLOCK DRIVER 1.8V 40VQFN Manufacturers: N/A In Stock: New original, 2735 pcs Stock Available. Quote: RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCU877ARHARG4 Description: IC PLL CLOCK DRIVER 1.8V 40VQFN Manufacturers: N/A In Stock: New original, 2656 pcs Stock Available. Quote: RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>CDCV855 Description: CDCV855 TI TSSOP28 Manufacturers: TI In Stock: New original, 2819 pcs Stock Available. Quote: RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCS502PWR Description: IC OSC CLOCK GENERATOR 8-TSSOP Manufacturers: N/A In Stock: New original, 2770 pcs Stock Available. Quote: RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCV850DGGRG4 Description: IC PLL CLOCK DRVR 2.5V 48TSSOP Manufacturers: N/A In Stock: New original, 2650 pcs Stock Available. Quote: RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>CDCU877GQLT Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2746 pcs Stock Available. Quote: RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCU877A Description: CDCU877A TI BGA Manufacturers: TI In Stock: New original, 2654 pcs Stock Available. Quote: RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCV304PWR-TR Description: TI TSSOP-8 Manufacturers: TI In Stock: New original, 6000 pcs Stock Available. Quote: RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>CDCV304PW Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 6600 pcs Stock Available. Quote: RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCU877ARHAR Description: IC PLL CLOCK DRIVER 1.8V 40VQFN Manufacturers: N/A In Stock: New original, 2749 pcs Stock Available. Quote: RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCV304TPWREP Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 2690 pcs Stock Available. Quote: RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>CDCS503PW Description: IC CLK BUFFER 1:1 108MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 2783 pcs Stock Available. Quote: RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCUA877ZQLR Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 17000 pcs Stock Available. Quote: RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCU877AGQLR Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2609 pcs Stock Available. Quote: RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>CDCV304PWG4 Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 2800 pcs Stock Available. Quote: RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCS503TPWRQ1 Description: IC CLK BUFFER 1:1 108MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 2685 pcs Stock Available. Quote: RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCU877AZQLT Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2645 pcs Stock Available. Quote: RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>CDCV304PWG4 Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 13000 pcs Stock Available. Quote: RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCUA877ZQLT Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2858 pcs Stock Available. Quote: RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCV304PWR Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 56000 pcs Stock Available. Quote: RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>CDCU877ZQLT Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2805 pcs Stock Available. Quote: RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCV850IDGGR Description: TI TSSOP Manufacturers: TI In Stock: New original, 2669 pcs Stock Available. Quote: RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCU2A877ZQLR Description: IC CLK BUFFER 1:8V 52-BGA Manufacturers: N/A In Stock: New original, 23600 pcs Stock Available. Quote: RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>CDCU877GQLR Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2749 pcs Stock Available. Quote: RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCV850DGGR Description: IC PLL CLOCK DRVR 2.5V 48-TSSOP Manufacturers: N/A In Stock: New original, 2855 pcs Stock Available. Quote: RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCUN1208LPRHBT Description: IC CLK BUFFER 2:8 400MHZ 32QFN Manufacturers: N/A In Stock: New original, 2792 pcs Stock Available. Quote: RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>CDCU877RHAT Description: IC PLL CLOCK DRIVER 1.8V 40VQFN Manufacturers: N/A In Stock: New original, 2823 pcs Stock Available. Quote: RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCS503PWR Description: IC CLK BUFFER 1:1 108MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 2834 pcs Stock Available. Quote: RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCV304 Description: CDCV304 TEXAS TSP08 Manufacturers: TEXAS In Stock: New original, 2736 pcs Stock Available. Quote: RFQ</p>



IC Components Limited
WWW.IC-COMPONENTS.COM

Email: Info@IC-Components.com
TEL: 00 852 - 30501935
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong