

IMAGE NOT AVAILABLE

CDCUN1208LPRHBT

Manufacturer Part Number: Manufacturer / Brand Part of Description: Datasheets: Lead Free Status / RoHS Status: Stock Condition:

CDCUN1208LPRHBT N/A IC CLK BUFFER 2:8 400MHZ 32QFN

Hong Kong

DHL/Fedex/TNT/UPS

Name of the American Compliant (Name of the American Compliant) New original, 2792 pcs Stock Available.

GET A QUOTE

CDCUN1208LPRHBT 100% New Original 2792pcs in Stock, Find CDCUN1208LPRHBT Price, Stock, datasheet at IC Components Ltd Online, buy CDCUN1208LPRHBT with warrantied. 100% guarantee confidence. RFQ CDCUN1208LPRHBT: Info@IC-Components.com

Ship From:

Shipment Way:

The specifications of CDCUN1208LPRHBT

Part Number	CDCUN1208LPRHBT	Manufacturer / Brand	N/A
Voltage - Supply	1.7 V ~ 3.63 V	Туре	Fanout Buffer (Distribution), Divider, Multiplexer
Supplier Device Package	32-VQFN (5x5)	Series	-
Ratio - Input:Output	2:8	Packaging	Cut Tape (CT)
Package / Case	32-VFQFN Exposed Pad	Output	HCSL, LVCMOS, LVDS
Other Names	296-38910-1	Operating Temperature	-40°C ~ 85°C
Number of Circuits	1	Mounting Type	Surface Mount
Moisture Sensitivity Level (MSL)	2 (1 Year)	Input	HCSL, LVCMOS, LVDS
Frequency - Max	400MHz	Differential - Input:Output	Yes/Yes
Detailed Description	Clock Fanout Buffer (Distribution), Divider, Multiplexer IC 2:8 400MHz 32-VFQFN Exposed Pad	Base Part Number	CDCUN1208
Stock Quantity	2792 pcs Stock	Category	Integrated Circuits (ICs) > Clock/Timing - Clock Buffers, Drivers
Description	IC CLK BUFFER 2:8 400MHZ 32QFN	Lead Free Status / RoHS Status	Lead free / RoHS Compliant

Keywords realted to CDCUN1208LPRHBT

CDCUN1208LPRHBT	CDCUN1208LPRHBT part	CDCUN1208LPRHBT Price	CDCUN1208LPRHBT Distributor
CDCUN1208LPRHBT Technical	CDCUN1208LPRHBT Stock	CDCUN1208LPRHBT Inventory	CDCUN1208LPRHBT Supplier
CDCUN1208LPRHBT Online Order	CDCUN1208LPRHBT Inquiry	CDCUN1208LPRHBT Image	CDCUN1208LPRHBT Picture
CDCUN1208LPRHBT pdf	CDCUN1208LPRHBT datasheet	CDCUN1208LPRHBT data sheet	CDCUN1208LPRHBT pdf datasheet
Download CDCUN1208LPRHBT datasheet	Manufacturer		

You May Be Also Be interested In:



IMAGE NOT

AVAILABLE

Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A

CDCV855

Manufacturers: □

CDCU2A877ZQLR

In Stock: New original, 23600 pcs Stock Available. Quote:

Description: CDCV855 TI TSSOP28

RFQ

In Stock: New original, 2819 pcs Stock Available.

Quote:

RFQ



IMAGE NOT

AVAILABLE

CDCV850DGGRG4

Manufacturers: N/A

RFQ Quote:

Description: IC PLL CLOCK DRVR 2.5V 48TSSOP

In Stock: New original, 2650 pcs Stock Available.

CDCV855-13CT

Description: CDCV855-13CT TI TSSOP

Manufacturers: TIIn Stock: New original, 2690 pcs Stock Available.

CDCU877AZQLT

Manufacturers: N/A

Description: IC PLL CLOCK DRIVER 1.8V 52-BGA

In Stock: New original, 2645 pcs Stock Available.

Quote:

Quote:

RFQ

RFQ



IMAGE NOT

AVAILABLE

IMAGE NOT

AVAILABLE

CDCU877ARHARG4

Description: IC PLL CLOCK DRIVER 1.8V 40VQFN Manufacturers: N/A In Stock: New original, 2656 pcs Stock Available.

CDCV304PWG4

Manufacturers: N/A

Quote: RFQ

Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP

In Stock: New original, 2800 pcs Stock Available.

Quote:

RFQ



Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A

CDCU877ZQLT

In Stock: New original, 2805 pcs Stock Available. RFQ Quote:

Description: IC PLL CLOCK DRIVER 1.8V 40VQFN

IMAGE NOT

AVAILABLE

IMAGE NOT

AVAILABLE

CDCV304PWR **Description:** IC CLK BUFFER 1:4 200MHZ 8TSSOP

Manufacturers: N/A

In Stock: New original, 56000 pcs Stock Available. Quote: RFQ

IMAGE NOT

AVAILABLE

IMAGE NOT

AVAILABLE

CDCV304PWR-TR

Manufacturers: ∏

Description: TI TSSOP-8

CDCV304PWRG4

Manufacturers: N/A

RFQ Quote:

Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP

In Stock: New original, 13000 pcs Stock Available.

Quote:

RFQ



In Stock: New original, 2735 pcs Stock Available.

CDCU877RHAR

Manufacturers: N/A

Quote:

CDCU877ARHAR

Description: IC PLL CLOCK DRIVER 1.8V 40VQFN Manufacturers: N/A

In Stock: New original, 2749 pcs Stock Available. RFQ Quote:



CDCU877AZQLR **Description:** IC PLL CLOCK DRIVER 1.8V 52-BGA

Manufacturers: N/A In Stock: New original, 2788 pcs Stock Available.

RFQ Quote:

CDCV850DGGR **Description:** IC PLL CLOCK DRVR 2.5V 48-TSSOP Manufacturers: N/A

In Stock: New original, 6000 pcs Stock Available.




IMAGE NOT

AVAILABLE

CDCU877AGQLR

Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A

In Stock: New original, 2609 pcs Stock Available.

Quote: RFQ



Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP Manufacturers: N/A

CDCV304TPWREP

In Stock: New original, 2690 pcs Stock Available.

Quote: RFQ




IMAGE NOT

AVAILABLE

CDCU877GQLR

Manufacturers: N/A

In Stock: New original, 2855 pcs Stock Available. RFQ Quote:

Description: IC PLL CLOCK DRIVER 1.8V 52-BGA

In Stock: New original, 2749 pcs Stock Available.



CDCV304PW

Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP Manufacturers: N/A

In Stock: New original, 6600 pcs Stock Available. Quote:

IMAGE NOT AVAILABLE

CDCV304

Description: CDCV304 TEXAS TSPO8 Manufacturers: TEXAS

In Stock: New original, 2736 pcs Stock Available.

RFQ Quote:



IMAGE NOT

AVAILABLE

CDCUA877ZQLT **Description:** IC PLL CLOCK DRIVER 1.8V 52-BGA

In Stock: New original, 2858 pcs Stock Available.

Quote:

Quote:

Quote:

RFQ

RFQ

RFQ



Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A

CDCU877GQLT

In Stock: New original, 2746 pcs Stock Available.

Quote:

RFQ

IMAGE NOT AVAILABLE

CDCV855IPWR

Description: IC PLL CLOCK DRVR 2.5V 28TSSOP Manufacturers: N/A

In Stock: New original, 2772 pcs Stock Available.

IMAGE NOT AVAILABLE

Manufacturers: N/A

CDCU877A Description: CDCU877A TI BGA **Manufacturers: ∏** In Stock: New original, 2654 pcs Stock Available.



CDCV855PW **Description:** IC 1:4 DDR PLL CLK-DRVR 28-TSSOP Manufacturers: N/A

In Stock: New original, 2784 pcs Stock Available.

RFQ Quote:

IMAGE NOT Description: IC 1:4 DDR PLL CLK-DRVR 28-TSSOP AVAILABLE



IMAGE NOT

AVAILABLE

Manufacturers: TIIn Stock: New original, 2669 pcs Stock Available.

CDCV850IDGGR

Description: TI TSSOP

In Stock: New original, 2823 pcs Stock Available.

Quote:

RFQ




IMAGE NOT

AVAILABLE

IMAGE NOT

AVAILABLE

CDCU877ZQLR

Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A **In Stock:** New original, 5000 pcs Stock Available. RFQ Quote:



Manufacturers: N/A

CDCV855PWR

In Stock: New original, 2821 pcs Stock Available. Quote: RFQ

Description: IC PLL CLOCK DRIVER 1.8V 40VQFN Manufacturers: N/A

CDCU877RHAT

RFQ Quote:



Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A

CDCUA877ZQLR

Quote: RFQ

In Stock: New original, 17000 pcs Stock Available.



Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong