



CDCU877ARHARG4

Manufacturer Part Number:	CDCU877ARHARG4
Manufacturer / Brand	N/A
Part of Description:	IC PLL CLOCK DRIVER 1.8V 40VQFN
Datasheets:	
Lead Free Status / RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	New original, 2656 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

CDCU877ARHARG4 100% New Original 2656pcs in Stock, Find CDCU877ARHARG4 Price, Stock, datasheet at IC Components Ltd Online, buy CDCU877ARHARG4 with warrantied. 100% guarantee confidence. RFQ CDCU877ARHARG4: Info@IC-Components.com

The specifications of CDCU877ARHARG4

Part Number	CDCU877ARHARG4	Manufacturer / Brand	N/A
Voltage - Supply	1.7 V ~ 1.9 V	Supplier Device Package	40-VQFN (6x6)
Series	-	Ratio - Input:Output	1:10
Packaging	Tape & Reel (TR)	Package / Case	40-VQFN Exposed Pad
PLL	Yes	Output	SSTL-18
Operating Temperature	-40°C ~ 85°C	Number of Circuits	1
Mounting Type	Surface Mount	Moisture Sensitivity Level (MSL)	3 (168 Hours)
Main Purpose	Memory, DDR2	Input	SSTL-18
Frequency - Max	400MHz	Differential - Input:Output	Yes/Yes
Base Part Number	CDCU877	Stock Quantity	2656 pcs Stock
Category	Integrated Circuits (ICs) > Clock/Timing - Application Specific	Description	IC PLL CLOCK DRIVER 1.8V 40VQFN
Lead Free Status / RoHS Status	Lead free / RoHS Compliant		

Keywords related to CDCU877ARHARG4

CDCU877ARHARG4	CDCU877ARHARG4 part	CDCU877ARHARG4 Price	CDCU877ARHARG4 Distributor
CDCU877ARHARG4 Technical	CDCU877ARHARG4 Stock	CDCU877ARHARG4 Inventory	CDCU877ARHARG4 Supplier
CDCU877ARHARG4 Online Order	CDCU877ARHARG4 Inquiry	CDCU877ARHARG4 Image	CDCU877ARHARG4 Picture
CDCU877ARHARG4 pdf	CDCU877ARHARG4 datasheet	CDCU877ARHARG4 data sheet	CDCU877ARHARG4 pdf datasheet
Download CDCU877ARHARG4 datasheet	Manufacturer		

You May Be Also Be interested In:

<p>IMAGE NOT AVAILABLE</p> <p>CDCU877A Description: CDCU877A TI BGA Manufacturers: TI In Stock: New original, 2654 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCU877AZQLR Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2788 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCR83ADBQR Description: IC DIRECT RAMBUS CLK GEN 24-QSOP Manufacturers: N/A In Stock: New original, 17500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>CDCUA877ZQLR Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 17000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCU877AGQLR Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2609 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCS502PWR Description: IC OSC CLOCK GENERATOR 8-TSSOP Manufacturers: N/A In Stock: New original, 2770 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>CDCS503PWR Description: IC CLK BUFFER 1:1 108MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 2834 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCU877RHAR Description: IC PLL CLOCK DRIVER 1.8V 40VQFN Manufacturers: N/A In Stock: New original, 2735 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCU877GQLR Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2749 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>CDCV304PW Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 6600 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCR83DBQ Description: IC DIRECT RAMBUS CLK GEN 24-QSOP Manufacturers: N/A In Stock: New original, 5000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCR83ADBQR G4 Description: CDCR83ADBQR G4 TI SSOP-24 Manufacturers: TI In Stock: New original, 2789 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>CDCUN1208LPRHBT Description: IC CLK BUFFER 2:8 400MHZ 32QFN Manufacturers: N/A In Stock: New original, 2792 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCU877GQLT Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2746 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCU877RHAT Description: IC PLL CLOCK DRIVER 1.8V 40VQFN Manufacturers: N/A In Stock: New original, 2823 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>CDCV304 Description: CDCV304 TEXAS TSP08 Manufacturers: TEXAS In Stock: New original, 2736 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCU877AZQLT Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2645 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCU877ZQLT Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2805 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>CDCR83DB Description: CDCR83DB TI SSOP Manufacturers: TI In Stock: New original, 2844 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCS503PW Description: IC CLK BUFFER 1:1 108MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 2783 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCV304PWG4 Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 2800 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>CDCS501PWR Description: IC CLOCK GEN/BUFFER SSC 8TSSOP Manufacturers: N/A In Stock: New original, 3200 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCU877ARHAR Description: IC PLL CLOCK DRIVER 1.8V 40VQFN Manufacturers: N/A In Stock: New original, 2749 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCU877ZQLR Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 5000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>CDCR83ADBQRG4 Description: IC DIRECT RAMBUS CLK GEN 24-QSOP Manufacturers: N/A In Stock: New original, 2500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCS503TPWRQ1 Description: IC CLK BUFFER 1:1 108MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 2685 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCV304PWR Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 56000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>CDCUA877ZQLT Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2858 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCU2A877ZQLR Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 23600 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCR83DBQR Description: IC DIRECT RAMBUS CLK GEN 24-QSOP Manufacturers: N/A In Stock: New original, 2500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>



IC Components Limited
WWW.IC-COMPONENTS.COM

Email: Info@IC-Components.com
TEL: 00 852 - 30501935
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong