



LB11861H-TLM-H

Manufacturer Part Number: LB11861H-TLM-H
Manufacturer / Brand: AMI Semiconductor / ON Semiconductor
Part of Description: IC MOTOR DRIVER
Datasheets:
Lead Free Status / RoHS Status: Lead free / RoHS Compliant
Stock Condition: New original, 2740 pcs Stock Available.
Ship From: Hong Kong
Shipment Way: DHL/Fedex/TNT/UPS

GET A QUOTE

LB11861H-TLM-H 100% New Original 2740pcs in Stock, Find LB11861H-TLM-H Price, Stock, datasheet at IC Components Ltd Online, buy LB11861H-TLM-H AMI Semiconductor / ON Semiconductor with warrantied. 100% guarantee confidence. RFQ LB11861H-TLM-H: Info@IC-Components.com

The specifications of LB11861H-TLM-H

| | | | |
|--------------------------------|--|----------------------------------|--------------------------------------|
| Part Number | LB11861H-TLM-H | Manufacturer / Brand | AMI Semiconductor / ON Semiconductor |
| Supplier Device Package | - | Series | * |
| Packaging | Tape & Reel (TR) | Package / Case | - |
| Mounting Type | - | Moisture Sensitivity Level (MSL) | 3 (168 Hours) |
| Detailed Description | Motor Driver | Stock Quantity | 2740 pcs Stock |
| Category | Integrated Circuits (ICs) > PMIC - Motor Drivers, Controllers | Description | IC MOTOR DRIVER |
| Lead Free Status / RoHS Status | Lead free / RoHS Compliant | | |

Keywords related to LB11861H-TLM-H

| | | | |
|---|--|--|---|
| AMI Semiconductor / ON Semiconductor LB11861H-TLM-H | LB11861H-TLM-H part | LB11861H-TLM-H Price | LB11861H-TLM-H Distributor |
| | LB11861H-TLM-H Technical | LB11861H-TLM-H Stock | LB11861H-TLM-H Inventory |
| LB11861H-TLM-H Supplier | LB11861H-TLM-H Online Order | LB11861H-TLM-H Inquiry | LB11861H-TLM-H Image |
| LB11861H-TLM-H Picture | LB11861H-TLM-H pdf | LB11861H-TLM-H datasheet | LB11861H-TLM-H data sheet |
| LB11861H-TLM-H pdf datasheet | Download LB11861H-TLM-H datasheet | AMI Semiconductor / ON Semiconductor Manufacturer | AMI Semiconductor / ON Semiconductor LB11861H-TLM-H |
| ON Semiconductor LB11861H-TLM-H | Aptina / ON Semiconductor LB11861H-TLM-H | Catalyst Semiconductor / ON Semiconductor LB11861H-TLM-H | PulseCore Semiconductor / ON Semiconductor LB11861H-TLM-H |
| Sanyo Semiconductor / ON Semiconductor LB11861H-TLM-H | | | |

You May Be Also Be interested In:

| | | |
|---|--|--|
| <p>IMAGE NOT AVAILABLE</p> <p>LB11862M-TE-L Description: LB11862M-TE-L SANYO SOP-10 Manufacturers: SANYO In Stock: New original, 9000 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p> | <p>IMAGE NOT AVAILABLE</p> <p>LB11861M-TLM-E. Description: LB11861M-TLM-E. SANYO SOP-10 Manufacturers: SANYO In Stock: New original, 2846 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p> | <p></p> <p>LB11867RV-MPB-H Description: IC MOTOR CTRL PAR/PWM SSOP16 Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 2648 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p> |
| <p>IMAGE NOT AVAILABLE</p> <p>LB11861J-NMB-TLM3-E Description: LB11861J-NMB-TLM3-E SANYO SOP Manufacturers: SANYO In Stock: New original, 39000 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p> | <p></p> <p>LB11867FV-TLM-H Description: IC MOTOR CONTROLLER PAR 16SSOP Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 4000 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p> | <p>IMAGE NOT AVAILABLE</p> <p>LB11826 Description: LB11826 SANYO DIP-28P Manufacturers: SANYO In Stock: New original, 2633 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p> |
| <p>IMAGE NOT AVAILABLE</p> <p>LB1186 Description: LB1186 SANYO原裝 SOP Manufacturers: SANYO In Stock: New original, 2807 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p> | <p>IMAGE NOT AVAILABLE</p> <p>LB11827-E Description: LB11827-E SANYO DIP28 Manufacturers: SANYO In Stock: New original, 2682 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p> | <p>IMAGE NOT AVAILABLE</p> <p>LB11867FV-ND-TLM-E Description: LB11867FV-ND-TLM-E SANYO SSOP-20 Manufacturers: SANYO In Stock: New original, 6000 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p> |
| <p></p> <p>LB11861H-TLM-E Description: IC MOTOR DRIVER Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 8000 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p> | <p></p> <p>LB11852FV-TLM-H Description: IC MOTOR CONTROLLER PAR 20SSOP Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 46000 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p> | <p>IMAGE NOT AVAILABLE</p> <p>LB11867FV-TLM Description: LB11867FV-TLM SANYO TSSOP Manufacturers: SANYO In Stock: New original, 2673 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p> |
| <p></p> <p>LB11867RV-TLM-H Description: IC MOTOR CONTROLLER PAR 16SSOP Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 2639 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p> | <p></p> <p>LB11850VA-TLM-H Description: IC MOTOR CONTROLLER PAR 24SSOP Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 10000 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p> | <p></p> <p>LB11867FV-TLM-E Description: IC MOTOR CONTROLLER PAR 16SSOP Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 10000 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p> |
| <p></p> <p>LB11862M-TLM-H Description: LB11862M-TLM-H ON SOP-10 Manufacturers: ON In Stock: New original, 2898 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p> | <p></p> <p>LB11852FV-MPB-H Description: IC MOTOR CTRL PAR/PWM SSOP20J Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 3100 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p> | <p>IMAGE NOT AVAILABLE</p> <p>LB11861M-TLM-E Description: LB11861M-TLM-E SANYO SOP10 Manufacturers: SANYO In Stock: New original, 5000 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p> |
| <p></p> <p>LB11852RV-MPB-H Description: IC MOTOR CTRL PAR/PWM SSOP20J Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 2652 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p> | <p></p> <p>LB11851TT-TLM-H Description: IC MOTOR CONTROLLER PWM 10MSOP Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 2667 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p> | <p>IMAGE NOT AVAILABLE</p> <p>LB11861M-TLM-H Description: LB11861M-TLM-H SANYO SOP10 Manufacturers: SANYO In Stock: New original, 2822 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p> |
| <p>IMAGE NOT AVAILABLE</p> <p>LB11861-N-TLM-H Description: LB11861-N-TLM-H SANYO HSOP16 Manufacturers: SANYO In Stock: New original, 2836 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p> | <p></p> <p>LB11861MC-AH Description: IC MOTOR DRIVER PWM 10MFPSK Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 3000 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p> | <p></p> <p>LB11868V-TLM-H Description: ON SOP Manufacturers: ON In Stock: New original, 2853 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p> |
| <p>IMAGE NOT AVAILABLE</p> <p>LB11851M-TE-L-E Description: LB11851M-TE-L-E SANYO SOP Manufacturers: SANYO In Stock: New original, 2708 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p> | <p></p> <p>LB11851MC-BH Description: IC MOTOR CONTROLLER PWM 10SOIC Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 2649 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p> | <p>IMAGE NOT AVAILABLE</p> <p>LB11861 Description: LB11861 ONS HSSOP-16 Manufacturers: ONS In Stock: New original, 2711 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p> |
| <p>IMAGE NOT AVAILABLE</p> <p>LB11847 Description: LB11847 SANYO DIP Manufacturers: SANYO In Stock: New original, 2611 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p> | <p>IMAGE NOT AVAILABLE</p> <p>LB11825 Description: LB11825 SANYO SOP14 Manufacturers: SANYO In Stock: New original, 13600 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p> | <p>IMAGE NOT AVAILABLE</p> <p>LB11862M-TLM-E Description: LB11862M-TLM-E SANYO SOP10 Manufacturers: SANYO In Stock: New original, 2673 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p> |



IC Components Limited
WWW.IC-COMPONENTS.COM

Email: Info@IC-Components.com
 TEL: 00 852 - 30501935
 FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong