



## CDCV850DGGR

<b>Manufacturer Part Number:</b>	CDCV850DGGR
<b>Manufacturer / Brand</b>	N/A
<b>Part of Description:</b>	IC PLL CLOCK DRVR 2.5V 48-TSSOP
<b>Datasheets:</b>	
<b>Lead Free Status / RoHS Status:</b>	Lead free / RoHS Compliant
<b>Stock Condition:</b>	New original, 2855 pcs Stock Available.
<b>Ship From:</b>	Hong Kong
<b>Shipment Way:</b>	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

**CDCV850DGGR** 100% New Original 2855pcs in Stock, Find CDCV850DGGR Price, Stock, datasheet at IC Components Ltd Online, buy CDCV850DGGR with warrantied. 100% guarantee confidence. RFQ CDCV850DGGR: [Info@IC-Components.com](mailto:Info@IC-Components.com)

### The specifications of CDCV850DGGR

Part Number	CDCV850DGGR	Manufacturer / Brand	N/A
Voltage - Supply	2.3 V ~ 2.7 V	Type	PLL Clock Driver
Supplier Device Package	48-TSSOP	Series	-
Ratio - Input:Output	1:11	Packaging	Tape & Reel (TR)
Package / Case	48-TFSOP (0.240", 6.10mm Width)	PLL	Yes with Bypass
Output	SSTL-2	Other Names	296-6721-2
Operating Temperature	0°C ~ 85°C	Number of Circuits	1
Mounting Type	Surface Mount	Moisture Sensitivity Level (MSL)	2 (1 Year)
Input	LVTTL, SSTL-2	Frequency - Max	140MHz
Divider/Multiplier	No/No	Differential - Input:Output	Yes/Yes
Base Part Number	CDCV850	Stock Quantity	2855 pcs Stock
Category	<a href="#">Integrated Circuits (ICs)</a> > <a href="#">Clock/Timing</a> - <a href="#">Clock Generators, PLLs, Frequency Synthesizers</a>	Description	IC PLL CLOCK DRVR 2.5V 48-TSSOP
Lead Free Status / RoHS Status	Lead free / RoHS Compliant		

### Keywords related to CDCV850DGGR

<a href="#">CDCV850DGGR</a>	<a href="#">CDCV850DGGR part</a>	<a href="#">CDCV850DGGR Price</a>	<a href="#">CDCV850DGGR Distributor</a>
<a href="#">CDCV850DGGR Technical</a>	<a href="#">CDCV850DGGR Stock</a>	<a href="#">CDCV850DGGR Inventory</a>	<a href="#">CDCV850DGGR Supplier</a>
<a href="#">CDCV850DGGR Online Order</a>	<a href="#">CDCV850DGGR Inquiry</a>	<a href="#">CDCV850DGGR Image</a>	<a href="#">CDCV850DGGR Picture</a>
<a href="#">CDCV850DGGR pdf</a>	<a href="#">CDCV850DGGR datasheet</a>	<a href="#">CDCV850DGGR data sheet</a>	<a href="#">CDCV850DGGR pdf datasheet</a>
<a href="#">Download CDCV850DGGR datasheet</a>	<a href="#">Manufacturer</a>		

### You May Be Also Be interested In:

<p><b>CDCV857ADGG</b> <b>Description:</b> IC SSTL-II PLL CLK-DRVR 48-TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2606 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>CDCV855PWG4</b> <b>Description:</b> IC PLL CLOCK DRVR 2.5V 28TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2640 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>CDCV304PWRG4</b> <b>Description:</b> IC CLK BUFFER 1:4 200MHZ 8TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 13000 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p><b>CDCV304PWG4</b> <b>Description:</b> IC CLK BUFFER 1:4 200MHZ 8TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2800 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>CDCV855IPWR</b> <b>Description:</b> IC PLL CLOCK DRVR 2.5V 28TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2772 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>CDCV857ADGGRG4</b> <b>Description:</b> IC SSTL-II PLL CLK-DRVR 48TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2816 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p><b>CDCV857BDGG</b> <b>Description:</b> IC SSTL-II PLL CLK-DRVR 48-TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2768 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>CDCU877RHAT</b> <b>Description:</b> IC PLL CLOCK DRIVER 1.8V 40VQFN <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2823 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>CDCU877ZQLR</b> <b>Description:</b> IC PLL CLOCK DRIVER 1.8V 52-BGA <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 5000 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p><b>CDCU877GQLT</b> <b>Description:</b> IC PLL CLOCK DRIVER 1.8V 52-BGA <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2746 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>CDCV857BDGGR</b> <b>Description:</b> IC SSTL-II PLL CLK-DRVR 48TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 26000 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>CDCU877ZQLT</b> <b>Description:</b> IC PLL CLOCK DRIVER 1.8V 52-BGA <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2805 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p><b>CDCV855</b> <b>Description:</b> CDCV855 TI TSSOP28 <b>Manufacturers:</b> TI <b>In Stock:</b> New original, 2819 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>CDCV304PWR-TR</b> <b>Description:</b> TI TSSOP-8 <b>Manufacturers:</b> TI <b>In Stock:</b> New original, 6000 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>CDCUN1208LPRHBT</b> <b>Description:</b> IC CLK BUFFER 2:8 400MHZ 32QFN <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2792 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p><b>CDCV850IDGGR</b> <b>Description:</b> TI TSSOP <b>Manufacturers:</b> TI <b>In Stock:</b> New original, 2669 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>CDCV857AQQLR</b> <b>Description:</b> IC CLK-DRVR PLL 2.5V 56-BGA <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2876 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>CDCV304PWR</b> <b>Description:</b> IC CLK BUFFER 1:4 200MHZ 8TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 56000 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p><b>CDCV857</b> <b>Description:</b> CDCV857 TI TSSOP48 <b>Manufacturers:</b> TI <b>In Stock:</b> New original, 2690 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>CDCV857ADGGR</b> <b>Description:</b> IC SSTL-II PLL CLK-DRVR 48-TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 18800 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>CDCV850DGGRG4</b> <b>Description:</b> IC PLL CLOCK DRVR 2.5V 48TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2650 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p><b>CDCV304</b> <b>Description:</b> CDCV304 TEXAS TSP08 <b>Manufacturers:</b> TEXAS <b>In Stock:</b> New original, 2736 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>CDCV855PWR</b> <b>Description:</b> IC 1:4 DDR PLL CLK-DRVR 28-TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2821 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>CDCV304TPWREP</b> <b>Description:</b> IC CLK BUFFER 1:4 200MHZ 8TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2690 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p><b>CDCU877RHAR</b> <b>Description:</b> IC PLL CLOCK DRIVER 1.8V 40VQFN <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2735 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>CDCV855-13CT</b> <b>Description:</b> CDCV855-13CT TI TSSOP <b>Manufacturers:</b> TI <b>In Stock:</b> New original, 2690 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>CDCV304PW</b> <b>Description:</b> IC CLK BUFFER 1:4 200MHZ 8TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 6600 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p><b>CDCUA877ZQLR</b> <b>Description:</b> IC PLL CLOCK DRIVER 1.8V 52-BGA <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 17000 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>CDCUA877ZQLT</b> <b>Description:</b> IC PLL CLOCK DRIVER 1.8V 52-BGA <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2858 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>CDCV855PW</b> <b>Description:</b> IC 1:4 DDR PLL CLK-DRVR 28-TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2784 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>



**IC Components Limited**  
WWW.IC-COMPONENTS.COM

Email: [Info@IC-Components.com](mailto:Info@IC-Components.com)  
TEL: 00 852 - 30501935  
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong