



A Renesas Company

CA3080AM

Manufacturer Part Number:	CA3080AM
Manufacturer / Brand	INTERSIL
Part of Description:	CA3080AM INTERSIL SOP8
Datasheets:	
Lead Free Status / RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	New original, 9400 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

CA3080AM 100% New Original 9400pcs in Stock, Find CA3080AM Price, Stock, datasheet at IC Components Ltd Online, buy CA3080AM Intersil with warranted. 100% guarantee confidence. RFQ CA3080AM: Info@IC-Components.com

The specifications of CA3080AM

Part Number	CA3080AM	Manufacturer / Brand	INTERSIL
Package	SOP8	Condition	New Original Stock
Warranty	100% Perfect Functions	Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union	Shipping by	DHL / Fedex / UPS
Port	HongKong	RFQ Email	Info@ic-components.com
Stock Quantity	9400 pcs Stock	Category	Integrated Circuits (ICs) > Specialized ICs
Description	CA3080AM INTERSIL SOP8	Lead Free Status / RoHS Status	Lead free / RoHS Compliant

Keywords related to CA3080AM

Intersil CA3080AM	CA3080AM part	CA3080AM Price	CA3080AM Distributor
CA3080AM Technical	CA3080AM Stock	CA3080AM Inventory	CA3080AM Supplier
CA3080AM Online Order	CA3080AM Inquiry	CA3080AM Image	CA3080AM Picture
CA3080AM pdf	CA3080AM datasheet	CA3080AM data sheet	CA3080AM pdf datasheet
Download CA3080AM datasheet	Intersil Manufacturer	Intersil CA3080AM	

You May Be Also Be interested In:

<p>CA3065E Description: CA3065E HAR DIP-14 Manufacturers: HAR In Stock: New original, 100 pcs Stock Available. Quote: RFQ</p>	<p>CA3059 Description: CA3059 INT DIP Manufacturers: INT In Stock: New original, 1300 pcs Stock Available. Quote: RFQ</p>	<p>CA3054MZ96 Description: IC OPAMP DIFF 550MHZ 14SOIC Manufacturers: Intersil In Stock: New original, 2900 pcs Stock Available. Quote: RFQ</p>
<p>CA3078E Description: CA3078E HARRIS DIP-8 Manufacturers: HARRIS In Stock: New original, 400 pcs Stock Available. Quote: RFQ</p>	<p>CA3078EZ Description: CA3078EZ INT DIP8 Manufacturers: INT In Stock: New original, 1400 pcs Stock Available. Quote: RFQ</p>	<p>CA3080AS Description: CA3080AS HAR CAN Manufacturers: HAR In Stock: New original, 100 pcs Stock Available. Quote: RFQ</p>
<p>CA3082 Description: CA3082 HARINTER DIP-16 Manufacturers: HARINTER In Stock: New original, 100 pcs Stock Available. Quote: RFQ</p>	<p>CA3080M Description: CA3080M INTERSI SOP8 Manufacturers: INTERSI In Stock: New original, 9700 pcs Stock Available. Quote: RFQ</p>	<p>CA3080MZ Description: CA3080MZ INTERSIL SOP8 Manufacturers: Intersil In Stock: New original, 200 pcs Stock Available. Quote: RFQ</p>
<p>CA3080AS/3 Description: CA3080AS/3 HAR CAN8 Manufacturers: HAR In Stock: New original, 200 pcs Stock Available. Quote: RFQ</p>	<p>CA3080AM96 Description: CA3080AM96 INTERSIL SOP-8 Manufacturers: Intersil In Stock: New original, 1300 pcs Stock Available. Quote: RFQ</p>	<p>CA3080A Description: CA3080A SOP-8P 03 Manufacturers: SOP-8P In Stock: New original, 700 pcs Stock Available. Quote: RFQ</p>
<p>CA3078AM96 Description: CA3078AM96 INTERSIL SOP8 Manufacturers: Intersil In Stock: New original, 3600 pcs Stock Available. Quote: RFQ</p>	<p>CA3080AE Description: CA3080AE INT DIP Manufacturers: INT In Stock: New original, 3400 pcs Stock Available. Quote: RFQ</p>	<p>CA3081E Description: CA3081E INTERSIL DIP16 Manufacturers: Intersil In Stock: New original, 200 pcs Stock Available. Quote: RFQ</p>
<p>CA3079 Description: CA3079 INT DIP Manufacturers: INT In Stock: New original, 5700 pcs Stock Available. Quote: RFQ</p>	<p>CA3081EZ Description: CA3081EZ INTRASIL DIP-16 Manufacturers: INTRASIL In Stock: New original, 100 pcs Stock Available. Quote: RFQ</p>	<p>CA3060E Description: CA3060E HAR DIP Manufacturers: HAR In Stock: New original, 100 pcs Stock Available. Quote: RFQ</p>
<p>CA3080EX Description: CA3080EX HAR DIP-8 Manufacturers: HAR In Stock: New original, 100 pcs Stock Available. Quote: RFQ</p>	<p>CA3080K Description: CA3080K H CAN Manufacturers: H In Stock: New original, 100 pcs Stock Available. Quote: RFQ</p>	<p>CA3080E Description: IC OPAMP TRANSCOND 2MHZ 8DIP Manufacturers: Intersil In Stock: New original, 6600 pcs Stock Available. Quote: RFQ</p>
<p>CA3078M96 Description: CA3078M96 INTERSIL SOP8 Manufacturers: Intersil In Stock: New original, 3900 pcs Stock Available. Quote: RFQ</p>	<p>CA3078M Description: CA3078M HARRIS SOP-8 Manufacturers: HARRIS In Stock: New original, 2300 pcs Stock Available. Quote: RFQ</p>	<p>CA3078AE Description: CA3078AE HAS DIP-8P Manufacturers: HAS In Stock: New original, 100 pcs Stock Available. Quote: RFQ</p>
<p>CA3081 Description: CA3081 INTER DIP-16 Manufacturers: INTER In Stock: New original, 7900 pcs Stock Available. Quote: RFQ</p>	<p>CA3081M Description: CA3081M INTEL SOP Manufacturers: INTEL In Stock: New original, 200 pcs Stock Available. Quote: RFQ</p>	<p>CA3080 Description: CA3080 INTERSIL SOP8 Manufacturers: Intersil In Stock: New original, 1100 pcs Stock Available. Quote: RFQ</p>
<p>CA3064E Description: CA3064E HRRIS DIP14 Manufacturers: HRRIS In Stock: New original, 500 pcs Stock Available. Quote: RFQ</p>	<p>CA3082F Description: CA3082F H NA Manufacturers: H In Stock: New original, 100 pcs Stock Available. Quote: RFQ</p>	<p>CA3083 Description: TRANS 5NPN 15V 0.1A 16DIP Manufacturers: Intersil In Stock: New original, 19100 pcs Stock Available. Quote: RFQ</p>



IC Components Limited
WWW.IC-COMPONENTS.COM

Email: Info@IC-Components.com
TEL: 00 852 - 30501935
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong