



LB11852FV-MPB-H

Manufacturer Part Number:	LB11852FV-MPB-H
Manufacturer / Brand	AMI Semiconductor / ON Semiconductor
Part of Description:	IC MOTOR CTRLR PAR/PWM SSOP20J
Datasheets:	
Lead Free Status / RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	New original, 3100 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

LB11852FV-MPB-H 100% New Original 3100pcs in Stock, Find LB11852FV-MPB-H Price, Stock, datasheet at IC Components Ltd Online, buy LB11852FV-MPB-H AMI Semiconductor / ON Semiconductor with warrantied. 100% guarantee confidence. RFQ LB11852FV-MPB-H: Info@IC-Components.com

The specifications of LB11852FV-MPB-H

Part Number	LB11852FV-MPB-H	Manufacturer / Brand	AMI Semiconductor / ON Semiconductor
Series	-	Moisture Sensitivity Level (MSL)	3 (168 Hours)
Package / Case	20-LFSOP (0.173", 4.40mm Width)	Packaging	Tube
Mounting Type	Surface Mount	Supplier Device Package	20-SSOPJ
Operating Temperature	-30°C ~ 95°C (TA)	Detailed Description	Motor Driver PWM 20-SSOPJ
Technology	-	Interface	PWM
Applications	Fan Controller	Voltage - Supply	4.5 V ~ 5.5 V, 5.5 V ~ 16 V
Function	Controller - Speed	Current - Output	-
Output Configuration	Pre-Driver - Half Bridge (2)	Voltage - Load	-
Motor Type - Stepper	-	Motor Type - AC, DC	Brushless DC (BLDC)
Step Resolution	-	Stock Quantity	3100 pcs Stock
Category	Integrated Circuits (ICs) > PMIC - Motor Drivers, Controllers	Description	IC MOTOR CTRLR PAR/PWM SSOP20J
Lead Free Status / RoHS Status	Lead free / RoHS Compliant		

Keywords related to LB11852FV-MPB-H

AMI Semiconductor / ON Semiconductor LB11852FV-MPB-H	LB11852FV-MPB-H part	LB11852FV-MPB-H Price	LB11852FV-MPB-H Distributor
	LB11852FV-MPB-H Technical	LB11852FV-MPB-H Stock	LB11852FV-MPB-H Inventory
LB11852FV-MPB-H Supplier	LB11852FV-MPB-H Online Order	LB11852FV-MPB-H Inquiry	LB11852FV-MPB-H Image
LB11852FV-MPB-H Picture	LB11852FV-MPB-H pdf	LB11852FV-MPB-H datasheet	LB11852FV-MPB-H data sheet
LB11852FV-MPB-H pdf datasheet	Download LB11852FV-MPB-H datasheet	AMI Semiconductor / ON Semiconductor Manufacturer	AMI Semiconductor / ON Semiconductor LB11852FV-MPB-H
ON Semiconductor LB11852FV-MPB-H	Aptina / ON Semiconductor LB11852FV-MPB-H	Catalyst Semiconductor / ON Semiconductor LB11852FV-MPB-H	PulseCore Semiconductor / ON Semiconductor LB11852FV-MPB-H
Sanyo Semiconductor / ON Semiconductor LB11852FV-MPB-H			

You May Be Also Be interested In:

<p>IMAGE NOT AVAILABLE</p> <p>LB11820M-MPB-E Description: LB11820M-MPB-E SANYO SOP30 Manufacturers: SANYO In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p></p> <p>LB11850VA-TLM-H Description: IC MOTOR CONTROLLER PAR 24SSOP Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 10000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>LB11813 Description: LB11813 SANYO SSOP Manufacturers: SANYO In Stock: New original, 5200 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>LB11816V-MPB-E Description: LB11816V-MPB-E SANYO SOP Manufacturers: SANYO In Stock: New original, 700 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>LB11826 Description: LB11826 SANYO DIP-28P Manufacturers: SANYO In Stock: New original, 500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>LB11861-N-TLM-H Description: LB11861-N-TLM-H SANYO HSOP16 Manufacturers: SANYO In Stock: New original, 1700 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>LB11862M-TLM-E Description: LB11862M-TLM-E SANYO SOP10 Manufacturers: SANYO In Stock: New original, 2000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p></p> <p>LB11861H-TLM-H Description: IC MOTOR DRIVER Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 1000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p></p> <p>LB11851MC-BH Description: IC MOTOR CONTROLLER PWM 10SOIC Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 2200 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>LB11851M-TE-L-E Description: LB11851M-TE-L-E SANYO SOP Manufacturers: SANYO In Stock: New original, 700 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p></p> <p>LB11861MC-AH Description: IC MOTOR DRIVER PWM 10MFPSK Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 3000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>LB11861 Description: LB11861 ONS HSSOP-16 Manufacturers: ONS In Stock: New original, 200 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>LB11698H-TE-L Description: LB11698H-TE-L SANYO SOP Manufacturers: SANYO In Stock: New original, 1000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p></p> <p>LB11851TT-TLM-H Description: IC MOTOR CONTROLLER PWM 10MSOP Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 1800 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p></p> <p>LB11852RV-MPB-H Description: IC MOTOR CTRLR PAR/PWM SSOP20J Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 1200 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>LB11861M-TLM-E Description: LB11861M-TLM-E SANYO SOP10 Manufacturers: SANYO In Stock: New original, 5000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>LB11847 Description: LB11847 SANYO DIP Manufacturers: SANYO In Stock: New original, 500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>LB11820M-TE-L Description: LB11820M-TE-L SANYO SSOP30 Manufacturers: SANYO In Stock: New original, 3200 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>LB11861J-NMB-TLM3-E Description: LB11861J-NMB-TLM3-E SANYO SOP Manufacturers: SANYO In Stock: New original, 39000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>LB11825 Description: LB11825 SANYO SOP14 Manufacturers: SANYO In Stock: New original, 13600 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>LB11862M-TE-L Description: LB11862M-TE-L SANYO SOP-10 Manufacturers: SANYO In Stock: New original, 9000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>LB11861M-TLM-E Description: LB11861M-TLM-E SANYO SOP-10 Manufacturers: SANYO In Stock: New original, 400 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>LB11822 Description: LB11822 SANYO DIP-28 Manufacturers: SANYO In Stock: New original, 1500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>LB11861M-TLM-H Description: LB11861M-TLM-H SANYO SOP10 Manufacturers: SANYO In Stock: New original, 900 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>LB11827-E Description: LB11827-E SANYO DIP28 Manufacturers: SANYO In Stock: New original, 1000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p></p> <p>LB11862M-TLM-H Description: LB11862M-TLM-H ON SOP-10 Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 700 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>LB1186 Description: LB1186 SANYO SOP Manufacturers: SANYO In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p></p> <p>LB11861H-TLM-E Description: IC MOTOR DRIVER Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 8000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p></p> <p>LB11852FV-TLM-H Description: IC MOTOR CONTROLLER PAR 20SSOP Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 46000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>LB11813V-TLM-E Description: LB11813V-TLM-E SANYO TSSOP-24 Manufacturers: SANYO In Stock: New original, 3000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>



IC Components Limited
WWW.IC-COMPONENTS.COM

Email: Info@IC-Components.com
TEL: 00 852 - 30501935
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong