



LB1938T-TLM-E

Shipment Way:

Manufacturer Part Number: Manufacturer / Brand Part of Description: Datasheets: Lead Free Status / RoHS Status: **Stock Condition: Ship From:**

LB1938T-TLM-E

Hong Kong

DHL/Fedex/TNT/UPS

IC MOTOR DRIVER PAR 8MSOP LB1938T-TLM-E.pdf 🖎 🚣 Lead free / RoHS Compliant New original, 10600 pcs Stock Available.

GET A QUOTE

LB1938T-TLM-E 100% New Original 10600pcs in Stock, Find LB1938T-TLM-E Price, Stock, datasheet at IC Components Ltd Online, buy LB1938T-TLM-E AMI Semiconductor / ON Semiconductor with warrantied. 100% guarantee confidence. RFQ LB1938T-TLM-E: Info@IC-Components.com

The specifications of LB1938T-TLM-E

Part Number	LB1938T-TLM-E	Manufacturer / Brand	AMI Semiconductor / ON Semiconductor
Series	-	Moisture Sensitivity Level (MSL)	3 (168 Hours)
Base Part Number	LB1938	Package / Case	8-TSSOP, 8-MSOP (0.118", 3.00mm Width)
Packaging	Cut Tape (CT)	Mounting Type	Surface Mount
Supplier Device Package	8-MSOP	Operating Temperature	-30°C ~ 85°C (TA)
Detailed Description	Motor Driver Bipolar Parallel 8-MSOP	Technology	Bipolar
Interface	Parallel	Applications	General Purpose
Voltage - Supply	2.2 V ~ 10 V	Function	Driver - Fully Integrated, Control and Power Stage
Current - Output	800mA	Output Configuration	Half Bridge (2)
Voltage - Load	2.2 V ~ 10 V	Motor Type - Stepper	-
Motor Type - AC, DC	Brushed DC	Step Resolution	-
Other Names	LB1938T-TLM-EOSCT LB1938TTLME	Stock Quantity	10600 pcs Stock
Category	Integrated Circuits (ICs) > PMIC - Motor Drivers, Controllers	Description	IC MOTOR DRIVER PAR 8MSOP
Lead Free Status / RoHS Status	Lead free / RoHS Compliant		

Keywords realted to LB1938T-TLM-E

AMI Semiconductor / ON Semiconductor LB1938T-	LB1938T-TLM-E part	LB1938T-TLM-E Price	LB1938T-TLM-E Distributor
TLM-E	LB1938T-TLM-E Technical	LB1938T-TLM-E Stock	LB1938T-TLM-E Inventory
LB1938T-TLM-E Supplier	LB1938T-TLM-E Online Order	LB1938T-TLM-E Inquiry	LB1938T-TLM-E Image
LB1938T-TLM-E Picture	LB1938T-TLM-E pdf	LB1938T-TLM-E datasheet	LB1938T-TLM-E data sheet
LB1938T-TLM-E pdf datasheet	Download LB1938T-TLM-E datasheet	AMI Semiconductor / ON Semiconductor Manufacturer	AMI Semiconductor / ON Semiconductor LB1938T-
			TLM-E
ON Semiconductor LB1938T-TLM-E	Aptina / ON Semiconductor LB1938T-TLM-E	Catalyst Semiconductor / ON Semiconductor LB1938T-	PulseCore Semiconductor / ON Semiconductor
		TLM-E	LB1938T-TLM-E
Sanyo Semiconductor / ON Semiconductor LB1938T-			
TLM-E			

You May Be Also Be interested In:



LB1939T-MPB-E **Description:** IC BRIDGE DRIVER PAR TSSOP-20

Semiconductor

LB1930M-TLM-E

Semiconductor

LB1947

Semiconductor In Stock: New original, 600 pcs Stock Available. RFQ Quote:

Manufacturers: AMI Semiconductor / ON

LB1933M-MPB-E

Description: IC BRIDGE DRIVER PAR MFP-14S

In Stock: New original, 700 pcs Stock Available.

Manufacturers: AMI Semiconductor / ON

RFQ Quote:

Description: IC MOTOR DRIVER PAR MFP10S

In Stock: New original, 1000 pcs Stock Available.

Quote:

Manufacturers: AMI Semiconductor / ON

Description: IC MOTOR DRIVER PAR 28HDIP Manufacturers: AMI Semiconductor / ON

LB1946-E

LB1930MC-AH

Semiconductor

Semiconductor In Stock: New original, 500 pcs Stock Available.

RFQ Quote:

Description: IC MOTOR DRIVER PAR 10SOIC

In Stock: New original, 2300 pcs Stock Available.

Quote:

RFQ

Manufacturers: AMI Semiconductor / ON

LB1945H-TLM-E **Description:** IC MOTOR DRIVER PAR 28HSOP

Manufacturers: AMI Semiconductor / ON Semiconductor

In Stock: New original, 8900 pcs Stock Available.

RFQ Quote:

LB1941T-TLM IMAGE NOT

Manufacturers: SANYO In Stock: New original, 22500 pcs Stock Available.

Description: LB1941T-TLM SANYO TSSOP-8

RFQ

IMAGE NOT

AVAILABLE

IMAGE NOT

AVAILABLE

LB1936V-TLM-E **Description:** IC MOTOR DRIVER PAR 16SSOP Manufacturers: AMI Semiconductor / ON



IMAGE NOT

AVAILABLE

In Stock: New original, 400 pcs Stock Available. Quote:

Description: LB1947 SANYO SIP-13

Manufacturers: SANYO

Description: LB1945 SANYO DIP-28

RFQ

RFQ

AVAILABLE

LB1935FA-AH

Semiconductor

Description: IC MOTOR DRIVER PAR 10MICRO

In Stock: New original, 1500 pcs Stock Available.

Manufacturers: AMI Semiconductor / ON

Quote:

RFQ



Semiconductor

LB1930M-TLM

LB1943

Manufacturers: SANYO

Manufacturers: SANYO

LB1936V-MPB-E

Semiconductor

Description: LB1930M-TLM SANYO SOP10

Description: LB1943 SANYO SIP-11

In Stock: New original, 600 pcs Stock Available.

Description: IC MOTOR DRIVER PAR 16SSOP

In Stock: New original, 600 pcs Stock Available.

Manufacturers: AMI Semiconductor / ON

In Stock: New original, 1100 pcs Stock Available.

Quote:

Quote:

Quote:

RFQ

RFQ

In Stock: New original, 15200 pcs Stock Available. Quote: RFQ



···· 🕕

Manufacturers: SANYO

LB1945

In Stock: New original, 1300 pcs Stock Available. Quote:

RFQ

LB1935T-TLM-E **Description:** IC MOTOR DRIVER PAR 10MSOP

Manufacturers: AMI Semiconductor / ON Semiconductor

In Stock: New original, 19000 pcs Stock Available. Quote: RFQ

LB1940U-TLM-E

Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 8700 pcs Stock Available.

Description: IC MOTOR DRIVER PAR 20MSOP

Quote: RFQ



IMAGE NOT

AVAILABLE

LB1938T-TLM

Manufacturers: SANYO

RFQ Quote:

In Stock: New original, 1900 pcs Stock Available.

Description: LB1938T-TLM SANYO MSOP8

Manufacturers: SANYO In Stock: New original, 292400 pcs Stock Available.



Description: IC MOTOR DRIVER PAR 20TSSOP Manufacturers: AMI Semiconductor / ON

LB1939T-TLM-E

Semiconductor In Stock: New original, 3400 pcs Stock Available.

Quote: RFQ

IMAGE NOT

AVAILABLE

Manufacturers: AMI Semiconductor / ON Semiconductor

LB1947-E

In Stock: New original, 2500 pcs Stock Available.

Description: IC MOTOR DRIVER PAR 13SIPHJ

RFQ Quote:



LB1938FA-AH

LB1946

Quote:

Description: LB1946 SANYO DIP-28

Description: IC MOTOR DRIVER PAR 8MSOP

Manufacturers: AMI Semiconductor / ON



Description: LB1943N SANYO SIP-12 Manufacturers: SANYO

LB1943N

In Stock: New original, 100 pcs Stock Available. Quote:

IMAGE NOT AVAILABLE

Manufacturers: SANYO In Stock: New original, 1500 pcs Stock Available.

LB1941T

Quote:

Description: LB1941T SANYO SSOP

RFQ

RFQ



Semiconductor In Stock: New original, 2200 pcs Stock Available.

LB1941T-TLM-E

Semiconductor

Quote: RFQ

Description: IC MOTOR DRIVER PAR 8MSOP

In Stock: New original, 1200 pcs Stock Available.

Manufacturers: AMI Semiconductor / ON



LB1935CL-TLM-E Description: LB1935CL-TLM-E ASSEMB CSPBGA

Manufacturers: ASSEMB In Stock: New original, 2500 pcs Stock Available.

RFQ Quote:

Description: IC BRIDGE DRIVER PAR TSSOP-24 Manufacturers: AMI Semiconductor / ON

Manufacturers: SANYO In Stock: New original, 200 pcs Stock Available.

LB1933

Quote:

Description: LB1933 SANYO SOP14

Manufacturers: AMI Semiconductor / ON




IMAGE NOT

AVAILABLE

IMAGE NOT

AVAILABLE

LB1936V-TLM

Description: LB1936V-TLM SANYO SSOP16 Manufacturers: SANYO In Stock: New original, 2800 pcs Stock Available. RFQ Quote:

Quote:

RFQ

Quote:



Semiconductor

LB1937T-MPB-E


In Stock: New original, 2700 pcs Stock Available. Quote: RFQ

Semiconductor

LB1945H-TLM

Description: LB1945H-TLM ON AHCTHSOP2

In Stock: New original, 100 pcs Stock Available. Quote: RFQ



Description: LB1934T-MPB-E SANYO TSSOP20 Manufacturers: SANYO In Stock: New original, 1400 pcs Stock Available.

LB1934T-MPB-E

RFQ