



LB11852FV-TLM-H

Manufacturer Part Number:	LB11852FV-TLM-H
Manufacturer / Brand:	AMI Semiconductor / ON Semiconductor
Part of Description:	IC MOTOR CONTROLLER PAR 20SSOP
Datasheets:	LB11852FV-TLM-H.pdf
Lead Free Status / RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	New original, 46000 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

LB11852FV-TLM-H 100% New Original 46000pcs in Stock, Find LB11852FV-TLM-H Price, Stock, datasheet at IC Components Ltd Online, buy LB11852FV-TLM-H AMI Semiconductor / ON Semiconductor with warrantied. 100% guarantee confidence. RFQ LB11852FV-TLM-H: Info@IC-Components.com































The specifications of LB11852FV-TLM-H

Part Number	LB11852FV-TLM-H	Manufacturer / Brand	AMI Semiconductor / ON Semiconductor
Voltage - Supply	4.5 V ~ 5.5 V, 5.5 V ~ 16 V	Voltage - Load	-
Technology	-	Supplier Device Package	20-SSOPJ
Step Resolution	-	Series	-
Packaging	Tape & Reel (TR)	Package / Case	20-LFSOP (0.173", 4.40mm Width)
Output Configuration	Pre-Driver - Half Bridge (2)	Operating Temperature	-30°C ~ 95°C (TA)
Mounting Type	Surface Mount	Motor Type - Stepper	-
Motor Type - AC, DC	Brushless DC (BLDC)	Moisture Sensitivity Level (MSL)	3 (168 Hours)
Interface	PWM	Function	Controller - Speed
Detailed Description	Motor Driver PWM 20-SSOPJ	Current - Output	-
Base Part Number	LB11852	Applications	Fan Controller
Stock Quantity	46000 pcs Stock	Category	Integrated Circuits (ICs) > PMIC - Motor Drivers, Controllers
Description	IC MOTOR CONTROLLER PAR 20SSOP	Lead Free Status / RoHS Status	Lead free / RoHS Compliant

Keywords related to LB11852FV-TLM-H

AMI Semiconductor / ON Semiconductor LB11852FV-TLM-H	LB11852FV-TLM-H part	LB11852FV-TLM-H Price	LB11852FV-TLM-H Distributor
LB11852FV-TLM-H Supplier	LB11852FV-TLM-H Technical	LB11852FV-TLM-H Stock	LB11852FV-TLM-H Inventory
LB11852FV-TLM-H Picture	LB11852FV-TLM-H Online Order	LB11852FV-TLM-H Inquiry	LB11852FV-TLM-H Image
LB11852FV-TLM-H pdf datasheet	LB11852FV-TLM-H pdf	LB11852FV-TLM-H datasheet	LB11852FV-TLM-H data sheet
	Download LB11852FV-TLM-H datasheet	AMI Semiconductor / ON Semiconductor Manufacturer	AMI Semiconductor / ON Semiconductor LB11852FV-TLM-H
ON Semiconductor LB11852FV-TLM-H	Aptina / ON Semiconductor LB11852FV-TLM-H	Catalyst Semiconductor / ON Semiconductor LB11852FV-TLM-H	PulseCore Semiconductor / ON Semiconductor LB11852FV-TLM-H
Sanyo Semiconductor / ON Semiconductor LB11852FV-TLM-H			

You May Be Also Be interested In:

 LB11820 Description: Manufacturers: SANYO In Stock: New original, 4000 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11816V-MPB-E Description: LB11816V-MPB-E SANYO SOP Manufacturers: SANYO In Stock: New original, 2618 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11847 Description: LB11847 SANYO DIP Manufacturers: SANYO In Stock: New original, 2611 pcs Stock Available. Quote: <input type="text"/> RFQ
 LB11862M-TLM-H Description: LB11862M-TLM-H ON SOP-10 Manufacturers: ON In Stock: New original, 2898 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11851M-TE-L-E Description: LB11851M-TE-L-E SANYO SOP Manufacturers: SANYO In Stock: New original, 2708 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11861 Description: LB11861 ONS HSSOP-16 Manufacturers: ONS In Stock: New original, 2711 pcs Stock Available. Quote: <input type="text"/> RFQ
 LB11851MC-BH Description: IC MOTOR CONTROLLER PWM 10SOIC Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 2649 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11822 Description: LB11822 SANYO DIP-28 Manufacturers: SANYO In Stock: New original, 2628 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11861-N-TLM-H Description: LB11861-N-TLM-H SANYO HSOP16 Manufacturers: SANYO In Stock: New original, 2836 pcs Stock Available. Quote: <input type="text"/> RFQ
 LB11852RV-MPB-H Description: IC MOTOR CTRL PAR/PWM SSOP20J Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 2652 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11850VA-TLM-H Description: IC MOTOR CONTROLLER PAR 24SSOP Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 10000 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11826 Description: LB11826 SANYO DIP-28P Manufacturers: SANYO In Stock: New original, 2633 pcs Stock Available. Quote: <input type="text"/> RFQ
 LB11861M-TLM-H Description: LB11861M-TLM-H SANYO SOP10 Manufacturers: SANYO In Stock: New original, 2822 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11852FV-MPB-H Description: IC MOTOR CTRL PAR/PWM SSOP20J Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 3100 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11820M-TE-L Description: LB11820M-TE-L SANYO SSOP30 Manufacturers: SANYO In Stock: New original, 3200 pcs Stock Available. Quote: <input type="text"/> RFQ
 LB11861J-NMB-TLM3-E Description: LB11861J-NMB-TLM3-E SANYO SOP Manufacturers: SANYO In Stock: New original, 39000 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11861H-TLM-H Description: IC MOTOR DRIVER Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 2740 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11862M-TE-L Description: LB11862M-TE-L SANYO SOP-10 Manufacturers: SANYO In Stock: New original, 9000 pcs Stock Available. Quote: <input type="text"/> RFQ
 LB11825 Description: LB11825 SANYO SOP14 Manufacturers: SANYO In Stock: New original, 13600 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB1186 Description: LB1186 SANYO 原装 SOP Manufacturers: SANYO In Stock: New original, 2807 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11867FV-ND-TLM-E Description: LB11867FV-ND-TLM-E SANYO SSOP-20 Manufacturers: SANYO In Stock: New original, 6000 pcs Stock Available. Quote: <input type="text"/> RFQ
 LB11851TT-TLM-H Description: IC MOTOR CONTROLLER PWM 10MSOP Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 2667 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11861H-TLM-E Description: IC MOTOR DRIVER Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 8000 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11861M-TLM-E Description: LB11861M-TLM-E SANYO SOP10 Manufacturers: SANYO In Stock: New original, 5000 pcs Stock Available. Quote: <input type="text"/> RFQ
 LB11861MC-AH Description: IC MOTOR DRIVER PWM 10MPFSK Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 3000 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11827-E Description: LB11827-E SANYO DIP28 Manufacturers: SANYO In Stock: New original, 2682 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11820M-MPB-E Description: LB11820M-MPB-E SANYO SOP30 Manufacturers: SANYO In Stock: New original, 2736 pcs Stock Available. Quote: <input type="text"/> RFQ
 LB11861M-TLM-E. Description: LB11861M-TLM-E. SANYO SOP-10 Manufacturers: SANYO In Stock: New original, 2846 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11813V-TLM-E Description: LB11813V-TLM-E 原装SANYO TSSOP-24 Manufacturers: SANYO In Stock: New original, 3000 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11862M-TLM-E Description: LB11862M-TLM-E SANYO SOP10 Manufacturers: SANYO In Stock: New original, 2673 pcs Stock Available. Quote: <input type="text"/> RFQ



IC Components Limited
WWW.IC-COMPONENTS.COM

Email: Info@IC-Components.com
TEL: 00 852 - 30501935
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong