



SY89202UMI

Manufacturer Part Number:	SY89202UMI
Manufacturer / Brand	Micrel / Microchip Technology
Part of Description:	IC CLK BUFFER 1:8 1.5GHZ 32MLF
Datasheets:	SY89202UMI.pdf
Lead Free Status / RoHS Status:	Contains lead / RoHS non-compliant
Stock Condition:	New original, 1000 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

SY89202UMI 100% New Original 1000pcs in Stock, Find SY89202UMI Price, Stock, datasheet at IC Components Ltd Online, buy SY89202UMI Micrel / Microchip Technology with warrantied. 100% guarantee confidence. RFQ SY89202UMI: Info@IC-Components.com































The specifications of SY89202UMI

Part Number	SY89202UMI	Manufacturer / Brand	Micrel / Microchip Technology
Series	Precision Edge®	Moisture Sensitivity Level (MSL)	3 (168 Hours)
Base Part Number	SY89202	Package / Case	32-VFQFN Exposed Pad, 32-MLF®
Packaging	Bulk	Mounting Type	Surface Mount
Supplier Device Package	32-MLF® (5x5)	Operating Temperature	-40°C ~ 85°C
Detailed Description	Clock Fanout Buffer (Distribution), Divider, Multiplexer IC 1:8 1.5GHZ 32-VFQFN Exposed Pad, 32-MLF®	Type	Fanout Buffer (Distribution), Divider, Multiplexer
Frequency - Max	1.5GHz	Number of Circuits	1
Voltage - Supply	2.375 V ~ 3.6 V	Output	LVPECL
Input	CML, LVDS, PECL	Ratio - Input:Output	1:8
Differential - Input:Output	Yes/Yes	Stock Quantily	1000 pcs Stock
Category	Integrated Circuits (ICs) > Clock/Timing - Clock Buffers, Drivers	Description	IC CLK BUFFER 1:8 1.5GHZ 32MLF
Lead Free Status / RoHS Status	Contains lead / RoHS non-compliant		

Keywords related to SY89202UMI

Micrel / Microchip Technology SY89202UMI	SY89202UMI part	SY89202UMI Price	SY89202UMI Distributor
SY89202UMI Technical	SY89202UMI Stock	SY89202UMI Inventory	SY89202UMI Supplier
SY89202UMI Online Order	SY89202UMI Inquiry	SY89202UMI Image	SY89202UMI Picture
SY89202UMI pdf	SY89202UMI datasheet	SY89202UMI data sheet	SY89202UMI pdf datasheet
Download SY89202UMI datasheet	Micrel / Microchip Technology Manufacturer	Microchip Technology SY89202UMI	Microchip Technology SY89202UMI
Roving Networks / Microchip Technology SY89202UMI			

You May Be Also Be interested In:

 SY89251VMG Description: SY89251VMG MICREL QFN Manufacturers: MICREL In Stock: New original, 1600 pcs Stock Available. Quote: <input type="text"/> RFQ	 SY89218UHG Description: SY89218UHG MICREL TQFP64 Manufacturers: MICREL In Stock: New original, 1000 pcs Stock Available. Quote: <input type="text"/> RFQ	 SY89112UMG Description: IC CLK BUFFER 2:12 3GHZ 44MLF Manufacturers: Micrel / Microchip Technology In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ
 SY89295UTG Description: IC DELAY LN 1024TAP PROG 32TQFP Manufacturers: Micrel / Microchip Technology In Stock: New original, 4500 pcs Stock Available. Quote: <input type="text"/> RFQ	 SY89218UHY Description: IC CLK BUFFER 2:15 2GHZ 64TQFP Manufacturers: Micrel / Microchip Technology In Stock: New original, 1600 pcs Stock Available. Quote: <input type="text"/> RFQ	 SY88993VKC Description: IC AMP POST 5/3.3V HS TTL 10MSOP Manufacturers: Micrel / Microchip Technology In Stock: New original, 200 pcs Stock Available. Quote: <input type="text"/> RFQ
 SY89200UMG Description: IC CLK BUFFER 1:8 1.5GHZ 32MLF Manufacturers: Micrel / Microchip Technology In Stock: New original, 500 pcs Stock Available. Quote: <input type="text"/> RFQ	 SY892955UTG Description: SY892955UTG MICREL QFP Manufacturers: MICREL In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ	 SY88993VKG Description: IC POST AMP CML LIMITING 10-MSOP Manufacturers: Micrel / Microchip Technology In Stock: New original, 7500 pcs Stock Available. Quote: <input type="text"/> RFQ
 SY89202UMGTR Description: SY89202UMGTR MICREL MLF-32 Manufacturers: MICREL In Stock: New original, 4500 pcs Stock Available. Quote: <input type="text"/> RFQ	 SY89202UMG-TR Description: IC CLK BUFFER 1:8 1.5GHZ 32MLF Manufacturers: Micrel / Microchip Technology In Stock: New original, 400 pcs Stock Available. Quote: <input type="text"/> RFQ	 SY89112UMY Description: IC CLK BUFFER 2:12 3GHZ 44MLF Manufacturers: Micrel / Microchip Technology In Stock: New original, 5000 pcs Stock Available. Quote: <input type="text"/> RFQ
 SY89250VMG Description: SY89250VMG MICREL MLF Manufacturers: MICREL In Stock: New original, 3500 pcs Stock Available. Quote: <input type="text"/> RFQ	 SY89295UMG Description: IC DELAY LINE 1024TAP PROG 32MLF Manufacturers: Micrel / Microchip Technology In Stock: New original, 11000 pcs Stock Available. Quote: <input type="text"/> RFQ	 SY88993AVKG Description: IC POST AMP 5/3.3V HS TTL 10MSOP Manufacturers: MICREL In Stock: New original, 20000 pcs Stock Available. Quote: <input type="text"/> RFQ
 SY89202U Description: SY89202U MICREL QFN32 Manufacturers: MICREL In Stock: New original, 400 pcs Stock Available. Quote: <input type="text"/> RFQ	 SY88993V Description: SY88993V MICREL MSOP10 Manufacturers: MICREL In Stock: New original, 2600 pcs Stock Available. Quote: <input type="text"/> RFQ	 SY89230UMG Description: IC CLOCK DIVIDER LVPECL 16-MLF Manufacturers: MICREL In Stock: New original, 600 pcs Stock Available. Quote: <input type="text"/> RFQ
 SY89202UMG Description: IC CLK BUFFER 1:8 1.5GHZ 32MLF Manufacturers: Micrel / Microchip Technology In Stock: New original, 6600 pcs Stock Available. Quote: <input type="text"/> RFQ	 SY89296UTG Description: IC DELAY LN 1024TAP PROG 32TQFP Manufacturers: Micrel / Microchip Technology In Stock: New original, 1200 pcs Stock Available. Quote: <input type="text"/> RFQ	 SY89221UHG Description: SY89221UHG SY QFP64 Manufacturers: SY In Stock: New original, 12700 pcs Stock Available. Quote: <input type="text"/> RFQ
 SY89295U Description: SY89295U SY QFN Manufacturers: SY In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ	 SY89295UTI Description: IC DELAY LN 1024TAP PROG 32TQFP Manufacturers: Micrel / Microchip Technology In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ	 SY88993AVKTR Description: SY88993AVKTR MICREL MSOP-10L Manufacturers: MICREL In Stock: New original, 42400 pcs Stock Available. Quote: <input type="text"/> RFQ
 SY89113UMY Description: IC CLK BUFFER 2:12 1GHZ 44MLF Manufacturers: Micrel / Microchip Technology In Stock: New original, 600 pcs Stock Available. Quote: <input type="text"/> RFQ	 SY89202UMG-TR VQFN32 Description: SY89202UMG-TR VQFN32 MICROCHIP VQFN32 Manufacturers: Micrel / Microchip Technology In Stock: New original, 800 pcs Stock Available. Quote: <input type="text"/> RFQ	 SY89221UHY Description: IC CLK BUFFER 2:15 2GHZ 64TQFP Manufacturers: Micrel / Microchip Technology In Stock: New original, 1500 pcs Stock Available. Quote: <input type="text"/> RFQ
 SY89250V Description: SY89250V MICREL MLF-8 Manufacturers: MICREL In Stock: New original, 6500 pcs Stock Available. Quote: <input type="text"/> RFQ	 SY89250VMG TR Description: SY89250VMG TR MICREL MLF220 Manufacturers: MICREL In Stock: New original, 600 pcs Stock Available. Quote: <input type="text"/> RFQ	 SY89200UMI Description: IC CLK BUFFER 1:8 1.5GHZ 32MLF Manufacturers: Micrel / Microchip Technology In Stock: New original, 200 pcs Stock Available. Quote: <input type="text"/> RFQ



IC Components Limited
WWW.IC-COMPONENTS.COM

Email: Info@IC-Components.com
TEL: 00 852 - 30501935
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong