

IMAGE NOT AVAILABLE



CDCV304PW

Manufacturer Part Number:	CDCV304PW
Manufacturer / Brand	N/A
Part of Description:	IC CLK BUFFER 1:4 200MHZ 8TSSOP
Datasheets:	
Lead Free Status / RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	New original, 6600 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

CDCV304PW 100% New Original 6600pcs in Stock, Find CDCV304PW Price, Stock, datasheet at IC Components Ltd Online, buy CDCV304PW with warrantied. 100% guarantee confidence. RFQ CDCV304PW: Info@IC-Components.com

The specifications of CDCV304PW

Part Number	CDCV304PW	Manufacturer / Brand	N/A
Voltage - Supply	2.3 V ~ 3.6 V	Type	Fanout Buffer (Distribution)
Supplier Device Package	8-TSSOP	Series	-
Ratio - Input:Output	1:4	Packaging	Tube
Package / Case	8-TSSOP (0.173", 4.40mm Width)	Output	LVTTTL
Other Names	296-12420-5	Operating Temperature	-40°C ~ 85°C
Number of Circuits	1	Mounting Type	Surface Mount
Moisture Sensitivity Level (MSL)	1 (Unlimited)	Input	LVTTTL
Frequency - Max	200MHz	Differential - Input:Output	No/No
Detailed Description	Clock Fanout Buffer (Distribution) IC 1:4 200MHz 8-TSSOP (0.173", 4.40mm Width)	Base Part Number	CDCV304
Stock Quantity	6600 pcs Stock	Category	Integrated Circuits (ICs) > Clock/Timing - Clock Buffers, Drivers
Description	IC CLK BUFFER 1:4 200MHZ 8TSSOP	Lead Free Status / RoHS Status	Lead free / RoHS Compliant

Keywords realted to CDCV304PW

CDCV304PW	CDCV304PW part	CDCV304PW Price	CDCV304PW Distributor
CDCV304PW Technical	CDCV304PW Stock	CDCV304PW Inventory	CDCV304PW Supplier
CDCV304PW Online Order	CDCV304PW Inquiry	CDCV304PW Image	CDCV304PW Picture
CDCV304PW pdf	CDCV304PW datasheet	CDCV304PW data sheet	CDCV304PW pdf datasheet
Download CDCV304PW datasheet	Manufacturer		

You May Be Also Be interested In:

<p>CDCV304PWG4 Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 2800 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>CDCV304PWR Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 56000 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>CDCV855PWRG4 Description: IC PLL CLOCK DRVR 2.5V 28TSSOP Manufacturers: N/A In Stock: New original, 2640 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p>CDCU877RHAR Description: IC PLL CLOCK DRIVER 1.8V 40VQFN Manufacturers: N/A In Stock: New original, 2735 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>CDCV304 Description: CDCV304 TEXAS TSP08 Manufacturers: TEXAS In Stock: New original, 2736 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>CDCV304TPWREP Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 2690 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p>CDCV855PWR Description: IC 1:4 DDR PLL CLK-DRVR 28-TSSOP Manufacturers: N/A In Stock: New original, 2821 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>CDCV855-13CT Description: CDCV855-13CT TI TSSOP Manufacturers: TI In Stock: New original, 2690 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>CDCV857 Description: CDCV857 TI TSSOP48 Manufacturers: TI In Stock: New original, 2690 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p>CDCU877ZQLR Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 5000 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>CDCU877AGQLR Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2609 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>CDCU877GQLT Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2746 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p>CDCV850IDGGR Description: TI TSSOP Manufacturers: TI In Stock: New original, 2669 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>CDCU877RHAT Description: IC PLL CLOCK DRIVER 1.8V 40VQFN Manufacturers: N/A In Stock: New original, 2823 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>CDCV850DGGRG4 Description: IC PLL CLOCK DRVR 2.5V 48TSSOP Manufacturers: N/A In Stock: New original, 2650 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p>CDCU877AZQLR Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2788 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>CDCV850DGGR Description: IC PLL CLOCK DRVR 2.5V 48-TSSOP Manufacturers: N/A In Stock: New original, 2855 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>CDCU877ARHAR Description: IC PLL CLOCK DRIVER 1.8V 40VQFN Manufacturers: N/A In Stock: New original, 2749 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p>CDCUN1208LPRHBT Description: IC CLK BUFFER 2:8 400MHZ 32QFN Manufacturers: N/A In Stock: New original, 2792 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>CDCUA877ZQLT Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2858 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>CDCV304PWR-TR Description: TI TSSOP-8 Manufacturers: TI In Stock: New original, 6000 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p>CDCV304PWRG4 Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 13000 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>CDCV855PW Description: IC 1:4 DDR PLL CLK-DRVR 28-TSSOP Manufacturers: N/A In Stock: New original, 2784 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>CDCU877AZQLT Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2645 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p>CDCV855 Description: CDCV855 TI TSSOP28 Manufacturers: TI In Stock: New original, 2819 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>CDCUA877ZQLR Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 17000 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>CDCU877ZQLT Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2805 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p>CDCU877GQLR Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2749 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>CDCU877ARHARG4 Description: IC PLL CLOCK DRIVER 1.8V 40VQFN Manufacturers: N/A In Stock: New original, 2656 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>CDCV855IPWR Description: IC PLL CLOCK DRVR 2.5V 28TSSOP Manufacturers: N/A In Stock: New original, 2772 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>



IC Components Limited
WWW.IC-COMPONENTS.COM

Email: Info@IC-Components.com
TEL: 00 852 - 30501935
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong