



2345FB39A0050E

Manufacturer Part Number:	2345FB39A0050E
Manufacturer / Brand	Johanson Technology
Part of Description:	BALUN 2.3GHZ-2.39GHZ 50/50 1008
Datasheets:	2345FB39A0050E.pdf
Lead Free Status / RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	New original, 11100 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

2345FB39A0050E 100% New Original 11100pcs in Stock, Find 2345FB39A0050E Price, Stock, datasheet at IC Components Ltd Online, buy 2345FB39A0050E Johanson Technology with warrantied. 100% guarantee confidence. RFQ 2345FB39A0050E: Info@IC-Components.com

The specifications of 2345FB39A0050E

Part Number	2345FB39A0050E	Manufacturer / Brand	Johanson Technology
Series	-	Moisture Sensitivity Level (MSL)	1 (Unlimited)
Package / Case	1008 (2520 Metric), 6 PC Pad	Packaging	Cut Tape (CT)
Mounting Type	Surface Mount	Detailed Description	RF Balun 2.3GHz ~ 2.39GHz 50 / 50 Ohm 1008 (2520 Metric), 6 PC Pad
Frequency Range	2.3GHz ~ 2.39GHz	Impedance - Unbalanced/Balanced	50 / 50 Ohm
Phase Difference	180° ±10°	Insertion Loss (Max)	3.2dB
Return Loss (Min)	11.73dB	Other Names	712-1404-1
Stock Quantity	11100 pcs Stock	Category	RF/IF and RFID > Balun
Description	BALUN 2.3GHZ-2.39GHZ 50/50 1008	Lead Free Status / RoHS Status	Lead free / RoHS Compliant

Keywords realted to 2345FB39A0050E

Johanson Technology 2345FB39A0050E	2345FB39A0050E part	2345FB39A0050E Price	2345FB39A0050E Distributor
2345FB39A0050E Technical	2345FB39A0050E Stock	2345FB39A0050E Inventory	2345FB39A0050E Supplier
2345FB39A0050E Online Order	2345FB39A0050E Inquiry	2345FB39A0050E Image	2345FB39A0050E Picture
2345FB39A0050E pdf	2345FB39A0050E datasheet	2345FB39A0050E data sheet	2345FB39A0050E pdf datasheet
Download 2345FB39A0050E datasheet	Johanson Technology Manufacturer	Johanson Technology 2345FB39A0050E	Johanson 2345FB39A0050E
Johanson Technology Inc. 2345FB39A0050E			

You May Be Also Be interested In:

<p>23474A Description: 23474A T1TSSOP14 Manufacturers: TI In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>HMM1517 Description: BALUN 2.4GHZ-2.5GHZ 50/50 0805 Manufacturers: TDK Corporation In Stock: New original, 124000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>2342 Description: RSU 12-RKWU 12-S4741/10 M Manufacturers: Lumberg Automation In Stock: New original, 7500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>BALF-NRG-01D3 Description: BALUN 2.4GHZ-2.5GHZ 50/50 4WFBGA Manufacturers: STMicroelectronics In Stock: New original, 14900 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>234-10UYD/S530-A3 Description: 234-10UYD/S530-A3 EVERLIGHT 3.0mmRound Manufacturers: Everlight Electronics In Stock: New original, 300 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>MABA-010125-TC1113 Description: E-SERIES TRANSFORMER 4.5-3000MHZ Manufacturers: Affinity Medical Technologies - a Molex company In Stock: New original, 200 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>5400BL15B100E Description: BALUN 4.9GHZ-5.9GHZ 50/100 0805 Manufacturers: Johanson Technology In Stock: New original, 700 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>B0322J5050AHF Description: BALUN 300MHZ-2.2GHZ 50/50 0805 Manufacturers: Anaren In Stock: New original, 2300 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>HMM1711E1 Description: BALUN 2.3GHZ-2.7GHZ 50/100 0603 Manufacturers: TDK Corporation In Stock: New original, 12000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>234Q063 Description: 234Q063 SHARP QFP32 Manufacturers: Sharp Microelectronics In Stock: New original, 700 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>CX2045LNLT Description: BALUN 3MHZ-300MHZ 5SMD Manufacturers: Pulse Electronics Corporation In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>MABA-007871-CT1A40 Description: TRANSFORMER 1:1 5-3000 MHZ Manufacturers: Affinity Medical Technologies - a Molex company In Stock: New original, 9300 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>2450BM14A0002T Description: BALUN 2.4GHZ-2.5GHZ 0603 Manufacturers: Johanson Technology In Stock: New original, 5000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>HMM1570B1 Description: BALUN 4.9GHZ-5.95GHZ 50/100 0805 Manufacturers: TDK Corporation In Stock: New original, 3700 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>DXW21BN7511TL Description: BALUN 50MHZ-870MHZ 75/75 0805 Manufacturers: Murata Electronics In Stock: New original, 58800 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>HMM1904A1 Description: BALUN 2.4GHZ-2.5GHZ 50/75 0402 Manufacturers: TDK Corporation In Stock: New original, 158000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>BD2425N50100AHF Description: BALUN 2.4GHZ-2.5GHZ 50/100 0404 Manufacturers: Anaren In Stock: New original, 8000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>HMM1534 Description: BALUN DUAL 50/200 0805 Manufacturers: TDK Corporation In Stock: New original, 2000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>2450BL15B100E Description: BALUN 2.4GHZ-2.5GHZ 50/100 0805 Manufacturers: Johanson Technology In Stock: New original, 13000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>2345FB39A0050T Description: 2345FB39A0050T JOHANSON SMD Manufacturers: Johanson Technology In Stock: New original, 8100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>HMM1521 Description: BALUN 2.4GHZ-2.5GHZ 50/200 0805 Manufacturers: TDK Corporation In Stock: New original, 21500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>2450FB15K0005E Description: BALUN 2.4GHZ-2.5GHZ 0805 Manufacturers: Johanson Technology In Stock: New original, 24400 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>DXP18BN5014HL Description: BALUN 470MHZ-790MHZ 50/200 0603 Manufacturers: Murata Electronics In Stock: New original, 3600 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>RFBLN1608050AM8T62 Description: BALUN 2.4GHZ-2.5GHZ 50/50 6SMD Manufacturers: Walsin Technology In Stock: New original, 2500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>2342 Description: ROUND SPACER #4 NYLON 1/4" Manufacturers: Keystone Electronics Corp. In Stock: New original, 7500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>2342 Description: FX MINI SOUND BOARD WAV/OGG Manufacturers: Adafruit In Stock: New original, 7500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>HMM1907B1 Description: BALUN 4.9GHZ-5.95GHZ 50/50 0402 Manufacturers: TDK Corporation In Stock: New original, 89000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>23400361-321 Description: 23400361-321 ST BGA Manufacturers: ST In Stock: New original, 200 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>HMM1522B1 Description: BALUN 880MHZ-960MHZ 50/50 0805 Manufacturers: TDK Corporation In Stock: New original, 2900 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>2343K05FAV Description: 2343K05FAV RENESAS QFP Manufacturers: Renesas Electronics America In Stock: New original, 200 pcs Stock Available. Quote: <input type="text"/> RFQ</p>



IC Components Limited
WWW.IC-COMPONENTS.COM

Email: Info@IC-Components.com
TEL: 00 852 - 30501935
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong