



**DXP2ABN7514TL**

<b>Manufacturer Part Number:</b>	DXP2ABN7514TL
<b>Manufacturer / Brand</b>	Murata Electronics
<b>Part of Description:</b>	BALUN 50MHZ-870MHZ 75/300 0804
<b>Datasheets:</b>	<a href="#">DXP2ABN7514TL.pdf</a>
<b>Lead Free Status / RoHS Status:</b>	Lead free / RoHS Compliant
<b>Stock Condition:</b>	New original, 3900 pcs Stock Available.
<b>Ship From:</b>	Hong Kong
<b>Shipment Way:</b>	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

**DXP2ABN7514TL** 100% New Original 3900pcs in Stock, Find DXP2ABN7514TL Price, Stock, datasheet at IC Components Ltd Online, buy DXP2ABN7514TL Murata Electronics with warrantied. 100% guarantee confidence. RFQ DXP2ABN7514TL: [Info@IC-Components.com](mailto:Info@IC-Components.com)

The specifications of DXP2ABN7514TL

Part Number	DXP2ABN7514TL	Manufacturer / Brand	Murata Electronics
Series	-	Return Loss (Min)	-
Phase Difference	-	Packaging	Cut Tape (CT)
Package / Case	0804 (2010 Metric), 8 Lead	Other Names	490-11951-1
Mounting Type	Surface Mount	Moisture Sensitivity Level (MSL)	1 (Unlimited)
Insertion Loss (Max)	1.8dB	Impedance - Unbalanced/Balanced	75 / 300 Ohm
Frequency Range	50MHz ~ 870MHz	Detailed Description	RF Balun 50MHz ~ 870MHz 75 / 300 Ohm 0804 (2010 Metric), 8 Lead
Stock Quantity	3900 pcs Stock	Category	<a href="#">RF/IF and RFID &gt; Balun</a>
Description	BALUN 50MHZ-870MHZ 75/300 0804	Lead Free Status / RoHS Status	Lead free / RoHS Compliant

Keywords realted to DXP2ABN7514TL

<a href="#">Murata Electronics DXP2ABN7514TL</a>	<a href="#">DXP2ABN7514TL part</a>	<a href="#">DXP2ABN7514TL Price</a>	<a href="#">DXP2ABN7514TL Distributor</a>
<a href="#">DXP2ABN7514TL Technical</a>	<a href="#">DXP2ABN7514TL Stock</a>	<a href="#">DXP2ABN7514TL Inventory</a>	<a href="#">DXP2ABN7514TL Supplier</a>
<a href="#">DXP2ABN7514TL Online Order</a>	<a href="#">DXP2ABN7514TL Inquiry</a>	<a href="#">DXP2ABN7514TL Image</a>	<a href="#">DXP2ABN7514TL Picture</a>
<a href="#">DXP2ABN7514TL pdf</a>	<a href="#">DXP2ABN7514TL datasheet</a>	<a href="#">DXP2ABN7514TL data sheet</a>	<a href="#">DXP2ABN7514TL pdf datasheet</a>
<a href="#">Download DXP2ABN7514TL datasheet</a>	<a href="#">Murata Electronics Manufacturer</a>	<a href="#">Murata Electronics DXP2ABN7514TL</a>	<a href="#">MURATA DXP2ABN7514TL</a>
<a href="#">Murata Electronics North America DXP2ABN7514TL</a>	<a href="#">TOKO / Murata DXP2ABN7514TL</a>		

You May Be Also Be interested In:

<p><b>LDM181G9310CC001</b> Description: BALUN 1.71-2.155GHZ 50/100 0603 Manufacturers: Murata Electronics In Stock: New original, 67100 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>DXP18CN7510T</b> Description: DXP18CN7510T MURATA SMD Manufacturers: MURATA In Stock: New original, 2758 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>DXP18BN5014TL</b> Description: BALUN 50MHZ-870MHZ 50/200 0603 Manufacturers: Murata Electronics In Stock: New original, 32000 pcs Stock Available. Quote: <a href="#">RFQ</a></p>
<p><b>DXP18CN7510TL</b> Description: RF DIR COUPLER 50MHZ-870MHZ 0603 Manufacturers: Murata Electronics In Stock: New original, 4800 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>MABA-009594-CF18A0</b> Description: BALUN 5MHZ-200MHZ 1:1 6SMD GW Manufacturers: Aeroflex (MACOM Technology Solutions) In Stock: New original, 4500 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>HHM1515B2</b> Description: BALUN 880MHZ-960MHZ 50/200 0805 Manufacturers: TDK Corporation In Stock: New original, 2684 pcs Stock Available. Quote: <a href="#">RFQ</a></p>
<p><b>LDB212G4005C-001</b> Description: BALUN 2.3GHZ-2.5GHZ 50/50 0805 Manufacturers: Murata Electronics In Stock: New original, 52000 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>HHM1932A2</b> Description: BALUN 862MHZ-894MHZ 50/100 0402 Manufacturers: TDK Corporation In Stock: New original, 20000 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>2450BL15B200E</b> Description: BALUN 2.4GHZ-2.5GHZ 50/200 0805 Manufacturers: Johanson Technology In Stock: New original, 10800 pcs Stock Available. Quote: <a href="#">RFQ</a></p>
<p><b>HHM1711D1</b> Description: BALUN 2.4GHZ-2.5GHZ 50/100 0603 Manufacturers: TDK Corporation In Stock: New original, 28500 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>MABA-007681-CT2010</b> Description: BALUN 5MHZ-1.2GHZ 1:2 4SMD Manufacturers: Aeroflex (MACOM Technology Solutions) In Stock: New original, 2720 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p>IMAGE NOT AVAILABLE</p> <p><b>DXP18BN5014T</b> Description: DXP18BN5014T MUARATA SMD Manufacturers: MUARATA In Stock: New original, 2752 pcs Stock Available. Quote: <a href="#">RFQ</a></p>
<p><b>BD2425J50100AHF</b> Description: BALUN 2.4GHZ-2.5GHZ 50/100 0805 Manufacturers: Anaren In Stock: New original, 3100 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>2450FB15M0001E</b> Description: BALUN 2.4GHZ-2.5GHZ 0805 Manufacturers: Johanson Technology In Stock: New original, 13000 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>HHM1548E1</b> Description: BALUN 3.2GHZ-3.9GHZ 50/200 0805 Manufacturers: TDK Corporation In Stock: New original, 2752 pcs Stock Available. Quote: <a href="#">RFQ</a></p>
<p><b>C6058NL</b> Description: IC CHIP Manufacturers: Pulse Electronics Corporation In Stock: New original, 2657 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>2450FB15K0005E</b> Description: BALUN 2.4GHZ-2.5GHZ 0805 Manufacturers: Johanson Technology In Stock: New original, 24400 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>C2073</b> Description: BALUN 5MHZ-200MHZ 1:4 5SMD MODUL Manufacturers: Pulse Electronics Corporation In Stock: New original, 50000 pcs Stock Available. Quote: <a href="#">RFQ</a></p>
<p><b>DXW21BN7511SL</b> Description: BALUN 1GHZ-1.5GHZ 75/75 0805 Manufacturers: Murata Electronics In Stock: New original, 47200 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>MABACT0063</b> Description: BALUN 5MHZ-1GHZ 1.5:1 6SMD FLAT Manufacturers: Aeroflex (MACOM Technology Solutions) In Stock: New original, 2789 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>DXP18BN5014HL</b> Description: BALUN 470MHZ-790MHZ 50/200 0603 Manufacturers: Murata Electronics In Stock: New original, 3600 pcs Stock Available. Quote: <a href="#">RFQ</a></p>
<p><b>LFB182G45BG5D920</b> Description: BALUN 2.4GHZ-2.5GHZ 6SMD Manufacturers: Murata Electronics In Stock: New original, 10800 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>5400BL15B100E</b> Description: BALUN 4.9GHZ-5.9GHZ 50/100 0805 Manufacturers: Johanson Technology In Stock: New original, 2694 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>HHM1570B1</b> Description: BALUN 4.9GHZ-5.95GHZ 50/100 0805 Manufacturers: TDK Corporation In Stock: New original, 3700 pcs Stock Available. Quote: <a href="#">RFQ</a></p>
<p><b>HHM1711E1</b> Description: BALUN 2.3GHZ-2.7GHZ 50/100 0603 Manufacturers: TDK Corporation In Stock: New original, 12000 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>HHM1904A1</b> Description: BALUN 2.4GHZ-2.5GHZ 50/75 0402 Manufacturers: TDK Corporation In Stock: New original, 158000 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>BAL-CW1250D3</b> Description: BALUN 2.4GHZ-2.5GHZ 5UFBGA FCBGA Manufacturers: STMicroelectronics In Stock: New original, 5000 pcs Stock Available. Quote: <a href="#">RFQ</a></p>
<p><b>HHM1523B3</b> Description: BALUN 824MHZ-894MHZ 50/100 0805 Manufacturers: TDK Corporation In Stock: New original, 4000 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>2595FB16A0100E</b> Description: BALUN 2.3GHZ-2.69GHZ 50/100 0806 Manufacturers: Johanson Technology In Stock: New original, 8100 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>DXP252690DT-5031A3</b> Description: TDK SMD Manufacturers: TDK In Stock: New original, 2800 pcs Stock Available. Quote: <a href="#">RFQ</a></p>



**IC Components Limited**  
WWW.IC-COMPONENTS.COM

Email: [Info@IC-Components.com](mailto:Info@IC-Components.com)  
TEL: 00 852 - 30501935  
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong