

LB1868M-TLM-H

Shipment Way:

Manufacturer Part Number: Manufacturer / Brand Part of Description: Datasheets: Lead Free Status / RoHS Status: **Stock Condition: Ship From:**

LB1868M-TLM-H

Hong Kong

DHL/Fedex/TNT/UPS

AMI Semiconductor / ON Semiconductor IC MOTOR DRIVER PAR 14MFP LB1868M-TLM-H.pdf 🖎 🚣 Lead free / RoHS Compliant New original, 26000 pcs Stock Available.

GET A QUOTE

LB1868M-TLM-H 100% New Original 26000pcs in Stock, Find LB1868M-TLM-H Price, Stock, datasheet at IC Components Ltd Online, buy LB1868M-TLM-H AMI Semiconductor / ON Semiconductor with warrantied. 100% guarantee confidence. RFQ LB1868M-TLM-H: Info@IC-Components.com


The specifications of LB1868M-TLM-H

Part Number	LB1868M-TLM-H	Manufacturer / Brand	AMI Semiconductor / ON Semiconductor
Series	-	Moisture Sensitivity Level (MSL)	3 (168 Hours)
Base Part Number	LB1868	Package / Case	14-LSOP (0.173", 4.40mm Width)
Packaging	Tape & Reel (TR)	Mounting Type	Surface Mount
Supplier Device Package	14-MFPS	Operating Temperature	-30°C ~ 80°C (TA)
Detailed Description	Half Bridge (2) Driver DC Motors, General Purpose Bipolar 14-MFPS	Technology	Bipolar
Features	-	Interface	Logic
Applications	DC Motors, General Purpose	Voltage - Supply	6.4 V ~ 7 V
Current - Output / Channel	1A	Current - Peak Output	-
Output Configuration	Half Bridge (2)	Fault Protection	Over Temperature
Load Type	Inductive	Rds On (Typ)	-
Voltage - Load	12V, 24V	Stock Quantity	26000 pcs Stock
Category	Integrated Circuits (ICs) > PMIC - Full, Half-Bridge Drivers	Description	IC MOTOR DRIVER PAR 14MFP
Lead Free Status / RoHS Status	Lead free / RoHS Compliant		

Keywords realted to LB1868M-TLM-H

AMI Semiconductor / ON Semiconductor LB1868M-	LB1868M-TLM-H part	LB1868M-TLM-H Price	LB1868M-TLM-H Distributor
TLM-H	LB1868M-TLM-H Technical	LB1868M-TLM-H Stock	LB1868M-TLM-H Inventory
LB1868M-TLM-H Supplier	LB1868M-TLM-H Online Order	LB1868M-TLM-H Inquiry	LB1868M-TLM-H Image
LB1868M-TLM-H Picture	LB1868M-TLM-H pdf	LB1868M-TLM-H datasheet	LB1868M-TLM-H data sheet
LB1868M-TLM-H pdf datasheet	Download LB1868M-TLM-H datasheet	AMI Semiconductor / ON Semiconductor Manufacturer	AMI Semiconductor / ON Semiconductor LB1868M-
			TLM-H
ON Semiconductor LB1868M-TLM-H	Aptina / ON Semiconductor LB1868M-TLM-H	Catalyst Semiconductor / ON Semiconductor	PulseCore Semiconductor / ON Semiconductor
		LB1868M-TLM-H	LB1868M-TLM-H
Sanyo Semiconductor / ON Semiconductor LB1868M-			
TLM-H			

You May Be Also Be interested In:



LB1867M-TLM-E **Description:** IC MOTOR DRIVER ON/OFF 14MFP Manufacturers: AMI Semiconductor / ON

LB1863M-TLM-H

Semiconductor

Semiconductor In Stock: New original, 1200 pcs Stock Available. Quote: **RFQ**

Description: IC MOTOR DRIVER ON/OFF 14MFP

In Stock: New original, 1400 pcs Stock Available.

Quote:

RFQ

Manufacturers: AMI Semiconductor / ON



IMAGE NOT

AVAILABLE

LB1875 Description: LB1875 SANYO SOP-36

LB1870

Manufacturers: SANYO

In Stock: New original, 1500 pcs Stock Available. Quote: RFQ

In Stock: New original, 200 pcs Stock Available.

Description: LB1870 SANYO SOP-36



IMAGE NOT

AVAILABLE

Description: IC MOTOR DRIVER ON/OFF 10MFPSK

Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 2000 pcs Stock Available. RFQ Quote:



LB1877V-MPB-E **Description:** LB1877V-MPB-E SANYO TSSOP20

Manufacturers: SANYO

In Stock: New original, 2800 pcs Stock Available. RFQ Quote:

AVAILABLE

IMAGE NOT

LB1863M-DELTA-TLM-H

Manufacturers: SANYO

Description: LB1863M-DELTA-TLM-H SANYO SOP14 Manufacturers: SANYO In Stock: New original, 2000 pcs Stock Available. Quote:

RFQ

RFQ

Manufacturers: SANYO In Stock: New original, 3000 pcs Stock Available.

LB1906CL-TLM

LB1862MC-AH

Quote: RFQ

Description: LB1863M-TE-L SANYO SOP14

In Stock: New original, 1000 pcs Stock Available.

Quote:

Quote:

RFQ

Description: LB1906CL-TLM SANYO SMD

IMAGE NOT

AVAILABLE

LB1870M-TE

Description: LB1870M-TE SANYO SSOP-36 Manufacturers: SANYO In Stock: New original, 200 pcs Stock Available. **IMAGE NOT AVAILABLE**

LB1869M-TLM-E

Description: LB1869M-TLM-E SANYO TSSOP Manufacturers: SANYO

In Stock: New original, 600 pcs Stock Available.

RFQ Quote:



IMAGE NOT

AVAILABLE

IMAGE NOT

AVAILABLE

LB1863M-TE-L

Manufacturers: SANYO

LB1877V-TLM Description: LB1877V-TLM SANYO SSOP20 Manufacturers: SANYO

In Stock: New original, 2000 pcs Stock Available.



Description: LB1879M-TE-L SANYO SOP Manufacturers: SANYO

LB1879M-TE-L

In Stock: New original, 30000 pcs Stock Available.

RFQ Quote:

Quote:

Quote:

RFQ



Description: IC BRIDGE DRIVER ON/OFF MFP14S Manufacturers: AMI Semiconductor / ON

LB1868M-TLM-E

Semiconductor In Stock: New original, 1000 pcs Stock Available.

RFQ Quote:



LB1894

LB1868M-TE-L

Manufacturers: SANYO

Description: LB1894 SANYO DSOP Manufacturers: SANYO In Stock: New original, 100 pcs Stock Available.




IMAGE NOT

AVAILABLE

Manufacturers: SANYO In Stock: New original, 1300 pcs Stock Available.

LB1862M-TLM-H **Description:** LB1862M-TLM-H SANYO SOP10



LB1868 Description: LB1868 SANYO SOP14 Manufacturers: SANYO

In Stock: New original, 28800 pcs Stock Available. Quote: RFQ



RFQ Quote:

Description: LB1868M-TE-L SANYO SOP14

In Stock: New original, 12000 pcs Stock Available.

Quote:



Description: LB1921 SANYO DIP-28

LB1921

Manufacturers: SANYO In Stock: New original, 6900 pcs Stock Available.

RFQ Quote:



Description: LB1867M SANYO SOP14 Manufacturers: SANYO

LB1867M

In Stock: New original, 300 pcs Stock Available. Quote:

RFQ



Description: LB1867 SANYO SOP14

LB1867

Manufacturers: SANYO In Stock: New original, 18300 pcs Stock Available. RFQ Quote:



IMAGE NOT

AVAILABLE

Description: LB1872 SANYO DIP-28 Manufacturers: SANYO

LB1872

In Stock: New original, 4600 pcs Stock Available. Quote: RFQ

Description: LB1863M SANYO SOP-14 Manufacturers: SANYO In Stock: New original, 400 pcs Stock Available.



Manufacturers: AMI Semiconductor / ON Semiconductor

LB1867M-MPB-H

Quote: RFQ

In Stock: New original, 2000 pcs Stock Available.

Description: IC BRIDGE DRIVER ON/OFF MFP14S

Description: LB1906CL-TLM-E SANYO BGA



AVAILABLE

IMAGE NOT

AVAILABLE

Description: LB1868M-NMB-TLM3-E SANYO SOP Manufacturers: SANYO

LB1868M-NMB-TLM3-E

In Stock: New original, 66000 pcs Stock Available. RFQ Quote:

Description: LB1862M-TLM-E SANYO SOP10



LB1863M

Quote:

RFQ

IMAGE NOT Description: LB1876 SANYO QFP-36



IMAGE NOT

Manufacturers: SANYO

LB1906CL-TLM-E

In Stock: New original, 21000 pcs Stock Available. RFQ Quote:

Description: LB1897 SANYO IC



In Stock: New original, 2600 pcs Stock Available.


Manufacturers: SANYO

LB1862M-TLM-E

LB1870M-TE-L

Quote:

RFQ




Manufacturers: SANYO

LB1876

In Stock: New original, 7300 pcs Stock Available.

RFQ Quote:



Manufacturers: SANYO In Stock: New original, 200 pcs Stock Available.

LB1897

RFQ Quote:



Description: LB1870M-TE-L SANYO SSOP36 Manufacturers: SANYO In Stock: New original, 6800 pcs Stock Available. RFQ Quote:

IC Components Limited WWW.IC-COMPONENTS.COM Email: Info@IC-Components.com TEL: 00 852 - 30501935

FAX: 00 852 - 30501945 Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong