

IMAGE NOT AVAILABLE



LMX2335MX

Manufacturer Part Number:	LMX2335MX
Manufacturer / Brand	N/A
Part of Description:	IC FREQ SYNTH DUAL 1.1GHZ 16SOIC
Datasheets:	
Lead Free Status / RoHS Status:	Contains lead / RoHS non-compliant
Stock Condition:	New original, 5000 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

LMX2335MX 100% New Original 5000pcs in Stock, Find LMX2335MX Price, Stock, datasheet at IC Components Ltd Online, buy LMX2335MX with warranted. 100% guarantee confidence. RFQ LMX2335MX: Info@IC-Components.com

The specifications of LMX2335MX

Part Number	LMX2335MX	Manufacturer / Brand	N/A
Voltage - Supply	2.7 V ~ 5.5 V	Type	PLL Frequency Synthesizer
Supplier Device Package	16-SOIC	Series	PLLatinum™
Ratio - Input:Output	3:1	Packaging	Tape & Reel (TR)
Package / Case	16-SOIC (0.154", 3.90mm Width)	PLL	Yes with Bypass
Output	CMOS	Other Names	*LMX2335MX
Operating Temperature	-40°C ~ 85°C	Number of Circuits	1
Mounting Type	Surface Mount	Moisture Sensitivity Level (MSL)	1 (Unlimited)
Input	CMOS, TTL	Frequency - Max	1.1GHz
Divider/Multiplier	Yes/No	Differential - Input:Output	No/No
Base Part Number	LMX2335	Stock Quantity	5000 pcs Stock
Category	Integrated Circuits (ICs) > Clock/Timing - Clock Generators, PLLs, Frequency Synthesizers	Description	IC FREQ SYNTH DUAL 1.1GHZ 16SOIC
Lead Free Status / RoHS Status	Contains lead / RoHS non-compliant		

Keywords related to LMX2335MX

LMX2335MX	LMX2335MX part	LMX2335MX Price	LMX2335MX Distributor
LMX2335MX Technical	LMX2335MX Stock	LMX2335MX Inventory	LMX2335MX Supplier
LMX2335MX Online Order	LMX2335MX Inquiry	LMX2335MX Image	LMX2335MX Picture
LMX2335MX pdf	LMX2335MX datasheet	LMX2335MX data sheet	LMX2335MX pdf datasheet
Download LMX2335MX datasheet	Manufacturer		

You May Be Also Be interested In:

<p>LMX2335MX</p> <p>IMAGE NOT AVAILABLE</p> <p>LMX2336LTM Description: LMX2336LTM NS TSSOP-20 Manufacturers: NS In Stock: New original, 16900 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>LMX2335UTM</p> <p>IMAGE NOT AVAILABLE</p> <p>Description: LMX2335UTM NS TSSOP Manufacturers: NS In Stock: New original, 2700 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>LMX2336UTM</p> <p>IMAGE NOT AVAILABLE</p> <p>Description: IC FREQ SYNTHESIZER DUAL 20TSSOP Manufacturers: N/A In Stock: New original, 2826 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>LMX2335LM</p> <p>IMAGE NOT AVAILABLE</p> <p>Description: LMX2335LM NS SOP16 Manufacturers: NS In Stock: New original, 2841 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>LMX2335TLMG</p> <p>IMAGE NOT AVAILABLE</p> <p>Description: LMX2335TLMG NS TSSOP-20 Manufacturers: NS In Stock: New original, 2666 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>LMX2335LTMG</p> <p>IMAGE NOT AVAILABLE</p> <p>Description: LMX2335LTMG NSC TSSOP Manufacturers: NSC In Stock: New original, 2767 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>LMX2332LTMXPB</p> <p>IMAGE NOT AVAILABLE</p> <p>Description: LMX2332LTMXPB NS TSSOP-20 Manufacturers: NS In Stock: New original, 2739 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>LMX2335MB</p> <p>IMAGE NOT AVAILABLE</p> <p>Description: NSC SOP16 Manufacturers: NSC In Stock: New original, 2704 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>LMX2332UTMX</p> <p>IMAGE NOT AVAILABLE</p> <p>Description: LMX2332UTMX NSC TSSOP Manufacturers: NSC In Stock: New original, 2746 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>LMX2333TMC</p> <p>IMAGE NOT AVAILABLE</p> <p>Description: LMX2333TMC NSC TSSOP-20 Manufacturers: NSC In Stock: New original, 2600 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>LMX2332UTM</p> <p>IMAGE NOT AVAILABLE</p> <p>Description: IC FREQ SYNTHESIZER DUAL 20TSSOP Manufacturers: N/A In Stock: New original, 2614 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>LMX2336LTMX</p> <p>IMAGE NOT AVAILABLE</p> <p>Description: LMX2336LTMX NS TSSOP-24 Manufacturers: NS In Stock: New original, 2500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>LMX2336TMG</p> <p>IMAGE NOT AVAILABLE</p> <p>Description: LMX2336TMG SOP eh87AB Manufacturers: SOP In Stock: New original, 6600 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>LMX2336LSLBX</p> <p>IMAGE NOT AVAILABLE</p> <p>Description: IC PLLANTINUM SYNTHESZR LAM CSP Manufacturers: N/A In Stock: New original, 27500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>LMX2336TM</p> <p>IMAGE NOT AVAILABLE</p> <p>Description: LMX2336TM NSC TSSOP20 Manufacturers: NSC In Stock: New original, 8500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>LMX2337M</p> <p>IMAGE NOT AVAILABLE</p> <p>Description: Manufacturers: NS In Stock: New original, 2867 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>LMX2332LTMF</p> <p>IMAGE NOT AVAILABLE</p> <p>Description: LMX2332LTMF NS TSSOP Manufacturers: NS In Stock: New original, 2698 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>LMX2332LTM</p> <p>IMAGE NOT AVAILABLE</p> <p>Description: LMX2332LTM TSSOP MM14RE Manufacturers: TSSOP In Stock: New original, 2711 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>LMX2332LTMG</p> <p>IMAGE NOT AVAILABLE</p> <p>Description: LMX2332LTMG NS SSOP-20 Manufacturers: NS In Stock: New original, 2755 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>LMX2335TMX</p> <p>IMAGE NOT AVAILABLE</p> <p>Description: LMX2335TMX NS TSSOP-16 Manufacturers: NS In Stock: New original, 2892 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>LMX2336TMC</p> <p>IMAGE NOT AVAILABLE</p> <p>Description: LMX2336TMC TSSOP EH87AB Manufacturers: TSSOP In Stock: New original, 2882 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>LMX2332LTX</p> <p>IMAGE NOT AVAILABLE</p> <p>Description: LMX2332LTX TI TSOP Manufacturers: TI In Stock: New original, 2756 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>LMX2332TLMG</p> <p>IMAGE NOT AVAILABLE</p> <p>Description: LMX2332TLMG NS TSSOP-20 Manufacturers: NS In Stock: New original, 2663 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>LMX2336TMX</p> <p>IMAGE NOT AVAILABLE</p> <p>Description: NS TSSOP-20 Manufacturers: NS In Stock: New original, 2821 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>LMX2337MC</p> <p>IMAGE NOT AVAILABLE</p> <p>Description: LMX2337MC NS SOP16 Manufacturers: NS In Stock: New original, 2712 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>LMX2336</p> <p>IMAGE NOT AVAILABLE</p> <p>Description: LMX2336 NS TSSOP20 Manufacturers: NS In Stock: New original, 2662 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>LMX2332LTMX</p> <p>IMAGE NOT AVAILABLE</p> <p>Description: LMX2332LTMX NS TSSOP-24 Manufacturers: NS In Stock: New original, 2781 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>LMX2335/A</p> <p>IMAGE NOT AVAILABLE</p> <p>Description: Manufacturers: NSC In Stock: New original, 2765 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>LMX2335M</p> <p>IMAGE NOT AVAILABLE</p> <p>Description: LMX2335M NS SOP Manufacturers: NS In Stock: New original, 2713 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>LMX2336LTMG</p> <p>IMAGE NOT AVAILABLE</p> <p>Description: LMX2336LTMG NS SSOP-20 Manufacturers: NS In Stock: New original, 2633 pcs Stock Available. Quote: <input type="text"/> RFQ</p>



IC Components Limited
WWW.IC-COMPONENTS.COM

Email: Info@IC-Components.com
TEL: 00 852 - 30501935
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong