



2450BM15A0015E

Manufacturer Part Number:	2450BM15A0015E
Manufacturer / Brand	Johanson Technology
Part of Description:	BALUN 2.4GHZ-2.5GHZ 0805
Datasheets:	2450BM15A0015E.pdf
Lead Free Status / RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	New original, 2800 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

2450BM15A0015E 100% New Original 2800pcs in Stock, Find 2450BM15A0015E Price, Stock, datasheet at IC Components Ltd Online, buy 2450BM15A0015E Johanson Technology with warrantied. 100% guarantee confidence. RFQ 2450BM15A0015E: Info@IC-Components.com

The specifications of 2450BM15A0015E

Part Number	2450BM15A0015E	Manufacturer / Brand	Johanson Technology
Series	-	Moisture Sensitivity Level (MSL)	1 (Unlimited)
Package / Case	0805 (2012 Metric), 6 PC Pad	Packaging	Original-Reel®
Mounting Type	Surface Mount	Detailed Description	RF Balun 2.4GHz ~ 2.5GHz 50 / - Ohm 0805 (2012 Metric), 6 PC Pad
Frequency Range	2.4GHz ~ 2.5GHz	Impedance - Unbalanced/Balanced	50 / - Ohm
Phase Difference	180° ±10°	Insertion Loss (Max)	1.5dB
Return Loss (Min)	9.5dB	Other Names	712-1576-6
Stock Quantity	2800 pcs Stock	Category	RF/IF and RFID > Balun
Description	BALUN 2.4GHZ-2.5GHZ 0805	Lead Free Status / RoHS Status	Lead free / RoHS Compliant

Keywords realted to 2450BM15A0015E

Johanson Technology 2450BM15A0015E	2450BM15A0015E part	2450BM15A0015E Price	2450BM15A0015E Distributor
2450BM15A0015E Technical	2450BM15A0015E Stock	2450BM15A0015E Inventory	2450BM15A0015E Supplier
2450BM15A0015E Online Order	2450BM15A0015E Inquiry	2450BM15A0015E Image	2450BM15A0015E Picture
2450BM15A0015E pdf	2450BM15A0015E datasheet	2450BM15A0015E data sheet	2450BM15A0015E pdf datasheet
Download 2450BM15A0015E datasheet	Johanson Technology Manufacturer	Johanson Technology 2450BM15A0015E	Johanson 2450BM15A0015E
Johanson Technology Inc. 2450BM15A0015E			

You May Be Also Be interested In:

 2450BP15H0100E Description: FILTER BAND PASS 2.45GHZ Manufacturers: Johanson Technology In Stock: New original, 8000 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 2450AT43F0100E Description: RF ANT 2.4GHZ CHIP SOLDER SMD Manufacturers: Johanson Technology In Stock: New original, 8100 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 2450FB15K0008T Description: 2450FB15K0008T JOHANSON SMD Manufacturers: Johanson Technology In Stock: New original, 13000 pcs Stock Available. Quote: <input type="button" value="RFQ"/>
 2450BP07A0100T Description: FILTER BANDPASS 2.4GHZ WIFI Manufacturers: Johanson Technology In Stock: New original, 50000 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 2450AT43D100E Description: RF ANT 2.4GHZ CHIP SOLDER SMD Manufacturers: Johanson Technology In Stock: New original, 32200 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 2450FB15K0002 Description: 2450FB15K0002 JOHANSON Manufacturers: Johanson Technology In Stock: New original, 32200 pcs Stock Available. Quote: <input type="button" value="RFQ"/>
 2450BL15B100E Description: BALUN 2.4GHZ-2.5GHZ 50/100 0805 Manufacturers: Johanson Technology In Stock: New original, 13000 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 2450BL15B050E Description: BALUN 2.4GHZ-2.5GHZ 50/50 0805 Manufacturers: Johanson Technology In Stock: New original, 5500 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 2450BM14A0002T Description: BALUN 2.4GHZ-2.5GHZ 0603 Manufacturers: Johanson Technology In Stock: New original, 5000 pcs Stock Available. Quote: <input type="button" value="RFQ"/>
 2450BL15B200E Description: BALUN 2.4GHZ-2.5GHZ 50/200 0805 Manufacturers: Johanson Technology In Stock: New original, 10800 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 2450FB14K0001E Description: 2450FB14K0001E JOHANSON Manufacturers: Johanson Technology In Stock: New original, 23500 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 2450BP18C100CE Description: FILTER BANDPASS 2.4GHZ Manufacturers: Johanson Technology In Stock: New original, 4000 pcs Stock Available. Quote: <input type="button" value="RFQ"/>
 2450BM14E0003T Description: BALUN 2.4GHZ-2.5GHZ 0603 Manufacturers: Johanson Technology In Stock: New original, 100 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 2450AT43H0100E Description: RF ANT 2.4GHZ CHIP SOLDER SMD Manufacturers: Johanson Technology In Stock: New original, 2300 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 2450AT42A100E Description: RF ANT 2.4GHZ CHIP SOLDER SMD Manufacturers: Johanson Technology In Stock: New original, 5800 pcs Stock Available. Quote: <input type="button" value="RFQ"/>
 2450AT42B100E Description: RF ANT 2.4GHZ CHIP SOLDER SMD Manufacturers: Johanson Technology In Stock: New original, 2500 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 2450FB15K0005T Description: 2450FB15K0005T JOHANSON SMD Manufacturers: Johanson Technology In Stock: New original, 12000 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 2450BP15B100E Description: FILTER BANDPASS 2.4GHZ Manufacturers: Johanson Technology In Stock: New original, 20000 pcs Stock Available. Quote: <input type="button" value="RFQ"/>
 2450BP39D100CE Description: FILTER BANDPASS 2.4GHZ Manufacturers: Johanson Technology In Stock: New original, 700 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 2450AT45A100E Description: RF ANT 2.4GHZ CHIP SOLDER SMD Manufacturers: Johanson Technology In Stock: New original, 8200 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	<p>IMAGE NOT AVAILABLE</p> 2450FB14K0002E Description: 2450FB14K0002E JOHNSON SMD Manufacturers: JOHANSON In Stock: New original, 8100 pcs Stock Available. Quote: <input type="button" value="RFQ"/>
 2450BP39C100BE Description: FILTER BANDPASS 2.4GHZ Manufacturers: Johanson Technology In Stock: New original, 2500 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 2450BP15P0100E Description: BAND PASS FILTER 2.45 GHZ 0805 Manufacturers: Johanson Technology In Stock: New original, 11900 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 2450BP39C100CE Description: FILTER BANDPASS 2.4GHZ Manufacturers: Johanson Technology In Stock: New original, 900 pcs Stock Available. Quote: <input type="button" value="RFQ"/>
 2450BP15E0100E Description: FILTER BANDPASS 2.4GHZ Manufacturers: Johanson Technology In Stock: New original, 6700 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 2450BM15A0002E Description: BALUN 2.4GHZ-2.5GHZ 0805 Manufacturers: Johanson Technology In Stock: New original, 12000 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 2450AT42D0100E Description: RF ANT 2.4GHZ CHIP SOLDER SMD Manufacturers: Johanson Technology In Stock: New original, 2000 pcs Stock Available. Quote: <input type="button" value="RFQ"/>
 2450FB15K0005E Description: BALUN 2.4GHZ-2.5GHZ 0805 Manufacturers: Johanson Technology In Stock: New original, 24400 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 2450AT43A100E Description: RF ANT 2.4GHZ CHIP SOLDER SMD Manufacturers: Johanson Technology In Stock: New original, 2300 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 2450AT44A100E Description: RF ANT 2.4GHZ CHIP SOLDER SMD Manufacturers: Johanson Technology In Stock: New original, 6700 pcs Stock Available. Quote: <input type="button" value="RFQ"/>



IC Components Limited
WWW.IC-COMPONENTS.COM

Email: Info@IC-Components.com
TEL: 00 852 - 30501935
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong