



CDC7005GVAT

Manufacturer Part Number:	CDC7005GVAT
Manufacturer / Brand	N/A
Part of Description:	IC CLK SYNC/JITTER CLEANER 64BGA
Datasheets:	
Lead Free Status / RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	New original, 4600 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

CDC7005GVAT 100% New Original 4600pcs in Stock, Find CDC7005GVAT Price, Stock, datasheet at IC Components Ltd Online, buy CDC7005GVAT with warranted. 100% guarantee confidence. RFQ CDC7005GVAT: Info@IC-Components.com

The specifications of CDC7005GVAT

Part Number	CDC7005GVAT	Manufacturer / Brand	N/A
Voltage - Supply	3 V ~ 3.6 V	Type	Clock Synchronizer and Jitter Cleaner
Supplier Device Package	64-BGA	Series	-
Ratio - Input:Output	2:5	Packaging	Original-Reel®
Package / Case	64-BGA	PLL	No
Output	LVPECL	Other Names	296-17399-6
Operating Temperature	-40°C ~ 85°C	Number of Circuits	1
Mounting Type	Surface Mount	Moisture Sensitivity Level (MSL)	3 (168 Hours)
Input	LVC MOS, LVPECL	Frequency - Max	800MHz
Divider/Multiplier	Yes/Yes	Differential - Input:Output	Yes/Yes
Base Part Number	CDC7005	Stock Quantity	4600 pcs Stock
Category	Integrated Circuits (ICs) > Clock/Timing - Clock Generators, PLLs, Frequency Synthesizers	Description	IC CLK SYNC/JITTER CLEANER 64BGA
Lead Free Status / RoHS Status	Lead free / RoHS Compliant		

Keywords related to CDC7005GVAT

CDC7005GVAT	CDC7005GVAT part	CDC7005GVAT Price	CDC7005GVAT Distributor
CDC7005GVAT Technical	CDC7005GVAT Stock	CDC7005GVAT Inventory	CDC7005GVAT Supplier
CDC7005GVAT Online Order	CDC7005GVAT Inquiry	CDC7005GVAT Image	CDC7005GVAT Picture
CDC7005GVAT pdf	CDC7005GVAT datasheet	CDC7005GVAT data sheet	CDC7005GVAT pdf datasheet
Download CDC7005GVAT datasheet	Manufacturer		

You May Be Also Be interested In:

<p>IMAGE NOT AVAILABLE</p> <p>CDC582PAH Description: IC 3.3V PLL CLOCK DRIVER 52-TQFP Manufacturers: N/A In Stock: New original, 2677 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDC536DB Description: IC 3.3V PLL CLOCK DRIVER 28-SSOP Manufacturers: N/A In Stock: New original, 2898 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDC857-2DGG Description: IC 2.5V PLL CLK-DRVR 48-TSSOP Manufacturers: N/A In Stock: New original, 2793 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>CDC5D23BNP-100LC Description: FIXED IND 10UH 1.04A 133 MOHM Manufacturers: Sumida America Components Inc. In Stock: New original, 6000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDC857-2DGGR Description: IC 2.5V PLL CLK-DRVR 48-TSSOP Manufacturers: N/A In Stock: New original, 6000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDC421A212RGER Description: IC CLK GEN 212.50MHZ 3.3V 24VQFN Manufacturers: N/A In Stock: New original, 2745 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>CDC586PAH Description: IC 3.3V PLL CLOCK DRIVER 52-TQFP Manufacturers: N/A In Stock: New original, 2810 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDC5801DBQR Description: IC CLOCK MLT/DIV LOW JTTR 24QSOP Manufacturers: N/A In Stock: New original, 2797 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDC509PWR Description: IC 3.3V PLL CLOCK DRVR 24-TSSOP Manufacturers: N/A In Stock: New original, 5000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>CDC7005ZVA Description: IC CLK SYNC/JITTER CLEANER 64BGA Manufacturers: N/A In Stock: New original, 2893 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDC924DLR Description: IC 133-MHZ CLOCK SYNTH 56-SSOP Manufacturers: N/A In Stock: New original, 2726 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDC586PAHR Description: IC 3.3V PLL CLOCK DRIVER 52-TQFP Manufacturers: N/A In Stock: New original, 2652 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>CDC516DGGR Description: IC 3.3V PLL CLK DRVR 35T 48TSSOP Manufacturers: N/A In Stock: New original, 2680 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDC750RGR Description: TI QFN Manufacturers: TI In Stock: New original, 2826 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDC706PWRG4 Description: IC 2:6PLL SYNTH/MULT/DIV 20TSSOP Manufacturers: N/A In Stock: New original, 2760 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>CDC736RHBR Description: TI QFN Manufacturers: TI In Stock: New original, 2827 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDC421A250RGER Description: IC CLK GEN 250.00MHZ 3.3V 24VQFN Manufacturers: N/A In Stock: New original, 2615 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDC750 Description: TEXAS QFN Manufacturers: TEXAS In Stock: New original, 2842 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>CDC7005ZVAT Description: IC CLK SYNC/JITTER CLEANER 64BGA Manufacturers: N/A In Stock: New original, 2866 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDC906PWR Description: IC 2:6PLL SYNTH/MULT/DIV 20TSSOP Manufacturers: N/A In Stock: New original, 2851 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDC582 Description: CDC582 TI QFP Manufacturers: TI In Stock: New original, 2836 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>CDC536DBR Description: IC 3.3V PLL CLOCK DRIVER 28-SSOP Manufacturers: N/A In Stock: New original, 2808 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDC7005RGZT Description: IC CLK SYNC/JITTER CLEANER 48QFN Manufacturers: N/A In Stock: New original, 2830 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDC7005ZVAR Description: IC CLOCK MLT/JITTER CLEANR 64BGA Manufacturers: N/A In Stock: New original, 2843 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>CDC950DGGR Description: IC DIFF CLOCK SYNTH/DRVR 48TSSOP Manufacturers: N/A In Stock: New original, 2734 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDC7005RGZR Description: TI VQFN48 Manufacturers: TI In Stock: New original, 2899 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDC5801ADBQRG4 Description: IC CLOCK MLT/DIV LOW JTTR 24QSOP Manufacturers: N/A In Stock: New original, 2670 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>CDC5801DBQ Description: IC CLOCK MLT/DIV LOW JTTR 24QSOP Manufacturers: N/A In Stock: New original, 2776 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>CDC857-3DGG Description: IC 3.3V PLL CLK-DRVR 48-TSSOP Manufacturers: N/A In Stock: New original, 2741 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p></p> <p>CDC5D23BNP-470KC Description: FIXED IND 47UH 490MA 546 MOHM Manufacturers: Sumida Corporation In Stock: New original, 2620 pcs Stock Available. Quote: <input type="text"/> RFQ</p>



IC Components Limited
WWW.IC-COMPONENTS.COM

Email: Info@IC-Components.com
TEL: 00 852 - 30501935
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong