




CDCV850DGGRG4

Manufacturer Part Number:	CDCV850DGGRG4
Manufacturer / Brand	N/A
Part of Description:	IC PLL CLOCK DRVR 2.5V 48TSSOP
Datasheets:	
Lead Free Status / RoHS Status:	 Lead free / RoHS Compliant
Stock Condition:	New original, 2650 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

CDCV850DGGRG4 100% New Original 2650pcs in Stock, Find CDCV850DGGRG4 Price, Stock, datasheet at IC Components Ltd Online, buy CDCV850DGGRG4 with warrantied. 100% guarantee confidence. RFQ CDCV850DGGRG4: Info@IC-Components.com































The specifications of CDCV850DGGRG4

Part Number	CDCV850DGGRG4	Manufacturer / Brand	N/A
Voltage - Supply	2.3 V ~ 2.7 V	Type	PLL Clock Driver
Supplier Device Package	48-TSSOP	Series	-
Ratio - Input:Output	1:11	Packaging	Tape & Reel (TR)
Package / Case	48-TFSOP (0.240", 6.10mm Width)	PLL	Yes with Bypass
Output	SSTL-2	Operating Temperature	0°C ~ 85°C
Number of Circuits	1	Mounting Type	Surface Mount
Moisture Sensitivity Level (MSL)	2 (1 Year)	Input	LVTTL, SSTL-2
Frequency - Max	140MHz	Divider/Multiplier	No/No
Differential - Input:Output	Yes/Yes	Base Part Number	CDCV850
Stock Quantity	2650 pcs Stock	Category	Integrated Circuits (ICs) > Clock/Timing - Clock Generators, PLLs, Frequency Synthesizers
Description	IC PLL CLOCK DRVR 2.5V 48TSSOP	Lead Free Status / RoHS Status	Lead free / RoHS Compliant

Keywords realted to CDCV850DGGRG4

CDCV850DGGRG4	CDCV850DGGRG4 part	CDCV850DGGRG4 Price	CDCV850DGGRG4 Distributor
CDCV850DGGRG4 Technical	CDCV850DGGRG4 Stock	CDCV850DGGRG4 Inventory	CDCV850DGGRG4 Supplier
CDCV850DGGRG4 Online Order	CDCV850DGGRG4 Inquiry	CDCV850DGGRG4 Image	CDCV850DGGRG4 Picture
CDCV850DGGRG4 pdf	CDCV850DGGRG4 datasheet	CDCV850DGGRG4 data sheet	CDCV850DGGRG4 pdf datasheet
Download CDCV850DGGRG4 datasheet	Manufacturer		

You May Be Also Be interested In:

 <p>CDCV850IDGGR Description: TI TSSOP Manufacturers: TI In Stock: New original, 2669 pcs Stock Available. Quote: RFQ</p>	 <p>CDCV857ADGG Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP Manufacturers: N/A In Stock: New original, 2606 pcs Stock Available. Quote: RFQ</p>	 <p>CDCV857AGQLR Description: IC CLK-DRVR PLL 2.5V 56-BGA Manufacturers: N/A In Stock: New original, 2876 pcs Stock Available. Quote: RFQ</p>
 <p>CDCV304PW Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 6600 pcs Stock Available. Quote: RFQ</p>	 <p>CDCV855PW Description: IC 1:4 DDR PLL CLK-DRVR 28-TSSOP Manufacturers: N/A In Stock: New original, 2784 pcs Stock Available. Quote: RFQ</p>	 <p>CDCV855PWRG4 Description: IC PLL CLOCK DRVR 2.5V 28TSSOP Manufacturers: N/A In Stock: New original, 2640 pcs Stock Available. Quote: RFQ</p>
 <p>CDCU877ZQLT Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2805 pcs Stock Available. Quote: RFQ</p>	 <p>CDCV857BDGGRG4 Description: IC SSTL-II PLL CLK-DRVR 48TSSOP Manufacturers: N/A In Stock: New original, 18000 pcs Stock Available. Quote: RFQ</p>	 <p>CDCV304PWR Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 56000 pcs Stock Available. Quote: RFQ</p>
 <p>CDCV857ADGGRG4 Description: IC SSTL-II PLL CLK-DRVR 48TSSOP Manufacturers: N/A In Stock: New original, 2816 pcs Stock Available. Quote: RFQ</p>	 <p>CDCV304 Description: CDCV304 TEXAS TSP08 Manufacturers: TEXAS In Stock: New original, 2736 pcs Stock Available. Quote: RFQ</p>	 <p>CDCUN1208LPRHBT Description: IC CLK BUFFER 2:8 400MHZ 32QFN Manufacturers: N/A In Stock: New original, 2792 pcs Stock Available. Quote: RFQ</p>
 <p>CDCV855IPWR Description: IC PLL CLOCK DRVR 2.5V 28TSSOP Manufacturers: N/A In Stock: New original, 2772 pcs Stock Available. Quote: RFQ</p>	 <p>CDCV304PWG4 Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 2800 pcs Stock Available. Quote: RFQ</p>	 <p>CDCV304PWRG4 Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 13000 pcs Stock Available. Quote: RFQ</p>
 <p>CDCV850DGGR Description: IC PLL CLOCK DRVR 2.5V 48-TSSOP Manufacturers: N/A In Stock: New original, 2855 pcs Stock Available. Quote: RFQ</p>	 <p>CDCUA877ZQLR Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 17000 pcs Stock Available. Quote: RFQ</p>	 <p>CDCV855-13CT Description: CDCV855-13CT TI TSSOP Manufacturers: TI In Stock: New original, 2690 pcs Stock Available. Quote: RFQ</p>
 <p>CDCV304PWR-TR Description: TI TSSOP-8 Manufacturers: TI In Stock: New original, 6000 pcs Stock Available. Quote: RFQ</p>	 <p>CDCV857 Description: CDCV857 TI TSSOP48 Manufacturers: TI In Stock: New original, 2690 pcs Stock Available. Quote: RFQ</p>	 <p>CDCU877RHAR Description: IC PLL CLOCK DRIVER 1.8V 40VQFN Manufacturers: N/A In Stock: New original, 2735 pcs Stock Available. Quote: RFQ</p>
 <p>CDCUA877ZQLT Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2858 pcs Stock Available. Quote: RFQ</p>	 <p>CDCV857ADGGR Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP Manufacturers: N/A In Stock: New original, 18800 pcs Stock Available. Quote: RFQ</p>	 <p>CDCU877RHAT Description: IC PLL CLOCK DRIVER 1.8V 40VQFN Manufacturers: N/A In Stock: New original, 2823 pcs Stock Available. Quote: RFQ</p>
 <p>CDCV857BDGG Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP Manufacturers: N/A In Stock: New original, 2768 pcs Stock Available. Quote: RFQ</p>	 <p>CDCU877ZQLR Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 5000 pcs Stock Available. Quote: RFQ</p>	 <p>CDCV304TPWREP Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 2690 pcs Stock Available. Quote: RFQ</p>
 <p>CDCV855PWR Description: IC 1:4 DDR PLL CLK-DRVR 28-TSSOP Manufacturers: N/A In Stock: New original, 2821 pcs Stock Available. Quote: RFQ</p>	 <p>CDCV855 Description: CDCV855 TI TSSOP28 Manufacturers: TI In Stock: New original, 2819 pcs Stock Available. Quote: RFQ</p>	 <p>CDCV857BDGGR Description: IC SSTL-II PLL CLK-DRVR 48TSSOP Manufacturers: N/A In Stock: New original, 26000 pcs Stock Available. Quote: RFQ</p>



IC Components Limited
WWW.IC-COMPONENTS.COM

Email: Info@IC-Components.com
TEL: 00 852 - 30501935
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong