



2450BP15H0100E

Manufacturer Part Number:	2450BP15H0100E
Manufacturer / Brand	Johanson Technology
Part of Description:	FILTER BAND PASS 2.45GHZ
Datasheets:	2450BP15H0100E.pdf
Lead Free Status / RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	New original, 8000 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

2450BP15H0100E 100% New Original 8000pcs in Stock, Find 2450BP15H0100E Price, Stock, datasheet at IC Components Ltd Online, buy 2450BP15H0100E Johanson Technology with warrantied. 100% guarantee confidence. RFQ 2450BP15H0100E: Info@IC-Components.com

The specifications of 2450BP15H0100E

Part Number	2450BP15H0100E	Manufacturer / Brand	Johanson Technology
Series	-	Moisture Sensitivity Level (MSL)	1 (Unlimited)
Package / Case	0805 (2012 Metric), 4 PC Pad	Packaging	Tape & Reel (TR)
Mounting Type	Surface Mount	Frequency	2.45GHz Center
Size / Dimension	0.079" L x 0.049" W (2.00mm x 1.25mm)	Height (Max)	0.026" (0.65mm)
Insertion Loss	1.5dB	Filter Type	Band Pass
Bandwidth	100MHz	Ripple	-
Other Names	2450BP15H0100E-ND 712-1587-2	Stock Quantity	8000 pcs Stock
Category	Filters > RF Filters	Description	FILTER BAND PASS 2.45GHZ
Lead Free Status / RoHS Status	Lead free / RoHS Compliant		

Keywords related to 2450BP15H0100E

Johanson Technology 2450BP15H0100E	2450BP15H0100E part	2450BP15H0100E Price	2450BP15H0100E Distributor
2450BP15H0100E Technical	2450BP15H0100E Stock	2450BP15H0100E Inventory	2450BP15H0100E Supplier
2450BP15H0100E Online Order	2450BP15H0100E Inquiry	2450BP15H0100E Image	2450BP15H0100E Picture
2450BP15H0100E pdf	2450BP15H0100E datasheet	2450BP15H0100E data sheet	2450BP15H0100E pdf datasheet
Download 2450BP15H0100E datasheet	Johanson Technology Manufacturer	Johanson Technology 2450BP15H0100E	Johanson 2450BP15H0100E
Johanson Technology Inc. 2450BP15H0100E			

You May Be Also Be interested In:

 2450BP18C100CE Description: FILTER BANDPASS 2.4GHZ Manufacturers: Johanson Technology In Stock: New original, 4000 pcs Stock Available. Quote: <input type="text"/> RFQ	 2450FB15K0002 Description: 2450FB15K0002 JOHANSON Manufacturers: Johanson Technology In Stock: New original, 32200 pcs Stock Available. Quote: <input type="text"/> RFQ	 2450FB15K0005E Description: BALUN 2.4GHZ-2.5GHZ 0805 Manufacturers: Johanson Technology In Stock: New original, 24400 pcs Stock Available. Quote: <input type="text"/> RFQ
 2450AT44A100E Description: RF ANT 2.4GHZ CHIP SOLDER SMD Manufacturers: Johanson Technology In Stock: New original, 6700 pcs Stock Available. Quote: <input type="text"/> RFQ	 2450FB15L0001T Description: 2450FB15L0001T JOHANSON SMD Manufacturers: Johanson Technology In Stock: New original, 11000 pcs Stock Available. Quote: <input type="text"/> RFQ	 2450FB15K0008T Description: 2450FB15K0008T JOHANSON SMD Manufacturers: Johanson Technology In Stock: New original, 13000 pcs Stock Available. Quote: <input type="text"/> RFQ
 2450AT43F0100E Description: RF ANT 2.4GHZ CHIP SOLDER SMD Manufacturers: Johanson Technology In Stock: New original, 8100 pcs Stock Available. Quote: <input type="text"/> RFQ	 2450FB39B100E Description: BALUN 2.4GHZ-2.5GHZ 50/100 1008 Manufacturers: Johanson Technology In Stock: New original, 32200 pcs Stock Available. Quote: <input type="text"/> RFQ	 2450BM14A0002T Description: BALUN 2.4GHZ-2.5GHZ 0603 Manufacturers: Johanson Technology In Stock: New original, 5000 pcs Stock Available. Quote: <input type="text"/> RFQ
 2450FB14K0001E Description: 2450FB14K0001E JOHANSON Manufacturers: Johanson Technology In Stock: New original, 23500 pcs Stock Available. Quote: <input type="text"/> RFQ	 2450FB15M0001E Description: BALUN 2.4GHZ-2.5GHZ 0805 Manufacturers: Johanson Technology In Stock: New original, 13000 pcs Stock Available. Quote: <input type="text"/> RFQ	 2450BP15P0100E Description: BAND PASS FILTER 2.45 GHZ 0805 Manufacturers: Johanson Technology In Stock: New original, 11900 pcs Stock Available. Quote: <input type="text"/> RFQ
 2450FB14K0002E Description: 2450FB14K0002E JOHANSON SMD Manufacturers: JOHANSON In Stock: New original, 8100 pcs Stock Available. Quote: <input type="text"/> RFQ	 2450BM15A0002E Description: BALUN 2.4GHZ-2.5GHZ 0805 Manufacturers: Johanson Technology In Stock: New original, 12000 pcs Stock Available. Quote: <input type="text"/> RFQ	 2450BL15B050E Description: BALUN 2.4GHZ-2.5GHZ 50/50 0805 Manufacturers: Johanson Technology In Stock: New original, 5500 pcs Stock Available. Quote: <input type="text"/> RFQ
 2450BM15A0015E Description: BALUN 2.4GHZ-2.5GHZ 0805 Manufacturers: Johanson Technology In Stock: New original, 2800 pcs Stock Available. Quote: <input type="text"/> RFQ	 2450BP07A0100T Description: FILTER BANDPASS 2.4GHZ WIFI Manufacturers: Johanson Technology In Stock: New original, 50000 pcs Stock Available. Quote: <input type="text"/> RFQ	 2450FB15K0005T Description: 2450FB15K0005T JOHANSON SMD Manufacturers: Johanson Technology In Stock: New original, 12000 pcs Stock Available. Quote: <input type="text"/> RFQ
 2450BM14E0003T Description: BALUN 2.4GHZ-2.5GHZ 0603 Manufacturers: Johanson Technology In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ	 2450BP39C100CE Description: FILTER BANDPASS 2.4GHZ Manufacturers: Johanson Technology In Stock: New original, 900 pcs Stock Available. Quote: <input type="text"/> RFQ	 2450AT45A100E Description: RF ANT 2.4GHZ CHIP SOLDER SMD Manufacturers: Johanson Technology In Stock: New original, 8200 pcs Stock Available. Quote: <input type="text"/> RFQ
 2450BP39C100BE Description: FILTER BANDPASS 2.4GHZ Manufacturers: Johanson Technology In Stock: New original, 2500 pcs Stock Available. Quote: <input type="text"/> RFQ	 2450AT43H0100E Description: RF ANT 2.4GHZ CHIP SOLDER SMD Manufacturers: Johanson Technology In Stock: New original, 2300 pcs Stock Available. Quote: <input type="text"/> RFQ	 2450BL15B200E Description: BALUN 2.4GHZ-2.5GHZ 50/200 0805 Manufacturers: Johanson Technology In Stock: New original, 10800 pcs Stock Available. Quote: <input type="text"/> RFQ
 2450BP39D100CE Description: FILTER BANDPASS 2.4GHZ Manufacturers: Johanson Technology In Stock: New original, 700 pcs Stock Available. Quote: <input type="text"/> RFQ	 2450BP15B100E Description: FILTER BANDPASS 2.4GHZ Manufacturers: Johanson Technology In Stock: New original, 20000 pcs Stock Available. Quote: <input type="text"/> RFQ	 2450FB15L0001E Description: BALUN 2.4GHZ-2.5GHZ 0805 Manufacturers: Johanson Technology In Stock: New original, 13400 pcs Stock Available. Quote: <input type="text"/> RFQ
 2450BP15E0100E Description: FILTER BANDPASS 2.4GHZ Manufacturers: Johanson Technology In Stock: New original, 6700 pcs Stock Available. Quote: <input type="text"/> RFQ	 2450AT43D100E Description: RF ANT 2.4GHZ CHIP SOLDER SMD Manufacturers: Johanson Technology In Stock: New original, 32200 pcs Stock Available. Quote: <input type="text"/> RFQ	 2450BL15B100E Description: BALUN 2.4GHZ-2.5GHZ 50/100 0805 Manufacturers: Johanson Technology In Stock: New original, 13000 pcs Stock Available. Quote: <input type="text"/> RFQ



IC Components Limited
WWW.IC-COMPONENTS.COM

Email: Info@IC-Components.com
TEL: 00 852 - 30501935
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong