

LB1861M-TLM-E

Shipment Way:

Manufacturer Part Number: Manufacturer / Brand Part of Description: Datasheets: Lead Free Status / RoHS Status: **Stock Condition: Ship From:**

LB1861M-TLM-E IC BRIDGE DRIVER PAR MFP-14S

🕟 🏒 Lead free / RoHS Compliant

Hong Kong

DHL/Fedex/TNT/UPS

New original, 6000 pcs Stock Available.

GET A QUOTE

LB1861M-TLM-E 100% New Original 6000pcs in Stock, Find LB1861M-TLM-E Price, Stock, datasheet at IC Components Ltd Online, buy LB1861M-TLM-E AMI Semiconductor / ON Semiconductor with warrantied. 100% guarantee confidence. RFQ LB1861M-TLM-E: Info@IC-Components.com

The specifications of LB1861M-TLM-E

Part Number	LB1861M-TLM-E	Manufacturer / Brand	AMI Semiconductor / ON Semiconductor
Series	-	Moisture Sensitivity Level (MSL)	3 (168 Hours)
Package / Case	14-LSOP (0.173", 4.40mm Width)	Packaging	Tape & Reel (TR)
Mounting Type	Surface Mount	Supplier Device Package	14-SOIC / 14MFPS
Operating Temperature	-30°C ~ 80°C (TA)	Detailed Description	Half Bridge (2) Driver DC Motors, General Purpose Bipolar 14-SOIC / 14MFPS
Technology	Bipolar	Features	-
Interface	Logic	Applications	DC Motors, General Purpose
Voltage - Supply	6.4 V ~ 7 V	Current - Output / Channel	1.5A
Current - Peak Output	-	Output Configuration	Half Bridge (2)
Fault Protection	Over Temperature	Load Type	Inductive
Rds On (Typ)	-	Voltage - Load	12V, 24V
Stock Quantity	6000 pcs Stock	Category	Integrated Circuits (ICs) > PMIC - Full, Half-Bridge Drivers
Description	IC BRIDGE DRIVER PAR MFP-14S	Lead Free Status / RoHS Status	Lead free / RoHS Compliant

Keywords realted to LB1861M-TLM-E

AMI Semiconductor / ON Semiconductor LB1861M-	LB1861M-TLM-E part	LB1861M-TLM-E Price	LB1861M-TLM-E Distributor
TLM-E	LB1861M-TLM-E Technical	LB1861M-TLM-E Stock	LB1861M-TLM-E Inventory
LB1861M-TLM-E Supplier	LB1861M-TLM-E Online Order	LB1861M-TLM-E Inquiry	LB1861M-TLM-E Image
LB1861M-TLM-E Picture	LB1861M-TLM-E pdf	LB1861M-TLM-E datasheet	LB1861M-TLM-E data sheet
LB1861M-TLM-E pdf datasheet	Download LB1861M-TLM-E datasheet	AMI Semiconductor / ON Semiconductor Manufacturer	AMI Semiconductor / ON Semiconductor LB1861M-
			TLM-E
ON Semiconductor LB1861M-TLM-E	Aptina / ON Semiconductor LB1861M-TLM-E	Catalyst Semiconductor / ON Semiconductor	PulseCore Semiconductor / ON Semiconductor
		LB1861M-TLM-E	LB1861M-TLM-E
Sanyo Semiconductor / ON Semiconductor LB1861M-			
TLM-E			

You May Be Also Be interested In:



LB1867 Description: LB1867 SANYO SOP14

Manufacturers: SANYO In Stock: New original, 18300 pcs Stock Available. RFQ Quote:



RFQ

RFQ

Quote:

IMAGE NOT Description: LB1862M-MPB-H SANYO SOP10 **AVAILABLE**

LB1862M-MPB-H

Manufacturers: SANYO In Stock: New original, 200 pcs Stock Available. Quote:

In Stock: New original, 200 pcs Stock Available.

Quote:

RFQ

RFQ

LB1847

Description: LB1847 SANYO DIP Manufacturers: SANYO In Stock: New original, 100 pcs Stock Available. RFQ Quote:



Description: LB1860M-TE SANYO SOP14 Manufacturers: SANYO In Stock: New original, 100 pcs Stock Available.

LB1860M-TE

Description: LB1860M-TE-L SANYO SOP-14

Manufacturers: SANYO In Stock: New original, 32500 pcs Stock Available.

RFQ Quote:



IMAGE NOT

IMAGE NOT

AVAILABLE

LB1863M

LB1862

Description: LB1863M SANYO SOP-14 Manufacturers: SANYO In Stock: New original, 400 pcs Stock Available.

Description: LB1862 SANYO DIP-10

Manufacturers: SANYO

Quote:

RFQ



IMAGE NOT

AVAILABLE

IMAGE NOT

AVAILABLE

IMAGE NOT

AVAILABLE

LB1862M-TLM-H **Description:** LB1862M-TLM-H SANYO SOP10 Manufacturers: SANYO

In Stock: New original, 1300 pcs Stock Available.

Quote:

RFQ



LB1860M-TE-L

LB1863M-TE-L **Description:** LB1863M-TE-L SANYO SOP14

Manufacturers: SANYO In Stock: New original, 1000 pcs Stock Available.



LB1862M-NMB-TLM3-E Description: LB1862M-NMB-TLM3-E SANYO SOP Manufacturers: SANYO

In Stock: New original, 9000 pcs Stock Available. Quote:

RFQ



RFQ Quote:

In Stock: New original, 2000 pcs Stock Available.

Description: LB1863M-DELTA-TLM-H SANYO SOP14

Manufacturers: AMI Semiconductor / ON

Description: IC MOTOR DRIVER ON/OFF 10MFPSK




IMAGE NOT

AVAILABLE

IMAGE NOT

AVAILABLE

RFQ Quote:

LB1862M-TLM-E **Description:** LB1862M-TLM-E SANYO SOP10 Manufacturers: SANYO

In Stock: New original, 2600 pcs Stock Available.

Quote:



AVAILABLE

LB1848M-TRM-E

In Stock: New original, 1000 pcs Stock Available.

Description: LB1848M-TRM-E SANYO MFP10S Manufacturers: SANYO

Quote:

RFQ



In Stock: New original, 2000 pcs Stock Available.

LB1862MC-AH

Semiconductor

RFQ Quote:

LB1861M-TE-L

Manufacturers: SANYO

LB1863M-DELTA-TLM-H

Manufacturers: SANYO

Description: LB1861M-TE-L SANYO SMD **In Stock:** New original, 30000 pcs Stock Available. Quote:

RFQ



LB1860M-TLM-H Description: IC MOTOR DRIVER PAR 14MFP

Manufacturers: AMI Semiconductor / ON

In Stock: New original, 50000 pcs Stock Available.

LB1862M-DELTA-TE-L

Manufacturers: SANYO

RFQ Quote:

Description: LB1862M-DELTA-TE-L SANYO SOP-10

Quote:

RFQ

In Stock: New original, 400 pcs Stock Available.

AVAILABLE

IMAGE NOT

Description: LB1848M-TE-R SANYO SOP10 Manufacturers: SANYO

LB1862M

Semiconductor

LB1848M-TE-R

In Stock: New original, 2100 pcs Stock Available.

Description: LB1862M ON SOP10

Manufacturers: AMI Semiconductor / ON

In Stock: New original, 700 pcs Stock Available.

RFQ Quote:

Quote:

RFQ



LB1848M-MPB-H **Description:** LB1848M-MPB-H SANYO SOP10 Manufacturers: SANYO

In Stock: New original, 1300 pcs Stock Available. RFQ Quote:

Description: LB1862M-TE-L SANYO SOP-10

In Stock: New original, 6000 pcs Stock Available.

Quote:

Quote:

RFQ

RFQ

RFQ



AVAILABLE

IMAGE NOT

AVAILABLE

LB1860M-E

Description: LB1860M-E SANYO SOP14 Manufacturers: SANYO

In Stock: New original, 200 pcs Stock Available.

RFQ Quote:




LB1860M-TLM-E **Description:** IC MOTOR DRIVER PAR 14MFP

Manufacturers: AMI Semiconductor / ON In Stock: New original, 1000 pcs Stock Available.

RFQ Quote:

Description: IC BRIDGE DRIVER PAR MFP-14S

Manufacturers: AMI Semiconductor / ON



AVAILABLE

IMAGE NOT

AVAILABLE

LB1860

LB1862M-TE-L

Manufacturers: SANYO

Description: LB1860 SANYO SOP14 Manufacturers: SANYO

In Stock: New original, 29700 pcs Stock Available.



IMAGE NOT

Manufacturers: SANYO

LB1848M

In Stock: New original, 100 pcs Stock Available. Quote:

Description: LB1848M SANYO SOP

RFQ

LB1863M-TLM-H



Semiconductor In Stock: New original, 300 pcs Stock Available.

LB1861M-MPB-H

RFQ Quote:

Description: IC MOTOR DRIVER PAR 14MFP

LB1861M-TLM-H

Quote: RFQ

LB1861M IMAGE NOT Description: LB1861M SANYO SOP14 AVAILABLE

Manufacturers: SANYO In Stock: New original, 1000 pcs Stock Available.

RFQ Quote:

Description: LB1860M-ND-TLM-E SANYO SOP-14

Quote:



Manufacturers: AMI Semiconductor / ON Semiconductor

In Stock: New original, 1400 pcs Stock Available. Quote: RFQ

Description: IC MOTOR DRIVER ON/OFF 14MFP



Manufacturers: AMI Semiconductor / ON Semiconductor

In Stock: New original, 2000 pcs Stock Available.



IMAGE NOT

AVAILABLE

In Stock: New original, 3000 pcs Stock Available.

LB1860M-ND-TLM-E

Manufacturers: SANYO



Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong