



TISP4125L3AJR-S

Manufacturer Part Number:	TISP4125L3AJR-S
Manufacturer / Brand:	Bourns, Inc.
Part of Description:	SINGLE BIDIRECTIONAL PROTECTOR
Datasheets:	TISP4125L3AJR-S.pdf
Lead Free Status / RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	New original, 12300 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

TISP4125L3AJR-S 100% New Original 12300pcs in Stock, Find TISP4125L3AJR-S Price, Stock, datasheet at IC Components Ltd Online, buy TISP4125L3AJR-S Bourns, Inc. with warrantied. 100% guarantee confidence. RFQ TISP4125L3AJR-S: Info@IC-Components.com

The specifications of TISP4125L3AJR-S

Part Number	TISP4125L3AJR-S	Manufacturer / Brand	Bourns, Inc.
Series	-	Moisture Sensitivity Level (MSL)	1 (Unlimited)
Package / Case	DO-214AC, SMA	Packaging	Tape & Reel (TR)
Mounting Type	Surface Mount	Capacitance	48pF
Current - Peak Pulse (10/1000µs)	30A	Voltage - Breakover	125V
Voltage - Off State	100V	Current - Peak Pulse (8/20µs)	100A
Current - Hold (Ih)	150mA	Number of Elements	1
Stock Quantity	12300 pcs Stock	Category	Circuit Protection > TVS - Thyristors
Description	SINGLE BIDIRECTIONAL PROTECTOR	Lead Free Status / RoHS Status	Lead free / RoHS Compliant

Keywords related to TISP4125L3AJR-S

Bourns, Inc. TISP4125L3AJR-S	TISP4125L3AJR-S part	TISP4125L3AJR-S Price	TISP4125L3AJR-S Distributor
TISP4125L3AJR-S Technical	TISP4125L3AJR-S Stock	TISP4125L3AJR-S Inventory	TISP4125L3AJR-S Supplier
TISP4125L3AJR-S Online Order	TISP4125L3AJR-S Inquiry	TISP4125L3AJR-S Image	TISP4125L3AJR-S Picture
TISP4125L3AJR-S pdf	TISP4125L3AJR-S datasheet	TISP4125L3AJR-S data sheet	TISP4125L3AJR-S pdf datasheet
Download TISP4125L3AJR-S datasheet	Bourns, Inc. Manufacturer	Bourns, Inc. TISP4125L3AJR-S	Bourns Inc. TISP4125L3AJR-S
J.W. Miller / Bourns TISP4125L3AJR-S			

You May Be Also Be interested In:

<p>TISP4145M3BJ Description: TISP4145M3BJ BOURNS SMB Manufacturers: Bourns, Inc. In Stock: New original, 2600 pcs Stock Available. Quote: RFQ</p>	<p>TISP4115J3BJR-S Description: THYRISTOR 90V 800A Manufacturers: Bourns, Inc. In Stock: New original, 800 pcs Stock Available. Quote: RFQ</p>	<p>TISP4165J3BJR-S Description: SINGLE BIDIRECTIONAL PROTECTOR Manufacturers: Bourns, Inc. In Stock: New original, 3000 pcs Stock Available. Quote: RFQ</p>
<p>TISP4095H3BJR Description: SURGE SUPP 75V BIDIR DO-214AA Manufacturers: Bourns, Inc. In Stock: New original, 3400 pcs Stock Available. Quote: RFQ</p>	<p>TISP4115M3BJR-S Description: PROTECTOR SINGLE BIDIRECTIONAL Manufacturers: Bourns, Inc. In Stock: New original, 2800 pcs Stock Available. Quote: RFQ</p>	<p>TISP4145L3AJR-S Description: SINGLE BIDIRECTIONAL PROTECTOR Manufacturers: Bourns, Inc. In Stock: New original, 12000 pcs Stock Available. Quote: RFQ</p>
<p>TISP4125L3AJR Description: TISP4125L3AJR BOURNS SMA Manufacturers: Bourns, Inc. In Stock: New original, 5000 pcs Stock Available. Quote: RFQ</p>	<p>TISP4150F3DR Description: TISP4150F3DR BOURNS SO8 Manufacturers: Bourns, Inc. In Stock: New original, 27500 pcs Stock Available. Quote: RFQ</p>	<p>TISP4165L3AJR Description: TISP4165L3AJR BOURNS SMA Manufacturers: Bourns, Inc. In Stock: New original, 5000 pcs Stock Available. Quote: RFQ</p>
<p>TISP4125M3BJR Description: SURGE SUPP 100V BIDIR DO-214AA Manufacturers: Bourns, Inc. In Stock: New original, 3000 pcs Stock Available. Quote: RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>TISP4180F3D Description: TISP4180F3D TI SOP-8 Manufacturers: TI In Stock: New original, 1300 pcs Stock Available. Quote: RFQ</p>	<p>TISP4165M3AJR-S Description: SINGLE BIDIRECTIONAL PROTECTOR Manufacturers: Bourns, Inc. In Stock: New original, 13100 pcs Stock Available. Quote: RFQ</p>
<p>TISP4090L3AJR-S Description: PROTECTOR SINGLE BIDIRECTIONAL Manufacturers: Bourns, Inc. In Stock: New original, 3000 pcs Stock Available. Quote: RFQ</p>	<p>TISP4090M3AJR-S Description: TISP4090M3AJR-S BOURNS SMA(DO-214AC) Manufacturers: Bourns, Inc. In Stock: New original, 12000 pcs Stock Available. Quote: RFQ</p>	<p>TISP4125H3BJR-S Description: PROTECTOR SINGLE BIDIRECT 125V Manufacturers: Bourns, Inc. In Stock: New original, 13100 pcs Stock Available. Quote: RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>TISP4180 Description: TISP4180 BOURNS TO220 Manufacturers: BOURNS In Stock: New original, 3000 pcs Stock Available. Quote: RFQ</p>	<p>TISP4145M3AJR-S Description: SINGLE BIDIRECTIONAL PROTECTOR Manufacturers: Bourns, Inc. In Stock: New original, 12000 pcs Stock Available. Quote: RFQ</p>	<p>TISP4125M3AJR-S Description: SINGLE BIDIRECTIONAL PROTECTOR Manufacturers: Bourns, Inc. In Stock: New original, 12300 pcs Stock Available. Quote: RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>TISP4125F3D Description: TISP4125F3D POWER SOP-8 Manufacturers: POWER In Stock: New original, 2200 pcs Stock Available. Quote: RFQ</p>	<p>TISP4115J1BJR-S Description: SINGLE BIDIRECTIONAL PROTECTOR Manufacturers: Bourns, Inc. In Stock: New original, 9000 pcs Stock Available. Quote: RFQ</p>	<p>TISP4180F3 Description: TISP4180F3 BOURNS SOP8 Manufacturers: Bourns, Inc. In Stock: New original, 700 pcs Stock Available. Quote: RFQ</p>
<p>TISP4125F3DR Description: TISP4125F3DR BOURNS SOP8 Manufacturers: Bourns, Inc. In Stock: New original, 12500 pcs Stock Available. Quote: RFQ</p>	<p>TISP4095M3AJR-S Description: SINGLE BIDIRECTIONAL PROTECTOR Manufacturers: Bourns, Inc. In Stock: New original, 13100 pcs Stock Available. Quote: RFQ</p>	<p>TISP4145M3BJR Description: SURGE SUPP 120V BIDIR DO-214AA Manufacturers: Bourns, Inc. In Stock: New original, 50000 pcs Stock Available. Quote: RFQ</p>
<p>TISP4080M3BJR-S Description: PROTECTOR SINGLE BIDIRECT 80V Manufacturers: Bourns, Inc. In Stock: New original, 3000 pcs Stock Available. Quote: RFQ</p>	<p>TISP4145J1BJR-S Description: PROTECTOR SINGLE BIDIRECTIONAL Manufacturers: Bourns, Inc. In Stock: New original, 900 pcs Stock Available. Quote: RFQ</p>	<p>TISP4145H3BJR-S Description: PROTECTOR SINGLE BIDIRECT 145V Manufacturers: Bourns, Inc. In Stock: New original, 3000 pcs Stock Available. Quote: RFQ</p>
<p>TISP4095H3BJR-S Description: PROTECTOR SINGLE BIDIRECT 95V Manufacturers: Bourns, Inc. In Stock: New original, 3000 pcs Stock Available. Quote: RFQ</p>	<p>TISP4115M3AJR-S Description: THYRISTOR 90V 220A Manufacturers: Bourns, Inc. In Stock: New original, 12600 pcs Stock Available. Quote: RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>TISP4082F3S Description: TISP4082F3S TI SIP2 Manufacturers: TI In Stock: New original, 100 pcs Stock Available. Quote: RFQ</p>



IC Components Limited
WWW.IC-COMPONENTS.COM

Email: Info@IC-Components.com
TEL: 00 852 - 30501935
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong