



1A1305-3

Manufacturer Part Number:	1A1305-3
Manufacturer / Brand	Anaren
Part of Description:	RF DIR COUPLER 1.5GHZ-2.2GHZ SMD
Datasheets:	1A1305-3.pdf
Lead Free Status / RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	New original, 4000 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

1A1305-3 100% New Original 4000pcs in Stock, Find 1A1305-3 Price, Stock, datasheet at IC Components Ltd Online, buy 1A1305-3 Anaren with warrantied. 100% guarantee confidence. RFQ 1A1305-3: Info@IC-Components.com

























The specifications of 1A1305-3

Part Number	1A1305-3	Manufacturer / Brand	Anaren
Supplier Device Package	-	Series	Xinger®
Return Loss	-	Power - Max	100W
Packaging	Tape & Reel (TR)	Package / Case	4-SMD, No Lead
Moisture Sensitivity Level (MSL)	1 (Unlimited)	Isolation	23dB
Insertion Loss	0.25dB	Frequency	1.5GHz ~ 2.2GHz
Detailed Description	RF Directional Coupler General Purpose 1.5GHz ~ 2.2GHz 100W 4-SMD, No Lead	Coupling Factor	-
Coupler Type	Standard	Applications	General Purpose
Stock Quantity	4000 pcs Stock	Category	RF/IF and RFID > RF Directional Coupler
Description	RF DIR COUPLER 1.5GHZ-2.2GHZ SMD	Lead Free Status / RoHS Status	Lead free / RoHS Compliant

Keywords realted to 1A1305-3

Anaren 1A1305-3	1A1305-3 part	1A1305-3 Price	1A1305-3 Distributor
1A1305-3 Technical	1A1305-3 Stock	1A1305-3 Inventory	1A1305-3 Supplier
1A1305-3 Online Order	1A1305-3 Inquiry	1A1305-3 Image	1A1305-3 Picture
1A1305-3 pdf	1A1305-3 datasheet	1A1305-3 data sheet	1A1305-3 pdf datasheet
Download 1A1305-3 datasheet	Anaren Manufacturer	Anaren 1A1305-3	

You May Be Also Be interested In:

 <p>C2327J5003AHF Description: RF DIR COUPLER 2.3-2.7GHZ 0805 Manufacturers: Anaren In Stock: New original, 11700 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>XC0900E-03S Description: RF DIR COUPLER 800MHZ-1GHZ SMD Manufacturers: Anaren In Stock: New original, 2701 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>DC18-731F Description: RF DIR COUPLER 1.71-1.99GHZ SOT6 Manufacturers: Skyworks Solutions, Inc. In Stock: New original, 11400 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>CPL-WB-01C2 Description: RF DIR COUPL 824MHZ-2.025GHZ FLP Manufacturers: STMicroelectronics In Stock: New original, 10500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>1A1305-20 Description: 1A1305-20 ANAREN SMD Manufacturers: ANAREN In Stock: New original, 2603 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>1A1305-5R Description: 1A1305-5R XINGER SMD Manufacturers: XINGER In Stock: New original, 4400 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>CP0603A1880ENTR Description: RF DIR COUPLER 1.85-1.91GHZ 0603 Manufacturers: AVX Corporation In Stock: New original, 2760 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>1A1305-30R Description: 1A1305-30R ANAREN SOP Manufacturers: ANAREN In Stock: New original, 2863 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>1A1305-20R Description: 1A1305-20R ANAREN SMD Manufacturers: ANAREN In Stock: New original, 2774 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>1A1305-15T Description: 1A1305-15T XINGER SMD Manufacturers: XINGER In Stock: New original, 2748 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>1A1G04QDBVRG4Q1 Description: TI SOT23-5 Manufacturers: TI In Stock: New original, 2719 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>0910CF15B0100E Description: RF DIR COUPLER 860-960MHZ 0805 Manufacturers: Johanson Technology In Stock: New original, 2639 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>XC0900A-03S Description: RF DIR COUPLER 811MHZ-1GHZ SMD Manufacturers: Anaren In Stock: New original, 4800 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>XC2100A-20S Description: RF DIR COUPLER 2GHZ-2.3GHZ SMD Manufacturers: Anaren In Stock: New original, 2784 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>1A1306-3 Description: 1A1306-3 XIN SMD Manufacturers: XIN In Stock: New original, 2765 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>1A1305-30T Description: 1A1305-30T XINGER SMD Manufacturers: XINGER In Stock: New original, 2790 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>TFSC06054125-2113A1X Description: RF DIR COUPLER 2.4-2.5GHZ 0202 Manufacturers: TDK Corporation In Stock: New original, 159800 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>CP0805A0902BWTR Description: RF DIR COUPLER 890-915MHZ 0805 Manufacturers: AVX Corporation In Stock: New original, 3000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>1A1305-3R Description: 1A1305-3R ANAREN SMD Manufacturers: ANAREN In Stock: New original, 4700 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>CP0805A1960DWTR Description: RF DIR COUPLER 1.93-1.99GHZ 0805 Manufacturers: AVX Corporation In Stock: New original, 35500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>1A1307-20 Description: 1A1307-20 Anaren SMD Manufacturers: Anaren In Stock: New original, 2854 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>CP0603V0836CNTR Description: RF DIR COUPLER 824-849MHZ 0603 Manufacturers: AVX Corporation In Stock: New original, 90000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>CP0603A1441DWTR Description: RF DIR COUPLER 1.429-1.453GHZ 0603 Manufacturers: AVX Corporation In Stock: New original, 2610 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>1D1304-3 Description: RF DIR COUPLER 800MHZ-1.2GHZ SMD Manufacturers: Anaren In Stock: New original, 2645 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>1A1305-10 Description: 1A1305-10 XINGER SMD Manufacturers: XINGER In Stock: New original, 2645 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>C1720J5003AHF Description: RF DIR COUPLER 1.7GHZ-2GHZ 0805 Manufacturers: Anaren In Stock: New original, 2807 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>CP0603A2070AWTR Description: RF DIR COUPLER 2.07GHZ 0603 Manufacturers: AVX Corporation In Stock: New original, 5700 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>TFSC06054125-2113A1 Description: RF DIR COUPLER 2.4GHZ-2.5GHZ SMD Manufacturers: TDK Corporation In Stock: New original, 127400 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>XC3500M-03S Description: RF DIR COUPLER 3.3GHZ-3.8GHZ SMD Manufacturers: Anaren In Stock: New original, 2889 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>30054 Description: RF DIR COUPLER 500MHZ-1GHZ MOD Manufacturers: Anaren In Stock: New original, 2710 pcs Stock Available. Quote: <input type="text"/> RFQ</p>



IC Components Limited
WWW.IC-COMPONENTS.COM

Email: Info@IC-Components.com
TEL: 00 852 - 30501935
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong