



### CDCU877RHAT

<b>Manufacturer Part Number:</b>	CDCU877RHAT
<b>Manufacturer / Brand</b>	N/A
<b>Part of Description:</b>	IC PLL CLOCK DRIVER 1.8V 40VQFN
<b>Datasheets:</b>	
<b>Lead Free Status / RoHS Status:</b>	Lead free / RoHS Compliant
<b>Stock Condition:</b>	New original, 2823 pcs Stock Available.
<b>Ship From:</b>	Hong Kong
<b>Shipment Way:</b>	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

**CDCU877RHAT** 100% New Original 2823pcs in Stock, Find CDCU877RHAT Price, Stock, datasheet at IC Components Ltd Online, buy CDCU877RHAT with warrantied. 100% guarantee confidence. RFQ CDCU877RHAT: [Info@IC-Components.com](mailto:Info@IC-Components.com)

### The specifications of CDCU877RHAT

Part Number	CDCU877RHAT	Manufacturer / Brand	N/A
Voltage - Supply	1.7 V ~ 1.9 V	Supplier Device Package	40-VQFN (6x6)
Series	-	Ratio - Input:Output	1:10
Packaging	Original-Reel®	Package / Case	40-VFQFN Exposed Pad
PLL	Yes	Output	SSTL-18
Other Names	296-18645-6	Operating Temperature	-40°C ~ 85°C
Number of Circuits	1	Mounting Type	Surface Mount
Moisture Sensitivity Level (MSL)	3 (168 Hours)	Main Purpose	Memory, DDR2
Input	SSTL-18	Frequency - Max	400MHz
Differential - Input:Output	Yes/Yes	Base Part Number	CDCU877
Stock Quantity	2823 pcs Stock	Category	<a href="#">Integrated Circuits (ICs) &gt; Clock/Timing - Application Specific</a>
Description	IC PLL CLOCK DRIVER 1.8V 40VQFN	Lead Free Status / RoHS Status	Lead free / RoHS Compliant

### Keywords related to CDCU877RHAT

<a href="#">CDCU877RHAT</a>	<a href="#">CDCU877RHAT part</a>	<a href="#">CDCU877RHAT Price</a>	<a href="#">CDCU877RHAT Distributor</a>
<a href="#">CDCU877RHAT Technical</a>	<a href="#">CDCU877RHAT Stock</a>	<a href="#">CDCU877RHAT Inventory</a>	<a href="#">CDCU877RHAT Supplier</a>
<a href="#">CDCU877RHAT Online Order</a>	<a href="#">CDCU877RHAT Inquiry</a>	<a href="#">CDCU877RHAT Image</a>	<a href="#">CDCU877RHAT Picture</a>
<a href="#">CDCU877RHAT pdf</a>	<a href="#">CDCU877RHAT datasheet</a>	<a href="#">CDCU877RHAT data sheet</a>	<a href="#">CDCU877RHAT pdf datasheet</a>
<a href="#">Download CDCU877RHAT datasheet</a>	<a href="#">Manufacturer</a>		

### You May Be Also Be interested In:

<p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCUA877ZQLT</b>  <b>Description:</b> IC PLL CLOCK DRIVER 1.8V 52-BGA  <b>Manufacturers:</b> N/A  <b>In Stock:</b> New original, 2858 pcs Stock Available.                  Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCV304</b>  <b>Description:</b> CDCV304 TEXAS TSP08  <b>Manufacturers:</b> TEXAS  <b>In Stock:</b> New original, 2736 pcs Stock Available.                  Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCU877AZQLT</b>  <b>Description:</b> IC PLL CLOCK DRIVER 1.8V 52-BGA  <b>Manufacturers:</b> N/A  <b>In Stock:</b> New original, 2645 pcs Stock Available.                  Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCV304PW</b>  <b>Description:</b> IC CLK BUFFER 1:4 200MHZ 8TSSOP  <b>Manufacturers:</b> N/A  <b>In Stock:</b> New original, 6600 pcs Stock Available.                  Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCU877GQLT</b>  <b>Description:</b> IC PLL CLOCK DRIVER 1.8V 52-BGA  <b>Manufacturers:</b> N/A  <b>In Stock:</b> New original, 2746 pcs Stock Available.                  Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCUA877ZQLR</b>  <b>Description:</b> IC PLL CLOCK DRIVER 1.8V 52-BGA  <b>Manufacturers:</b> N/A  <b>In Stock:</b> New original, 17000 pcs Stock Available.                  Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCU877ZQLT</b>  <b>Description:</b> IC PLL CLOCK DRIVER 1.8V 52-BGA  <b>Manufacturers:</b> N/A  <b>In Stock:</b> New original, 2805 pcs Stock Available.                  Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCV304PWR</b>  <b>Description:</b> IC CLK BUFFER 1:4 200MHZ 8TSSOP  <b>Manufacturers:</b> N/A  <b>In Stock:</b> New original, 56000 pcs Stock Available.                  Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCV850IDGGR</b>  <b>Description:</b> TI TSSOP  <b>Manufacturers:</b> TI  <b>In Stock:</b> New original, 2669 pcs Stock Available.                  Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCV850DGGR</b>  <b>Description:</b> IC PLL CLOCK DRVR 2.5V 48-TSSOP  <b>Manufacturers:</b> N/A  <b>In Stock:</b> New original, 2855 pcs Stock Available.                  Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCV304TPWREP</b>  <b>Description:</b> IC CLK BUFFER 1:4 200MHZ 8TSSOP  <b>Manufacturers:</b> N/A  <b>In Stock:</b> New original, 2690 pcs Stock Available.                  Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCS501PWR</b>  <b>Description:</b> IC CLK GEN/BUFFER SSC 8TSSOP  <b>Manufacturers:</b> N/A  <b>In Stock:</b> New original, 3200 pcs Stock Available.                  Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCV850DGGRG4</b>  <b>Description:</b> IC PLL CLOCK DRVR 2.5V 48TSSOP  <b>Manufacturers:</b> N/A  <b>In Stock:</b> New original, 2650 pcs Stock Available.                  Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCS503TPWRQ1</b>  <b>Description:</b> IC CLK BUFFER 1:1 108MHZ 8TSSOP  <b>Manufacturers:</b> N/A  <b>In Stock:</b> New original, 2685 pcs Stock Available.                  Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCUN1208LPRHBT</b>  <b>Description:</b> IC CLK BUFFER 2:8 400MHZ 32QFN  <b>Manufacturers:</b> N/A  <b>In Stock:</b> New original, 2792 pcs Stock Available.                  Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCV304PWG4</b>  <b>Description:</b> IC CLK BUFFER 1:4 200MHZ 8TSSOP  <b>Manufacturers:</b> N/A  <b>In Stock:</b> New original, 2800 pcs Stock Available.                  Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCU877AGQLR</b>  <b>Description:</b> IC PLL CLOCK DRIVER 1.8V 52-BGA  <b>Manufacturers:</b> N/A  <b>In Stock:</b> New original, 2609 pcs Stock Available.                  Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCV304PWR-TR</b>  <b>Description:</b> TI TSSOP-8  <b>Manufacturers:</b> TI  <b>In Stock:</b> New original, 6000 pcs Stock Available.                  Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCU877ARHARG4</b>  <b>Description:</b> IC PLL CLOCK DRIVER 1.8V 40VQFN  <b>Manufacturers:</b> N/A  <b>In Stock:</b> New original, 2656 pcs Stock Available.                  Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCU877ARHAR</b>  <b>Description:</b> IC CLK BUFFER 1:1 108MHZ 8TSSOP  <b>Manufacturers:</b> N/A  <b>In Stock:</b> New original, 2749 pcs Stock Available.                  Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCU2A877ZQLR</b>  <b>Description:</b> IC PLL CLOCK DRIVER 1.8V 52-BGA  <b>Manufacturers:</b> N/A  <b>In Stock:</b> New original, 23600 pcs Stock Available.                  Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCS502PWR</b>  <b>Description:</b> IC OSC CLOCK GENERATOR 8-TSSOP  <b>Manufacturers:</b> N/A  <b>In Stock:</b> New original, 2770 pcs Stock Available.                  Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCS503PWR</b>  <b>Description:</b> IC CLK BUFFER 1:1 108MHZ 8TSSOP  <b>Manufacturers:</b> N/A  <b>In Stock:</b> New original, 2834 pcs Stock Available.                  Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCU877AZQLR</b>  <b>Description:</b> IC PLL CLOCK DRIVER 1.8V 52-BGA  <b>Manufacturers:</b> N/A  <b>In Stock:</b> New original, 2788 pcs Stock Available.                  Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCU877A</b>  <b>Description:</b> CDCU877A TI BGA  <b>Manufacturers:</b> TI  <b>In Stock:</b> New original, 2654 pcs Stock Available.                  Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCU877ZQLR</b>  <b>Description:</b> IC PLL CLOCK DRIVER 1.8V 52-BGA  <b>Manufacturers:</b> N/A  <b>In Stock:</b> New original, 5000 pcs Stock Available.                  Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCU877RHAR</b>  <b>Description:</b> IC PLL CLOCK DRIVER 1.8V 40VQFN  <b>Manufacturers:</b> N/A  <b>In Stock:</b> New original, 2735 pcs Stock Available.                  Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCU877GQLR</b>  <b>Description:</b> IC PLL CLOCK DRIVER 1.8V 52-BGA  <b>Manufacturers:</b> N/A  <b>In Stock:</b> New original, 2749 pcs Stock Available.                  Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCV304PWRG4</b>  <b>Description:</b> IC CLK BUFFER 1:4 200MHZ 8TSSOP  <b>Manufacturers:</b> N/A  <b>In Stock:</b> New original, 13000 pcs Stock Available.                  Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCS503PW</b>  <b>Description:</b> IC CLK BUFFER 1:1 108MHZ 8TSSOP  <b>Manufacturers:</b> N/A  <b>In Stock:</b> New original, 2783 pcs Stock Available.                  Quote: <input type="text"/> <input type="button" value="RFQ"/></p>



**IC Components Limited**  
WWW.IC-COMPONENTS.COM

Email: [Info@IC-Components.com](mailto:Info@IC-Components.com)  
 TEL: 00 852 - 30501935  
 FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong