

IMAGE NOT AVAILABLE



CDCVF2310PW

Manufacturer Part Number:	CDCVF2310PW
Manufacturer / Brand	N/A
Part of Description:	IC CLK BUF 1:10 200MHZ 24TSSOP
Datasheets:	
Lead Free Status / RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	New original, 2826 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

CDCVF2310PW 100% New Original 2826pcs in Stock, Find CDCVF2310PW Price, Stock, datasheet at IC Components Ltd Online, buy CDCVF2310PW with warranted. 100% guarantee confidence. RFQ CDCVF2310PW: Info@IC-Components.com

The specifications of CDCVF2310PW

Part Number	CDCVF2310PW	Manufacturer / Brand	N/A
Voltage - Supply	2.3 V ~ 3.6 V	Type	Fanout Buffer (Distribution)
Supplier Device Package	24-TSSOP	Series	-
Ratio - Input:Output	1:10	Packaging	Tube
Package / Case	24-TSSOP (0.173", 4.40mm Width)	Output	LVTTTL
Other Names	296-12019-5	Operating Temperature	-40°C ~ 85°C
Number of Circuits	1	Mounting Type	Surface Mount
Moisture Sensitivity Level (MSL)	1 (Unlimited)	Input	LVTTTL
Frequency - Max	200MHz	Differential - Input:Output	No/No
Detailed Description	Clock Fanout Buffer (Distribution) IC 1:10 200MHz 24-TSSOP (0.173", 4.40mm Width)	Base Part Number	CDCVF2310
Stock Quantity	2826 pcs Stock	Category	Integrated Circuits (ICs) > Clock/Timing - Clock Buffers, Drivers
Description	IC CLK BUF 1:10 200MHZ 24TSSOP	Lead Free Status / RoHS Status	Lead free / RoHS Compliant

Keywords related to CDCVF2310PW

CDCVF2310PW	CDCVF2310PW part	CDCVF2310PW Price	CDCVF2310PW Distributor
CDCVF2310PW Technical	CDCVF2310PW Stock	CDCVF2310PW Inventory	CDCVF2310PW Supplier
CDCVF2310PW Online Order	CDCVF2310PW Inquiry	CDCVF2310PW Image	CDCVF2310PW Picture
CDCVF2310PW pdf	CDCVF2310PW datasheet	CDCVF2310PW data sheet	CDCVF2310PW pdf datasheet
Download CDCVF2310PW datasheet	Manufacturer		

You May Be Also Be interested In:

<p>IMAGE NOT AVAILABLE</p> <p>CDCV857DGGR Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP Manufacturers: N/A In Stock: New original, 20000 pcs Stock Available.</p> <p>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCVF11FN Description: IC CLK BUFFER 1:9 650MHZ 28PLCC Manufacturers: N/A In Stock: New original, 2874 pcs Stock Available.</p> <p>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCV857DGGRG4 Description: IC SSTL-II PLL CLK-DRVR 48TSSOP Manufacturers: N/A In Stock: New original, 2752 pcs Stock Available.</p> <p>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p>IMAGE NOT AVAILABLE</p> <p>CDCV857ADGGR Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP Manufacturers: N/A In Stock: New original, 18800 pcs Stock Available.</p> <p>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCVF25081DRG4 Description: IC 1:8 3.3V PLL CLK-DRVR 16-SOIC Manufacturers: N/A In Stock: New original, 2729 pcs Stock Available.</p> <p>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCV857ADGG Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP Manufacturers: N/A In Stock: New original, 2606 pcs Stock Available.</p> <p>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p>IMAGE NOT AVAILABLE</p> <p>CDCVF2505PWR Description: IC 3.3V PLL CLOCK DRVR 8-TSSOP Manufacturers: N/A In Stock: New original, 47200 pcs Stock Available.</p> <p>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCVF11FNR Description: IC CLK BUFFER 1:9 650MHZ 28PLCC Manufacturers: N/A In Stock: New original, 2611 pcs Stock Available.</p> <p>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCV857ADGGRG4 Description: IC SSTL-II PLL CLK-DRVR 48TSSOP Manufacturers: N/A In Stock: New original, 2816 pcs Stock Available.</p> <p>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p>IMAGE NOT AVAILABLE</p> <p>CDCV857AGQLR Description: IC CLK-DRVR PLL 2.5V 56-BGA Manufacturers: N/A In Stock: New original, 2876 pcs Stock Available.</p> <p>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCVF2310PWRG4 Description: IC CLK BUF 1:10 200MHZ 24TSSOP Manufacturers: N/A In Stock: New original, 2603 pcs Stock Available.</p> <p>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCVF2505D Description: IC 3.3V PLL CLOCK DRVR 8-SOIC Manufacturers: N/A In Stock: New original, 2754 pcs Stock Available.</p> <p>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p>IMAGE NOT AVAILABLE</p> <p>CDCVF25081PWR Description: IC 1:8 3.3V PLL CLK-DRVR 16TSSOP Manufacturers: N/A In Stock: New original, 2600 pcs Stock Available.</p> <p>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCVF2310PWR Description: IC CLK BUF 1:10 200MHZ 24TSSOP Manufacturers: N/A In Stock: New original, 6600 pcs Stock Available.</p> <p>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCV857 Description: CDCV857 TI TSSOP48 Manufacturers: TI In Stock: New original, 2690 pcs Stock Available.</p> <p>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p>IMAGE NOT AVAILABLE</p> <p>CDCVF2505DR Description: IC 3.3V PLL CLOCK DRVR 8-SOIC Manufacturers: N/A In Stock: New original, 8500 pcs Stock Available.</p> <p>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCV855PWRG4 Description: IC CLK CLOCK DRVR 2.5V 28TSSOP Manufacturers: N/A In Stock: New original, 2640 pcs Stock Available.</p> <p>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCV857BDGG Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP Manufacturers: N/A In Stock: New original, 2768 pcs Stock Available.</p> <p>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p>IMAGE NOT AVAILABLE</p> <p>CDCVF25081DR Description: IC 1:8 3.3V PLL CLK-DRVR 16-SOIC Manufacturers: N/A In Stock: New original, 2602 pcs Stock Available.</p> <p>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCV855PWR Description: IC 1:4 DDR PLL CLK-DRVR 28-TSSOP Manufacturers: N/A In Stock: New original, 2821 pcs Stock Available.</p> <p>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCVF2505PWG4 Description: IC 3.3V PLL CLOCK-DRVR 8-TSSOP Manufacturers: N/A In Stock: New original, 2776 pcs Stock Available.</p> <p>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p>IMAGE NOT AVAILABLE</p> <p>CDCVF25081PWRG4 Description: IC 1:8 3.3V PLL CLK-DRVR 16TSSOP Manufacturers: N/A In Stock: New original, 2762 pcs Stock Available.</p> <p>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCVF2505DRG4 Description: IC 3.3V PLL CLOCK DRVR 8-SOIC Manufacturers: N/A In Stock: New original, 2641 pcs Stock Available.</p> <p>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCV857BDGGRG4 Description: IC SSTL-II PLL CLK-DRVR 48TSSOP Manufacturers: N/A In Stock: New original, 18000 pcs Stock Available.</p> <p>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p>IMAGE NOT AVAILABLE</p> <p>CDCV857BDGGR Description: IC SSTL-II PLL CLK-DRVR 48TSSOP Manufacturers: N/A In Stock: New original, 26000 pcs Stock Available.</p> <p>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCVF2505PWRG4 Description: IC 3.3V PLL CLOCK DRVR 8-TSSOP Manufacturers: N/A In Stock: New original, 2899 pcs Stock Available.</p> <p>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCVF2505PW Description: IC 3.3V PLL CLOCK-DRVR 8-TSSOP Manufacturers: N/A In Stock: New original, 3400 pcs Stock Available.</p> <p>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p>IMAGE NOT AVAILABLE</p> <p>CDCVF2310MPWREP Description: IC CLK BUF 1:10 200MHZ 24TSSOP Manufacturers: N/A In Stock: New original, 7800 pcs Stock Available.</p> <p>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCVF2509APW Description: IC 3.3V PLL CLK-DRVR 24-TSSOP Manufacturers: N/A In Stock: New original, 2741 pcs Stock Available.</p> <p>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p> <p>CDCVF25081PW Description: IC 1:8 3.3V PLL CLK-DRVR 16TSSOP Manufacturers: N/A In Stock: New original, 2702 pcs Stock Available.</p> <p>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>



IC Components Limited
WWW.IC-COMPONENTS.COM

Email: Info@IC-Components.com
 TEL: 00 852 - 30501935
 FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong