



SY89825UHI

Manufacturer Part Number:	SY89825UHI
Manufacturer / Brand	Micrel / Microchip Technology
Part of Description:	IC CLK BUFFER 2:22 2GHZ 64TQFP
Datasheets:	SY89825UHI.pdf
Lead Free Status / RoHS Status:	Contains lead / RoHS non-compliant
Stock Condition:	New original, 800 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

SY89825UHI 100% New Original 800pcs in Stock, Find SY89825UHI Price, Stock, datasheet at IC Components Ltd Online, buy SY89825UHI Micrel / Microchip Technology with warranted. 100% guarantee confidence. RFQ SY89825UHI: Info@IC-Components.com































The specifications of SY89825UHI

Part Number	SY89825UHI	Manufacturer / Brand	Micrel / Microchip Technology
Series	Precision Edge®	Moisture Sensitivity Level (MSL)	3 (168 Hours)
Base Part Number	SY89825	Package / Case	64-TQFP Exposed Pad
Packaging	Tray	Mounting Type	Surface Mount
Supplier Device Package	64-EP-TQFP	Operating Temperature	-40°C ~ 85°C
Detailed Description	Clock Fanout Buffer (Distribution), Multiplexer, Translator IC 2:22 2GHZ 64-TQFP Exposed Pad	Type	Fanout Buffer (Distribution), Multiplexer, Translator
Frequency - Max	2GHz	Number of Circuits	1
Voltage - Supply	2.37 V ~ 3.6 V	Output	LVPECL
Input	LVDS, LVPECL	Ratio - Input:Output	2:22
Differential - Input:Output	Yes/Yes	Stock Quantily	800 pcs Stock
Category	Integrated Circuits (ICs) > Clock/Timing - Clock Buffers, Drivers	Description	IC CLK BUFFER 2:22 2GHZ 64TQFP
Lead Free Status / RoHS Status	Contains lead / RoHS non-compliant		

Keywords related to SY89825UHI

Micrel / Microchip Technology SY89825UHI	SY89825UHI part	SY89825UHI Price	SY89825UHI Distributor
SY89825UHI Technical	SY89825UHI Stock	SY89825UHI Inventory	SY89825UHI Supplier
SY89825UHI Online Order	SY89825UHI Inquiry	SY89825UHI Image	SY89825UHI Picture
SY89825UHI pdf	SY89825UHI datasheet	SY89825UHI data sheet	SY89825UHI pdf datasheet
Download SY89825UHI datasheet	Micrel / Microchip Technology Manufacturer	Microchip Technology SY89825UHI	Microchip Technology SY89825UHI
Roving Networks / Microchip Technology SY89825UHI			

You May Be Also Be interested In:

 <p>SY89828CHY Description: SY89828CHY MICREL TQFP64 Manufacturers: MICREL In Stock: New original, 2800 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>SY897132LKGTR Description: SY897132LKGTR MICREL TSSOP Manufacturers: MICREL In Stock: New original, 200 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>SY89826LHI Description: IC CLK BUFFER 2:22 1GHZ 64TQFP Manufacturers: Micrel / Microchip Technology In Stock: New original, 2300 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>SY89809LTC Description: IC CLK BUFFER 2:9 500MHZ 32TQFP Manufacturers: Micrel / Microchip Technology In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>SY89809LTH TR Description: SY89809LTH TR MICREL QFP32 Manufacturers: MICREL In Stock: New original, 1000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>SY89831UMGTR Description: SY89831UMGTR micrel MLF-16 Manufacturers: micrel In Stock: New original, 4000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>SY89825UHG Description: IC CLK BUFFER 2:22 2GHZ 64TQFP Manufacturers: Micrel / Microchip Technology In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>SY89826LHY Description: IC CLK BUFFER 2:22 1GHZ 64TQFP Manufacturers: Micrel / Microchip Technology In Stock: New original, 2200 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>SY89824LHC Description: IC CLK BUFFER 2:22 64TQFP Manufacturers: Micrel / Microchip Technology In Stock: New original, 600 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>SY89823LHY Description: IC CLK BUFFER 2:22 500MHZ 64TQFP Manufacturers: Micrel / Microchip Technology In Stock: New original, 1300 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>SY89824LHZTR Description: SY89824LHZTR MICREL QFP-64L Manufacturers: MICREL In Stock: New original, 700 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>SY89825UHY Description: IC CLK BUFFER 2:22 2GHZ 64TQFP Manufacturers: Micrel / Microchip Technology In Stock: New original, 1100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>SY89830UK4G Description: IC CLK BUFFER 2:4 2.5GHZ 16TSSOP Manufacturers: Micrel / Microchip Technology In Stock: New original, 800 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>SY89809L Description: SY89809L MICREL QFP32 Manufacturers: MICREL In Stock: New original, 700 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>SY89829UHY Description: IC CLK BUFFER 2:10 2GHZ 64TQFP Manufacturers: Micrel / Microchip Technology In Stock: New original, 2000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>SY89827LHI Description: IC CLK BUF 4:20/2:10 64TQFP Manufacturers: Micrel / Microchip Technology In Stock: New original, 800 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>SY89831U Description: SY89831U MICREL MLF-16 Manufacturers: MICREL In Stock: New original, 1200 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>SY897132L Description: SY897132L MIC TSSOP-28 Manufacturers: MIC In Stock: New original, 14600 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>SY89827LHG Description: SY89827LHG MICREL QFP Manufacturers: MICREL In Stock: New original, 300 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>SY89830UK4G-TR Description: IC CLK BUFFER 2:4 2.5GHZ 16TSSOP Manufacturers: Micrel / Microchip Technology In Stock: New original, 1000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>SY89824LHZ Description: IC CLK BUFFER 2:22 64TQFP Manufacturers: Micrel / Microchip Technology In Stock: New original, 600 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>SY89831UMG Description: IC CLK BUFFER 1:4 2GHZ 16MLF Manufacturers: Micrel / Microchip Technology In Stock: New original, 12600 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>SY89831UMI Description: IC CLK BUFFER 1:4 2GHZ 16MLF Manufacturers: Micrel / Microchip Technology In Stock: New original, 13200 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>SY89808LTG Description: IC CLK BUFFER 2:9 500MHZ 32TQFP Manufacturers: Micrel / Microchip Technology In Stock: New original, 300 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>SY89809LTH Description: IC CLK BUFFER 2:9 500MHZ 32TQFP Manufacturers: Micrel / Microchip Technology In Stock: New original, 600 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>SY89826LHG Description: SY89826LHG MICREL TQFP64 Manufacturers: MICREL In Stock: New original, 1200 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>SY89828LHY Description: IC CLK BUFFER 2:10 1GHZ 64TQFP Manufacturers: Micrel / Microchip Technology In Stock: New original, 4200 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>SY89809ALTZ Description: IC CLK BUFFER 2:9 750MHZ 32TQFP Manufacturers: Micrel / Microchip Technology In Stock: New original, 200 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>SY897132LKG Description: IC CLK LINK REPLICATOR HDTV Manufacturers: Micrel / Microchip Technology In Stock: New original, 400 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>SY89823LHI Description: IC CLK BUFFER 2:22 500MHZ 64TQFP Manufacturers: Micrel / Microchip Technology In Stock: New original, 600 pcs Stock Available. Quote: <input type="text"/> RFQ</p>



IC Components Limited
WWW.IC-COMPONENTS.COM

Email: Info@IC-Components.com
TEL: 00 852 - 30501935
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong