



## CDCEL925PWR

<b>Manufacturer Part Number:</b>	CDCEL925PWR
<b>Manufacturer / Brand</b>	N/A
<b>Part of Description:</b>	IC 2PLL VCXO CLK SYNTH 16-TSSOP
<b>Datasheets:</b>	
<b>Lead Free Status / RoHS Status:</b>	Lead free / RoHS Compliant
<b>Stock Condition:</b>	New original, 2764 pcs Stock Available.
<b>Ship From:</b>	Hong Kong
<b>Shipment Way:</b>	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

**CDCEL925PWR** 100% New Original 2764pcs in Stock, Find CDCEL925PWR Price, Stock, datasheet at IC Components Ltd Online, buy CDCEL925PWR with warrantied. 100% guarantee confidence. RFQ CDCEL925PWR: [Info@IC-Components.com](mailto:Info@IC-Components.com)

### The specifications of CDCEL925PWR

Part Number	CDCEL925PWR	Manufacturer / Brand	N/A
Voltage - Supply	1.7 V ~ 1.9 V	Type	Clock/Frequency Synthesizer
Supplier Device Package	16-TSSOP	Series	-
Ratio - Input:Output	1:5	Packaging	Original-Reel®
Package / Case	16-TSSOP (0.173", 4.40mm Width)	PLL	Yes with Bypass
Output	LVC MOS	Other Names	296-48117-6
Operating Temperature	-40°C ~ 85°C	Number of Circuits	1
Mounting Type	Surface Mount	Moisture Sensitivity Level (MSL)	1 (Unlimited)
Input	LVC MOS, Crystal	Frequency - Max	230MHz
Divider/Multiplier	Yes/No	Differential - Input:Output	No/No
Base Part Number	CDCEL925	Stock Quantity	2764 pcs Stock
Category	<a href="#">Integrated Circuits (ICs)</a> > <a href="#">Clock/Timing</a> - <a href="#">Clock Generators, PLLs, Frequency Synthesizers</a>	Description	IC 2PLL VCXO CLK SYNTH 16-TSSOP
Lead Free Status / RoHS Status	Lead free / RoHS Compliant		

### Keywords related to CDCEL925PWR

<a href="#">CDCEL925PWR</a>	<a href="#">CDCEL925PWR part</a>	<a href="#">CDCEL925PWR Price</a>	<a href="#">CDCEL925PWR Distributor</a>
<a href="#">CDCEL925PWR Technical</a>	<a href="#">CDCEL925PWR Stock</a>	<a href="#">CDCEL925PWR Inventory</a>	<a href="#">CDCEL925PWR Supplier</a>
<a href="#">CDCEL925PWR Online Order</a>	<a href="#">CDCEL925PWR Inquiry</a>	<a href="#">CDCEL925PWR Image</a>	<a href="#">CDCEL925PWR Picture</a>
<a href="#">CDCEL925PWR pdf</a>	<a href="#">CDCEL925PWR datasheet</a>	<a href="#">CDCEL925PWR data sheet</a>	<a href="#">CDCEL925PWR pdf datasheet</a>
<a href="#">Download CDCEL925PWR datasheet</a>	<a href="#">Manufacturer</a>		

### You May Be Also Be interested In:

<p><b>CDCEL913PWR</b> <b>Description:</b> IC 1-PLL VCXO CLK SYNTH 14-TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2600 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p><b>CDCFR83ADBQ</b> <b>Description:</b> IC CLOCK GENERATOR 533MHZ 24QSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2738 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p><b>CDCE949R04PWR</b> <b>Description:</b> CDCE949R04PWR TEXAS TSSOP-24L <b>Manufacturers:</b> TEXAS <b>In Stock:</b> New original, 28500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p><b>CDCF2509PWR</b> <b>Description:</b> IC 3.3V PLL CLOCK-DRVR 24-TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 26500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p><b>CDCEL913PWRG4</b> <b>Description:</b> IC 1-PLL VCXO CLK SYNTH 14-TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2621 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p><b>CDCE936PW</b> <b>Description:</b> CDCE936PW TI TSSOP <b>Manufacturers:</b> TI <b>In Stock:</b> New original, 2629 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p><b>CDCE949PWG4</b> <b>Description:</b> IC 4-PLL VCXO LVC MOS 24-TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2770 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p><b>CDCF2510PWR</b> <b>Description:</b> IC 3.3V PLL CLK-DRVR 24-TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 30000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p><b>CDCEL937QPWRQ1</b> <b>Description:</b> IC 3-PLL VCXO LVC MOS 20TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 10000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p><b>CDCEL913IPWRQ1</b> <b>Description:</b> IC 1PLL VCXO CLK SYNTH 14TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p><b>CDCEL925PW</b> <b>Description:</b> IC 2PLL VCXO CLK SYNTH 16-TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2765 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p><b>CDCE949QPWRQ1</b> <b>Description:</b> IC 4-PLL VCXO LVC MOS 24TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2644 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p><b>CDCF5801DBQRG4</b> <b>Description:</b> IC PLL CLOCK MULTIPLIER 24-QSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2783 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p><b>CDCFR83</b> <b>Description:</b> CDCFR83 TI TSSOP <b>Manufacturers:</b> TI <b>In Stock:</b> New original, 2898 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p><b>CDCEL913PW</b> <b>Description:</b> IC 1-PLL VCXO CLK SYNTH 14-TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 5000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p><b>CDCFR83ADBQR</b> <b>Description:</b> IC CLOCK GENERATOR 533MHZ 24QSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2635 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p><b>CDCEL949PWRG4</b> <b>Description:</b> IC 4-PLL VCXO CLK SYNTH 24-TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2615 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p><b>CDCE949PWR</b> <b>Description:</b> IC 4-PLL VCXO LVC MOS 24-TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2708 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p><b>CDCF2510</b> <b>Description:</b> CDCF2510 TEXAS SOP <b>Manufacturers:</b> TEXAS <b>In Stock:</b> New original, 3300 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p><b>CDCE937PW</b> <b>Description:</b> IC 3PLL VCXO CLK SYNTH 20-TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2862 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p><b>CDCE937Q</b> <b>Description:</b> CDCE937Q TI优势 TSSOP <b>Manufacturers:</b> TI <b>In Stock:</b> New original, 2865 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p><b>CDCF2509</b> <b>Description:</b> CDCF2509 TI TSOP24 <b>Manufacturers:</b> TI <b>In Stock:</b> New original, 2639 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p><b>CDCE937PWR</b> <b>Description:</b> IC 3PLL VCXO CLK SYNTH 20-TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p><b>CDCE937QPWRQ1</b> <b>Description:</b> IC 3PLL VCXO CLK SYNTH 20TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 6600 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p><b>CDCF2509PW</b> <b>Description:</b> IC 3.3V PLL CLOCK-DRVR 24-TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 4200 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p><b>CDCE949PW</b> <b>Description:</b> IC 4-PLL VCXO LVC MOS 24-TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2652 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p><b>CDCEL949PW</b> <b>Description:</b> TI TSSOP <b>Manufacturers:</b> TI <b>In Stock:</b> New original, 2782 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p><b>CDCF2510PW</b> <b>Description:</b> IC 3.3V PLL CLOCK-DRVR 24-TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2691 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p><b>CDCF5801DBQ</b> <b>Description:</b> IC CLOCK MULTIPLIER/DIV 24-QSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 2672 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p><b>CDCEL937PWR</b> <b>Description:</b> IC 3-PLL VCXO CLK SYNTH 20-TSSOP <b>Manufacturers:</b> N/A <b>In Stock:</b> New original, 10000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>



**IC Components Limited**  
WWW.IC-COMPONENTS.COM

Email: [Info@IC-Components.com](mailto:Info@IC-Components.com)  
TEL: 00 852 - 30501935  
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong