



**LB11876-TLM-E**

Manufacturer Part Number:	LB11876-TLM-E
Manufacturer / Brand	AMI Semiconductor / ON Semiconductor
Part of Description:	IC MOTOR CONTROLLER PAR 36SSOP
Datasheets:	LB11876-TLM-E.pdf
Lead Free Status / RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	New original, 100 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

**LB11876-TLM-E** 100% New Original 100pcs in Stock, Find LB11876-TLM-E Price, Stock, datasheet at IC Components Ltd Online, buy LB11876-TLM-E AMI Semiconductor / ON Semiconductor with warrantied. 100% guarantee confidence. RFQ LB11876-TLM-E: [Info@IC-Components.com](mailto:Info@IC-Components.com)

The specifications of LB11876-TLM-E

Part Number	LB11876-TLM-E	Manufacturer / Brand	AMI Semiconductor / ON Semiconductor
Series	-	Moisture Sensitivity Level (MSL)	3 (168 Hours)
Base Part Number	LB11876	Package / Case	36-LSOP (0.220", 5.60mm Width)
Packaging	Tape & Reel (TR)	Mounting Type	Surface Mount
Supplier Device Package	36-SSOP	Operating Temperature	-20°C ~ 85°C (TA)
Detailed Description	Motor Driver Parallel 36-SSOP	Technology	-
Interface	Parallel	Applications	Polygonal Mirror
Voltage - Supply	4.5 V ~ 5.5 V, 8 V ~ 17 V	Function	Controller - Commutation, Direction Management
Current - Output	-	Output Configuration	Pre-Driver - Half Bridge (3)
Voltage - Load	-	Motor Type - Stepper	-
Motor Type - AC, DC	Brushless DC (BLDC)	Step Resolution	-
Stock Quantity	100 pcs Stock	Category	<a href="#">Integrated Circuits (ICs) &gt; PMIC - Motor Drivers, Controllers</a>
Description	IC MOTOR CONTROLLER PAR 36SSOP	Lead Free Status / RoHS Status	Lead free / RoHS Compliant

Keywords related to LB11876-TLM-E

AMI Semiconductor / ON Semiconductor LB11876-TLM-E	LB11876-TLM-E part	LB11876-TLM-E Price	LB11876-TLM-E Distributor
	LB11876-TLM-E Technical	LB11876-TLM-E Stock	LB11876-TLM-E Inventory
LB11876-TLM-E Supplier	LB11876-TLM-E Online Order	LB11876-TLM-E Inquiry	LB11876-TLM-E Image
LB11876-TLM-E Picture	LB11876-TLM-E pdf	LB11876-TLM-E datasheet	LB11876-TLM-E data sheet
LB11876-TLM-E pdf datasheet	Download LB11876-TLM-E datasheet	AMI Semiconductor / ON Semiconductor Manufacturer	AMI Semiconductor / ON Semiconductor LB11876-TLM-E
ON Semiconductor LB11876-TLM-E	Aptina / ON Semiconductor LB11876-TLM-E	Catalyst Semiconductor / ON Semiconductor LB11876-TLM-E	PulseCore Semiconductor / ON Semiconductor LB11876-TLM-E
Sanyo Semiconductor / ON Semiconductor LB11876-TLM-E			

You May Be Also Be interested In:

 <b>LB11885</b> Description: LB11885 SANYO HSOP-48P Manufacturers: SANYO In Stock: New original, 2000 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 <b>LB11861M-TLM-E</b> Description: LB11861M-TLM-E SANYO SOP-10 Manufacturers: SANYO In Stock: New original, 400 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 <b>LB11884</b> Description: LB11884 SANYO SOP-44 Manufacturers: SANYO In Stock: New original, 100 pcs Stock Available. Quote: <input type="button" value="RFQ"/>
 <b>LB11861MC-AH</b> Description: IC MOTOR DRIVER PWM 10MFPSK Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 3000 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 <b>LB11861M-TLM-E</b> Description: LB11861M-TLM-E SANYO SOP10 Manufacturers: SANYO In Stock: New original, 5000 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 <b>LB11880</b> Description: LB11880 SANYO DIP Manufacturers: SANYO In Stock: New original, 6000 pcs Stock Available. Quote: <input type="button" value="RFQ"/>
 <b>LB11861M-TLM-H</b> Description: LB11861M-TLM-H SANYO SOP10 Manufacturers: SANYO In Stock: New original, 900 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 <b>LB11882N</b> Description: LB11882N SANYO HSOP-48P Manufacturers: SANYO In Stock: New original, 300 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 <b>LB11867FV-ND-TLM-E</b> Description: LB11867FV-ND-TLM-E SANYO SSOP-20 Manufacturers: SANYO In Stock: New original, 6000 pcs Stock Available. Quote: <input type="button" value="RFQ"/>
 <b>LB11883</b> Description: LB11883 SANYO SSOP Manufacturers: SANYO In Stock: New original, 3600 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 <b>LB11867FV-TLM-E</b> Description: IC MOTOR CONTROLLER PAR 16SSOP Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 10000 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 <b>LB11867FV-TLM</b> Description: LB11867FV-TLM SANYO TSSOP Manufacturers: SANYO In Stock: New original, 200 pcs Stock Available. Quote: <input type="button" value="RFQ"/>
 <b>LB11862M-TLM-H</b> Description: LB11862M-TLM-H ON SOP-10 Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 700 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 <b>LB11862M-TE-L</b> Description: LB11862M-TE-L SANYO SOP-10 Manufacturers: SANYO In Stock: New original, 9000 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 <b>LB11872</b> Description: LB11872 SANYO HSOP-28P Manufacturers: SANYO In Stock: New original, 300 pcs Stock Available. Quote: <input type="button" value="RFQ"/>
 <b>LB11889M</b> Description: LB11889M SANYO SOP Manufacturers: SANYO In Stock: New original, 500 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 <b>LB11885-TRM</b> Description: LB11885-TRM SANYO SSOP Manufacturers: SANYO In Stock: New original, 5000 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 <b>LB11870</b> Description: LB11870 SANYO SOPW48 Manufacturers: SANYO In Stock: New original, 2500 pcs Stock Available. Quote: <input type="button" value="RFQ"/>
 <b>LB11886N</b> Description: LB11886N SANYO HSOP-28P Manufacturers: SANYO In Stock: New original, 600 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 <b>LB11885J</b> Description: LB11885J SANYO HSOP-48P Manufacturers: SANYO In Stock: New original, 1600 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 <b>LB11867RV-TLM-H</b> Description: IC MOTOR CONTROLLER PAR 16SSOP Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 1800 pcs Stock Available. Quote: <input type="button" value="RFQ"/>
 <b>LB11862M-TLM-E</b> Description: LB11862M-TLM-E SANYO SOP10 Manufacturers: SANYO In Stock: New original, 2000 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 <b>LB11867RV-MPB-H</b> Description: IC MOTOR CTR PAR/PWM SSOP16 Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 100 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 <b>LB11883N</b> Description: LB11883N SANYO SSOP-44P Manufacturers: SANYO In Stock: New original, 400 pcs Stock Available. Quote: <input type="button" value="RFQ"/>
 <b>LB11908</b> Description: LB11908 SANYO SSOP30 Manufacturers: SANYO In Stock: New original, 600 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 <b>LB11884N</b> Description: LB11884N SANYO SSOP-44P Manufacturers: SANYO In Stock: New original, 500 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 <b>LB11867FV-TLM-H</b> Description: IC MOTOR CONTROLLER PAR 16SSOP Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 4000 pcs Stock Available. Quote: <input type="button" value="RFQ"/>
 <b>LB11899</b> Description: LB11899 SANYO SSOP-44P Manufacturers: SANYO In Stock: New original, 1900 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 <b>LB11906V-B-TRM-E</b> Description: LB11906V-B-TRM-E SANYO SOPPB Manufacturers: SANYO In Stock: New original, 19000 pcs Stock Available. Quote: <input type="button" value="RFQ"/>	 <b>LB11882J</b> Description: LB11882J SANYO HSOP-48P Manufacturers: SANYO In Stock: New original, 5000 pcs Stock Available. Quote: <input type="button" value="RFQ"/>



**IC Components Limited**  
WWW.IC-COMPONENTS.COM

Email: [Info@IC-Components.com](mailto:Info@IC-Components.com)  
TEL: 00 852 - 30501935  
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong