


IMAGE NOT AVAILABLE



THS6032IGQER

Manufacturer Part Number:	THS6032IGQER
Manufacturer / Brand	N/A
Part of Description:	IC LINE DRIVER DSL 2CHAN 80BGA
Datasheets:	
Lead Free Status / RoHS Status:	 Lead free / RoHS Compliant
Stock Condition:	New original, 10800 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

GET A QUOTE

THS6032IGQER 100% New Original 10800pcs In Stock, Find THS6032IGQER Price, Stock, datasheet at IC Components Ltd Online, buy THS6032IGQER with warrantied. 100% guarantee confidence. RFQ THS6032IGQER: Info@IC-Components.com

The specifications of THS6032IGQER

Part Number	THS6032IGQER	Manufacturer / Brand	N/A
Voltage - Supply	5 V ~ 16 V	Type	Driver
Supplier Device Package	80-BGA MICROSTAR JUNIOR (5x5)	Series	-
Protocol	DSL	Packaging	Original-Reel®
Package / Case	80-VFBGA	Other Names	296-10066-6
Operating Temperature	-40°C ~ 85°C	Number of Drivers/Receivers	2/0
Mounting Type	Surface Mount	Moisture Sensitivity Level (MSL)	2 (1 Year)
Duplex	-	Detailed Description	2/0 Driver DSL 80-BGA MICROSTAR JUNIOR (5x5)
Data Rate	-	Base Part Number	THS6032
Stock Quantity	10800 pcs Stock	Category	Integrated Circuits (ICs) > Interface - Drivers, Receivers, Transceivers
Description	IC LINE DRIVER DSL 2CHAN 80BGA	Lead Free Status / RoHS Status	Lead free / RoHS Compliant

Keywords realted to THS6032IGQER

THS6032IGQER	THS6032IGQER part	THS6032IGQER Price	THS6032IGQER Distributor
THS6032IGQER Technical	THS6032IGQER Stock	THS6032IGQER Inventory	THS6032IGQER Supplier
THS6032IGQER Online Order	THS6032IGQER Inquiry	THS6032IGQER Image	THS6032IGQER Picture
THS6032IGQER pdf	THS6032IGQER datasheet	THS6032IGQER data sheet	THS6032IGQER pdf datasheet
Download THS6032IGQER datasheet	Manufacturer		

You May Be Also Be interested In:

<p>IMAGE NOT AVAILABLE</p> <p>THS6062CDGN Description: IC DIFF RCVR DUAL HS LN 8-MSOP Manufacturers: N/A In Stock: New original, 2765 pcs Stock Available.</p> <p>Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>THS6052I Description: IC DIFF RCVR DUAL HS LN 8-MSOP Manufacturers: TI In Stock: New original, 5000 pcs Stock Available.</p> <p>Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>THS6012IDWPR Description: IC LINE DVR 500MA DUAL 20SOPWR Manufacturers: N/A In Stock: New original, 15400 pcs Stock Available.</p> <p>Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>THS6022IPW Description: THS6022IPW TI TSSOP Manufacturers: TI In Stock: New original, 2622 pcs Stock Available.</p> <p>Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>THS6043ID Description: IC CPE LINE DRVR HS W/SD 14-SOIC Manufacturers: N/A In Stock: New original, 2705 pcs Stock Available.</p> <p>Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>THS6012IDW Description: THS6012IDW TI SOP20 Manufacturers: TI In Stock: New original, 2605 pcs Stock Available.</p> <p>Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>THS6032I Description: THS6032I TI SOP-20 Manufacturers: TI In Stock: New original, 2683 pcs Stock Available.</p> <p>Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>THS6032IDWPR Description: IC LINE DRIVER 2CHAN 20SO-PWR Manufacturers: N/A In Stock: New original, 3500 pcs Stock Available.</p> <p>Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>THS6032TVFP Description: THS6032TVFP QFP 02 Manufacturers: QFP In Stock: New original, 8700 pcs Stock Available.</p> <p>Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>THS6022IPWP Description: IC DUAL DIFF LINE DRVR 14-HTSSOP Manufacturers: N/A In Stock: New original, 2813 pcs Stock Available.</p> <p>Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>THS6053ID Description: IC LINE DRIVER DSL 2CHAN 14SOIC Manufacturers: N/A In Stock: New original, 5000 pcs Stock Available.</p> <p>Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>THS6022C Description: THS6022C TI SSOP14 Manufacturers: TI In Stock: New original, 2788 pcs Stock Available.</p> <p>Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>THS6062CDGNR Description: IC DIFF RCVR DUAL HS LN 8-MSOP Manufacturers: N/A In Stock: New original, 12500 pcs Stock Available.</p> <p>Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>THS6062CDR SOP8 Description: THS6062CDR SOP8 TI SOP8 Manufacturers: TI In Stock: New original, 2500 pcs Stock Available.</p> <p>Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>THS6053CPWP Description: IC ADSL CPE DVR 175MA 14-HTSSOP Manufacturers: N/A In Stock: New original, 2847 pcs Stock Available.</p> <p>Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>THS6022CPWP Description: IC DUAL DIFF LINE DRVR 14-HTSSOP Manufacturers: N/A In Stock: New original, 4000 pcs Stock Available.</p> <p>Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>THS6062CDRG4 Description: IC ADSL DUAL DIFF RCVR 8-SOIC Manufacturers: N/A In Stock: New original, 15500 pcs Stock Available.</p> <p>Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>THS6012IDWP Description: IC LINE DVR 500MA DUAL 20SOPWR Manufacturers: N/A In Stock: New original, 2645 pcs Stock Available.</p> <p>Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>THS6032CDWP Description: IC LP ADSL LINE DRVR 20SOPWRPAD Manufacturers: N/A In Stock: New original, 2702 pcs Stock Available.</p> <p>Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>THS6032I Description: THS6032I TEXAS SOP-20 Manufacturers: TEXAS In Stock: New original, 2750 pcs Stock Available.</p> <p>Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>THS6062CD Description: IC DUAL ADSL DIFF RCVR 8-SOIC Manufacturers: N/A In Stock: New original, 2783 pcs Stock Available.</p> <p>Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>THS6062CDR Description: IC ADSL DUAL DIFF RCVR 8-SOIC Manufacturers: N/A In Stock: New original, 16300 pcs Stock Available.</p> <p>Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>THS6032IDW Description: THS6032IDW TEXAS SOP-20 Manufacturers: TEXAS In Stock: New original, 2865 pcs Stock Available.</p> <p>Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>THS6043C Description: THS6043C TI SOP-14 Manufacturers: TI In Stock: New original, 2778 pcs Stock Available.</p> <p>Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>THS6022CPWPR Description: IC LINE DVR 250MA DUAL 14-HTSSOP Manufacturers: N/A In Stock: New original, 22600 pcs Stock Available.</p> <p>Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>THS6042IDR Description: IC LINE DRIVER DSL 2CHAN 8SOIC Manufacturers: N/A In Stock: New original, 2780 pcs Stock Available.</p> <p>Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>THS6032IDWP Description: IC LINE DRIVER 2CHAN 20SO-PWR Manufacturers: N/A In Stock: New original, 2706 pcs Stock Available.</p> <p>Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>THS6053I Description: THS6053I TI SOP14 Manufacturers: TI In Stock: New original, 2694 pcs Stock Available.</p> <p>Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>THS6022IPWPR Description: IC LINE DVR 250MA DUAL 14-HTSSOP Manufacturers: N/A In Stock: New original, 2500 pcs Stock Available.</p> <p>Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>THS6052ID Description: IC LINE DVR 250MA DUAL 14-HTSSOP Manufacturers: N/A In Stock: New original, 2778 pcs Stock Available.</p> <p>Quote: <input type="text"/> RFQ</p>



IC Components Limited
WWW.IC-COMPONENTS.COM

Email: Info@IC-Components.com

TEL: 00 852 - 30501935

FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong