



LB11851MC-BH

Manufacturer Part Number:	LB11851MC-BH
Manufacturer / Brand:	AMI Semiconductor / ON Semiconductor
Part of Description:	IC MOTOR CONTROLLER PWM 10SOIC
Datasheets:	LB11851MC-BH.pdf
Lead Free Status / RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	New original, 2200 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

LB11851MC-BH 100% New Original 2200pcs in Stock, Find LB11851MC-BH Price, Stock, datasheet at IC Components Ltd Online, buy LB11851MC-BH AMI Semiconductor / ON Semiconductor with warrantied, 100% guarantee confidence. RFQ LB11851MC-BH: Info@IC-Components.com































The specifications of LB11851MC-BH

Part Number	LB11851MC-BH	Manufacturer / Brand	AMI Semiconductor / ON Semiconductor
Series	-	Moisture Sensitivity Level (MSL)	1 (Unlimited)
Base Part Number	LB11851	Package / Case	10-SOP (0.154", 3.90mm Width)
Packaging	Tape & Reel (TR)	Mounting Type	Surface Mount
Supplier Device Package	10-SOIC	Operating Temperature	-30°C ~ 90°C (TA)
Detailed Description	Motor Driver PWM 10-SOIC	Technology	-
Interface	PWM	Applications	Fan Controller
Voltage - Supply	6 V ~ 16 V	Function	Controller - Commutation, Direction Management
Current - Output	-	Output Configuration	Pre-Driver - Half Bridge (2)
Voltage - Load	-	Motor Type - Stepper	-
Motor Type - AC, DC	Brushed DC	Step Resolution	-
Stock Quantity	2200 pcs Stock	Category	Integrated Circuits (ICs) > PMIC - Motor Drivers, Controllers
Description	IC MOTOR CONTROLLER PWM 10SOIC	Lead Free Status / RoHS Status	Lead free / RoHS Compliant

Keywords related to LB11851MC-BH

AMI Semiconductor / ON Semiconductor LB11851MC-BH	LB11851MC-BH part	LB11851MC-BH Price	LB11851MC-BH Distributor
LB11851MC-BH Supplier	LB11851MC-BH Technical	LB11851MC-BH Stock	LB11851MC-BH Inventory
LB11851MC-BH Picture	LB11851MC-BH Online Order	LB11851MC-BH Inquiry	LB11851MC-BH Image
LB11851MC-BH pdf datasheet	LB11851MC-BH pdf	LB11851MC-BH datasheet	LB11851MC-BH data sheet
Download LB11851MC-BH datasheet	Download LB11851MC-BH datasheet	AMI Semiconductor / ON Semiconductor Manufacturer	AMI Semiconductor / ON Semiconductor LB11851MC-BH
ON Semiconductor LB11851MC-BH	Aptina / ON Semiconductor LB11851MC-BH	Catalyst Semiconductor / ON Semiconductor	PulseCore Semiconductor / ON Semiconductor
Sanyo Semiconductor / ON Semiconductor		LB11851MC-BH	LB11851MC-BH

You May Be Also Be interested In:

 LB11825 Description: LB11825 SANYO SOP14 Manufacturers: SANYO In Stock: New original, 13600 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11696V-TLM-E Description: IC MOTOR CONTROLLER PAR 30SSOP Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 4400 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11820M-MPB-E Description: LB11820M-MPB-E SANYO SOP30 Manufacturers: SANYO In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ
 LB11852RV-MPB-H Description: IC MOTOR CTRLR PAR/PWM SSOP20J Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 1200 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11852FV-MPB-H Description: IC MOTOR CTRLR PAR/PWM SSOP20J Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 3100 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11847 Description: LB11847 SANYO DIP Manufacturers: SANYO In Stock: New original, 500 pcs Stock Available. Quote: <input type="text"/> RFQ
 LB1186 Description: LB1186 SANYO SOP Manufacturers: SANYO In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11861MC-AH Description: IC MOTOR DRIVER PWM 10MFPSK Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 3000 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11826 Description: LB11826 SANYO DIP-28P Manufacturers: SANYO In Stock: New original, 500 pcs Stock Available. Quote: <input type="text"/> RFQ
 LB11813 Description: LB11813 SANYO SSOP Manufacturers: SANYO In Stock: New original, 5200 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11851TT-TLM-H Description: IC MOTOR CONTROLLER PWM 10MSOP Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 1800 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11816V-MPB-E Description: LB11816V-MPB-E SANYO SOP Manufacturers: SANYO In Stock: New original, 700 pcs Stock Available. Quote: <input type="text"/> RFQ
 LB11827-E Description: LB11827-E SANYO DIP28 Manufacturers: SANYO In Stock: New original, 1000 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11820M-TE-L Description: LB11820M-TE-L SANYO SSOP30 Manufacturers: SANYO In Stock: New original, 3200 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11861-N-TLM-H Description: LB11861-N-TLM-H SANYO HSOP16 Manufacturers: SANYO In Stock: New original, 1700 pcs Stock Available. Quote: <input type="text"/> RFQ
 LB11850VA-TLM-H Description: IC MOTOR CONTROLLER PAR 24SSOP Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 10000 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11861 Description: LB11861 ONS HSSOP-16 Manufacturers: ONS In Stock: New original, 200 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11697V-TLM-E Description: IC MOTOR CTRLR PAR/PWM SSOP30 Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 1000 pcs Stock Available. Quote: <input type="text"/> RFQ
 LB11861H-TLM-E Description: IC MOTOR DRIVER Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 8000 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11861M-TLM-E Description: LB11861M-TLM-E SANYO SOP10 Manufacturers: SANYO In Stock: New original, 5000 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11861M-TLM-H Description: LB11861M-TLM-H SANYO SOP10 Manufacturers: SANYO In Stock: New original, 900 pcs Stock Available. Quote: <input type="text"/> RFQ
 LB11813V-TLM-E Description: LB11813V-TLM-E SANYO TSSOP-24 Manufacturers: SANYO In Stock: New original, 3000 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11861M-TLM-E Description: LB11861M-TLM-E SANYO SOP-10 Manufacturers: SANYO In Stock: New original, 400 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11852FV-TLM-H Description: IC MOTOR CONTROLLER PAR 20SSOP Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 46000 pcs Stock Available. Quote: <input type="text"/> RFQ
 LB11862M-TE-L Description: LB11862M-TE-L SANYO SOP-10 Manufacturers: SANYO In Stock: New original, 9000 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11822 Description: LB11822 SANYO DIP-28 Manufacturers: SANYO In Stock: New original, 1500 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11861J-NMB-TLM3-E Description: LB11861J-NMB-TLM3-E SANYO SOP Manufacturers: SANYO In Stock: New original, 39000 pcs Stock Available. Quote: <input type="text"/> RFQ
 LB11861H-TLM-H Description: IC MOTOR DRIVER Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 1000 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11698H-TE-L Description: LB11698H-TE-L SANYO SOP Manufacturers: SANYO In Stock: New original, 1000 pcs Stock Available. Quote: <input type="text"/> RFQ	 LB11851M-TE-L-E Description: LB11851M-TE-L-E SANYO SOP Manufacturers: SANYO In Stock: New original, 700 pcs Stock Available. Quote: <input type="text"/> RFQ



IC Components Limited
WWW.IC-COMPONENTS.COM

Email: Info@IC-Components.com
TEL: 00 852 - 30501935
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong