



**X93154UM8I-3**

Manufacturer Part Number:	X93154UM8I-3
Manufacturer / Brand:	Intersil
Part of Description:	IC XDCP 32-TAP 50K 3-WIRE 8-MSOP
Datasheets:	X93154UM8I-3.pdf
Lead Free Status / RoHS Status:	Contains lead / RoHS non-compliant
Stock Condition:	New original, 1100 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

X93154UM8I-3 100% New Original 1100pcs in Stock, Find X93154UM8I-3 Price, Stock, datasheet at IC Components Ltd Online, buy X93154UM8I-3 Intersil with warrantied. 100% guarantee confidence. RFQ X93154UM8I-3: [Info@IC-Components.com](mailto:Info@IC-Components.com)































The specifications of X93154UM8I-3

Part Number	X93154UM8I-3	Manufacturer / Brand	Intersil
Series	XDCP™	Moisture Sensitivity Level (MSL)	1 (Unlimited)
Base Part Number	X93154	Package / Case	8-TSSOP, 8-MSOP (0.118", 3.00mm Width)
Packaging	Tube	Supplier Device Package	8-MSOP
Operating Temperature	-40°C ~ 85°C	Detailed Description	Digital Potentiometer 50k Ohm 1 Circuit 32 Taps Up/Down (U/D, INC, CS) Interface 8-MSOP
Features	-	Interface	Up/Down (U/D, INC, CS)
Configuration	Rheostat	Tolerance	±30%
Number of Circuits	1	Voltage - Supply	2.7 V ~ 3.3 V
Memory Type	Non-Volatile	Resistance (Ohms)	50k
Taper	Linear	Number of Taps	32
Temperature Coefficient (Typ)	±35 ppm/°C	Resistance - Wiper (Ohms) (Typ)	1000 (Max)
Stock Quantity	1100 pcs Stock	Category	Integrated Circuits (ICs) > Data Acquisition - Digital Potentiometers
Description	IC XDCP 32-TAP 50K 3-WIRE 8-MSOP	Lead Free Status / RoHS Status	Contains lead / RoHS non-compliant

Keywords related to X93154UM8I-3

Intersil X93154UM8I-3	X93154UM8I-3 part	X93154UM8I-3 Price	X93154UM8I-3 Distributor
X93154UM8I-3 Technical	X93154UM8I-3 Stock	X93154UM8I-3 Inventory	X93154UM8I-3 Supplier
X93154UM8I-3 Online Order	X93154UM8I-3 Inquiry	X93154UM8I-3 Image	X93154UM8I-3 Picture
X93154UM8I-3 pdf	X93154UM8I-3 datasheet	X93154UM8I-3 data sheet	X93154UM8I-3 pdf datasheet
Download X93154UM8I-3 datasheet	Intersil Manufacturer	Intersil X93154UM8I-3	

You May Be Also Be interested In:

 <p><b>X9314WSZT1</b> Description: IC POT DGTL SGL 10K OHM 8-SOIC Manufacturers: Intersil In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>X93154UU8IZ-3T1</b> Description: IC POT DGTL LP LN 50K OHM 8-TDFN Manufacturers: Intersil In Stock: New original, 1100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>X9314WPI</b> Description: IC XDCP SGL 32-TAP 10K 8-DIP Manufacturers: Intersil In Stock: New original, 1200 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p><b>X9315UP</b> Description: IC XDCP 32-TAP 50K 3WIRE 8-DIP Manufacturers: Intersil In Stock: New original, 2180 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>X9314WSZ</b> Description: IC XDCP SGL 32-TAP 10K 8-SOIC Manufacturers: Intersil In Stock: New original, 8800 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>X9314WSZ-3</b> Description: IC XDCP SGL 32-TAP 10K 8-SOIC Manufacturers: Intersil In Stock: New original, 200 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p><b>X9314WSI</b> Description: IC XDCP SGL 32-TAP 10K 8-SOIC Manufacturers: Intersil In Stock: New original, 200 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>X9314WP</b> Description: IC XDCP SGL 32-TAP 10K 8-DIP Manufacturers: Intersil In Stock: New original, 1900 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>X93155UM8IT1</b> Description: IC XDCP 32-TAP 50K 3-WIRE 8-MSOP Manufacturers: Intersil In Stock: New original, 5000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p><b>X9314WE</b> Description: X9314WE XICOR SOP8 Manufacturers: XICOR In Stock: New original, 800 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>X9314WS</b> Description: IC DIG POT 10K 32TP LOG TPR 8SO Manufacturers: Intersil In Stock: New original, 1100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>X9314W</b> Description: X9314W INTERSIL SOP8 Manufacturers: Intersil In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p><b>X9315UPI</b> Description: IC XDCP 32-TAP 50K 3WIRE 8-DIP Manufacturers: Intersil In Stock: New original, 4900 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>X93154UPD</b> Description: X93154UPD XICOR DIP-8 Manufacturers: XICOR In Stock: New original, 1600 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>X9314WMT6-TR</b> Description: X9314WMT6-TR XICOR MSOP-8 Manufacturers: XICOR In Stock: New original, 1000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p><b>X9315UMI-2.7T1</b> Description: IC XDCP 32-TAP 50K 3WIRE 8-MSOP Manufacturers: Intersil In Stock: New original, 6900 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>X9314WSIZ</b> Description: IC XDCP SGL 32-TAP 10K 8-SOIC Manufacturers: Intersil In Stock: New original, 7600 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>X9314WS8ZT1</b> Description: X9314WS8ZT1 INTERSIL SOP8 Manufacturers: Intersil In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p><b>X93154UM8IZ-3T1</b> Description: IC POT DGTL LP LN 50K OHM 8-MSOP Manufacturers: Intersil In Stock: New original, 1500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>X9315W</b> Description: X9315W XICOR SOP Manufacturers: XICOR In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>X9314WZ</b> Description: X9314WZ INTERSIL SOP8 Manufacturers: Intersil In Stock: New original, 200 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p><b>X9315UMIZ-2.7T1</b> Description: IC XDCP 32-TAP 50K 3WIRE 8-MSOP Manufacturers: Intersil In Stock: New original, 11500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>X93154UP</b> Description: X93154UP XICOR DIP-8 Manufacturers: XICOR In Stock: New original, 3000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>X9314WM-3T5</b> Description: X9314WM-3T5 Intersil 8MSOP Manufacturers: Intersil In Stock: New original, 5800 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p><b>X93154UM8IZ-3</b> Description: IC XDCP 32-TAP 50K 3-WIRE 8-MSOP Manufacturers: Intersil In Stock: New original, 1100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>X9313ZSZT1</b> Description: IC POT DGTL 1K OHM 8-SOIC Manufacturers: Intersil In Stock: New original, 2300 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>X93156UM8IZ-2.7</b> Description: IC XDCP 32-TAP 50K 3-WIRE 8-MSOP Manufacturers: Intersil In Stock: New original, 16500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p><b>X9315UM-2.7T1</b> Description: IC XDCP 32-TAP 50K 3WIRE 8-MSOP Manufacturers: Intersil In Stock: New original, 1700 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>X9315UF-2.7T1</b> Description: X9315UF-2.7T1 INTERSIL SOP8 Manufacturers: Intersil In Stock: New original, 200 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>X9315TSZ</b> Description: IC XDCP 32-TAP 100K 3WIRE 8-SOIC Manufacturers: Intersil In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>



**IC Components Limited**  
WWW.IC-COMPONENTS.COM

Email: [Info@IC-Components.com](mailto:Info@IC-Components.com)  
TEL: 00 852 - 30501935  
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong