



TISP4080M3BJR

Manufacturer Part Number:	TISP4080M3BJR
Manufacturer / Brand	Bourns, Inc.
Part of Description:	SURGE SUPP 65V BIDIR DO-214AA
Datasheets:	TISP4080M3BJR.pdf
Lead Free Status / RoHS Status:	Contains lead / RoHS non-compliant
Stock Condition:	New original, 2700 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

TISP4080M3BJR 100% New Original 2700pcs in Stock, Find TISP4080M3BJR Price, Stock, datasheet at IC Components Ltd Online, buy TISP4080M3BJR Bourns, Inc. with warrantied. 100% guarantee confidence. RFQ TISP4080M3BJR: Info@IC-Components.com

The specifications of TISP4080M3BJR

Part Number	TISP4080M3BJR	Manufacturer / Brand	Bourns, Inc.
Series	-	Moisture Sensitivity Level (MSL)	1 (Unlimited)
Package / Case	DO-214AA, SMB	Packaging	Tape & Reel (TR)
Mounting Type	Surface Mount	Capacitance	120pF
Current - Peak Pulse (10/1000µs)	50A	Voltage - Breakover	80V
Voltage - Off State	65V	Current - Peak Pulse (8/20µs)	220A
Current - Hold (Ih)	150mA	Number of Elements	1
Voltage - On State	3V	Stock Quantity	2700 pcs Stock
Category	Circuit Protection > TVS - Thyristors	Description	SURGE SUPP 65V BIDIR DO-214AA
Lead Free Status / RoHS Status	Contains lead / RoHS non-compliant		

Keywords related to TISP4080M3BJR

Bourns, Inc. TISP4080M3BJR	TISP4080M3BJR part	TISP4080M3BJR Price	TISP4080M3BJR Distributor
TISP4080M3BJR Technical	TISP4080M3BJR Stock	TISP4080M3BJR Inventory	TISP4080M3BJR Supplier
TISP4080M3BJR Online Order	TISP4080M3BJR Inquiry	TISP4080M3BJR Image	TISP4080M3BJR Picture
TISP4080M3BJR pdf	TISP4080M3BJR datasheet	TISP4080M3BJR data sheet	TISP4080M3BJR pdf datasheet
Download TISP4080M3BJR datasheet	Bourns, Inc. Manufacturer	Bourns, Inc. TISP4080M3BJR	Bourns Inc. TISP4080M3BJR
J.W. Miller / Bourns TISP4080M3BJR			

You May Be Also Be interested In:

<p>TISP4090M3AJR-S Description: TISP4090M3AJR-S BOURNS SMA(DO-214AC) Manufacturers: Bourns, Inc. In Stock: New original, 12000 pcs Stock Available. Quote: RFQ</p>	<p>TISP4095M3AJR-S Description: SINGLE BIDIRECTIONAL PROTECTOR Manufacturers: Bourns, Inc. In Stock: New original, 13100 pcs Stock Available. Quote: RFQ</p>	<p>TISP4072F3 Description: TISP4072F3 BOURNS SOP8 Manufacturers: Bourns, Inc. In Stock: New original, 100 pcs Stock Available. Quote: RFQ</p>
<p>TISP4115M3BJR-S Description: PROTECTOR SINGLE BIDIRECTIONAL Manufacturers: Bourns, Inc. In Stock: New original, 2800 pcs Stock Available. Quote: RFQ</p>	<p>TISP4080M3BJR-S Description: PROTECTOR SINGLE BIDIRECT 80V Manufacturers: Bourns, Inc. In Stock: New original, 3000 pcs Stock Available. Quote: RFQ</p>	<p>TISP4115J3BJR-S Description: THYRISTOR 90V 800A Manufacturers: Bourns, Inc. In Stock: New original, 800 pcs Stock Available. Quote: RFQ</p>
<p>TISP4070L3AJR-S Description: SINGLE BIDIRECTIONAL PROTECTOR Manufacturers: Bourns, Inc. In Stock: New original, 12000 pcs Stock Available. Quote: RFQ</p>	<p>TISP4070M3BJR-S Description: SURGE SUPP 58V 220A DO-214AA Manufacturers: Bourns, Inc. In Stock: New original, 3000 pcs Stock Available. Quote: RFQ</p>	<p>TISP4090L3AJR-S Description: PROTECTOR SINGLE BIDIRECTIONAL Manufacturers: Bourns, Inc. In Stock: New original, 12600 pcs Stock Available. Quote: RFQ</p>
<p>TISP4040L1AJR-S Description: PROTECTOR SINGLE BIDIRECTIONAL Manufacturers: Bourns, Inc. In Stock: New original, 13100 pcs Stock Available. Quote: RFQ</p>	<p>TISP4070H3BJR-S Description: SURGE SUPP 58V BIDIR DO-214AA Manufacturers: Bourns, Inc. In Stock: New original, 6800 pcs Stock Available. Quote: RFQ</p>	<p>TISP4125H3BJR-S Description: PROTECTOR SINGLE BIDIRECT 125V Manufacturers: Bourns, Inc. In Stock: New original, 2900 pcs Stock Available. Quote: RFQ</p>
<p>TISP4070J1B Description: TISP4070J1B TI DO-214B Manufacturers: TI In Stock: New original, 1500 pcs Stock Available. Quote: RFQ</p>	<p>TISP4125F3DR Description: THYRISTOR TISP4125F3DR BOURNS SOP8 Manufacturers: Bourns, Inc. In Stock: New original, 12500 pcs Stock Available. Quote: RFQ</p>	<p>TISP4115M3AJR-S Description: THYRISTOR 90V 220A Manufacturers: Bourns, Inc. In Stock: New original, 12600 pcs Stock Available. Quote: RFQ</p>
<p>TISP4115J1BJR-S Description: SINGLE BIDIRECTIONAL PROTECTOR Manufacturers: Bourns, Inc. In Stock: New original, 9000 pcs Stock Available. Quote: RFQ</p>	<p>TISP4082F3S Description: SURGE SUPP TISP4082F3S TI SIP2 Manufacturers: TI In Stock: New original, 100 pcs Stock Available. Quote: RFQ</p>	<p>TISP4070H3BJR Description: PROTECTOR SINGLE BIDIRECTIONAL Manufacturers: Bourns, Inc. In Stock: New original, 2200 pcs Stock Available. Quote: RFQ</p>
<p>TISP4095H3BJR Description: SURGE SUPP 75V BIDIR DO-214AA Manufacturers: Bourns, Inc. In Stock: New original, 3400 pcs Stock Available. Quote: RFQ</p>	<p>TISP4080H3BJR-S Description: PROTECTOR SINGLE BIDIRECT 80V Manufacturers: Bourns, Inc. In Stock: New original, 3000 pcs Stock Available. Quote: RFQ</p>	<p>TISP4072F3DR Description: TISP4072F3DR BOURNS SOP-8 Manufacturers: Bourns, Inc. In Stock: New original, 2500 pcs Stock Available. Quote: RFQ</p>
<p>TISP4125L3AJR Description: TISP4125L3AJR BOURNS SMA Manufacturers: Bourns, Inc. In Stock: New original, 5000 pcs Stock Available. Quote: RFQ</p>	<p>TISP4072F3DR-S Description: PROTECTOR SINGLE BIDIRECTIONAL Manufacturers: Bourns, Inc. In Stock: New original, 9000 pcs Stock Available. Quote: RFQ</p>	<p>TISP4095H3BJR-S Description: PROTECTOR SINGLE BIDIRECT 95V Manufacturers: Bourns, Inc. In Stock: New original, 3000 pcs Stock Available. Quote: RFQ</p>
<p>TISP4070M3AJR-S Description: SINGLE BIDIRECTIONAL PROTECTOR Manufacturers: Bourns, Inc. In Stock: New original, 12600 pcs Stock Available. Quote: RFQ</p>	<p>TISP4070J3BJR-STR-N Description: TISP4070J3BJR-STR-N BOURNS SMB Manufacturers: Bourns, Inc. In Stock: New original, 2500 pcs Stock Available. Quote: RFQ</p>	<p>TISP4040L1BJR-S Description: PROTECTOR SINGLE BIDIRECT 40V Manufacturers: Bourns, Inc. In Stock: New original, 1800 pcs Stock Available. Quote: RFQ</p>
<p>TISP4125F3D Description: TISP4125F3D POWER SOP-8 Manufacturers: POWER In Stock: New original, 2200 pcs Stock Available. Quote: RFQ</p>	<p>TISP4070J3BJR-S Description: THYRISTOR 58V 800A DO-214AA Manufacturers: Bourns, Inc. In Stock: New original, 3000 pcs Stock Available. Quote: RFQ</p>	<p>TISP4080J3BJR-S Description: PROTECTOR SINGLE BIDIRECTIONAL Manufacturers: Bourns, Inc. In Stock: New original, 3000 pcs Stock Available. Quote: RFQ</p>



IC Components Limited
WWW.IC-COMPONENTS.COM

Email: Info@IC-Components.com
TEL: 00 852 - 30501935
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong