



**AD9515BCPZ-REEL7**

Manufacturer Part Number:	AD9515BCPZ-REEL7
Manufacturer / Brand	ADI (Analog Devices, Inc.)
Part of Description:	IC CLK BUFFER 1:2 1.6GHZ 32LFCSP
Datasheets:	AD9515BCPZ-REEL7.pdf
Lead Free Status / RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	New original, 1300 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

AD9515BCPZ-REEL7 100% New Original 1300pcs in Stock, Find AD9515BCPZ-REEL7 Price, Stock, datasheet at IC Components Ltd Online, buy AD9515BCPZ-REEL7 ADI (Analog Devices, Inc.) with warrantied. 100% guarantee confidence. RFQ AD9515BCPZ-REEL7: [Info@IC-Components.com](mailto:Info@IC-Components.com)































The specifications of AD9515BCPZ-REEL7

Part Number	AD9515BCPZ-REEL7	Manufacturer / Brand	ADI (Analog Devices, Inc.)
Series	-	Moisture Sensitivity Level (MSL)	3 (168 Hours)
Base Part Number	AD9515	Package / Case	32-VFQFN Exposed Pad, CSP
Packaging	Original-Reel®	Mounting Type	Surface Mount
Supplier Device Package	32-LFCSP-VQ (5x5)	Operating Temperature	-40°C ~ 85°C
Detailed Description	Clock Fanout Buffer (Distribution), Divider IC 1:2 1.6GHz 32-VFQFN Exposed Pad, CSP	Type	Fanout Buffer (Distribution), Divider
Frequency - Max	1.6GHz	Number of Circuits	1
Voltage - Supply	3.135 V ~ 3.465 V	Output	CMOS, LVDS, LVPECL
Input	Clock	Ratio - Input:Output	1:2
Differential - Input:Output	Yes/Yes	Other Names	AD9515BCPZ-REEL7DKR
Stock Quantity	1300 pcs Stock	Category	<a href="#">Integrated Circuits (ICs) &gt; Clock/Timing - Clock Buffers, Drivers</a>
Description	IC CLK BUFFER 1:2 1.6GHZ 32LFCSP	Lead Free Status / RoHS Status	Lead free / RoHS Compliant

Keywords related to AD9515BCPZ-REEL7

<a href="#">ADI (Analog Devices, Inc.) AD9515BCPZ-REEL7</a>	<a href="#">AD9515BCPZ-REEL7 part</a>	<a href="#">AD9515BCPZ-REEL7 Price</a>	<a href="#">AD9515BCPZ-REEL7 Distributor</a>
<a href="#">AD9515BCPZ-REEL7 Technical</a>	<a href="#">AD9515BCPZ-REEL7 Stock</a>	<a href="#">AD9515BCPZ-REEL7 Inventory</a>	<a href="#">AD9515BCPZ-REEL7 Supplier</a>
<a href="#">AD9515BCPZ-REEL7 Online Order</a>	<a href="#">AD9515BCPZ-REEL7 Inquiry</a>	<a href="#">AD9515BCPZ-REEL7 Image</a>	<a href="#">AD9515BCPZ-REEL7 Picture</a>
<a href="#">AD9515BCPZ-REEL7 pdf</a>	<a href="#">AD9515BCPZ-REEL7 datasheet</a>	<a href="#">AD9515BCPZ-REEL7 data sheet</a>	<a href="#">AD9515BCPZ-REEL7 pdf datasheet</a>
<a href="#">Download AD9515BCPZ-REEL7 datasheet</a>	<a href="#">ADI (Analog Devices, Inc.) Manufacturer</a>	<a href="#">ADI (Analog Devices, Inc.) AD9515BCPZ-REEL7</a>	<a href="#">AD AD9515BCPZ-REEL7</a>
<a href="#">ADI (Analog Devices, Inc.) AD9515BCPZ-REEL7</a>	<a href="#">Analog Devices Inc. AD9515BCPZ-REEL7</a>	<a href="#">Analog Devices, Inc. AD9515BCPZ-REEL7</a>	

You May Be Also Be interested In:

 <p><b>AD9518-2ABCPZ</b> Description: IC CLOCK GEN 6CH 2.2GHZ 48LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>AD9516-2BCPZ</b> Description: IC CLOCK PLL/VCO 2.2GHZ 64LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>AD9516-1BCPZ-REEL7</b> Description: IC CLOCK GEN 2.5GHZ VCO 64-LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 200 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p><b>AD9516-1BCPZ</b> Description: IC CLOCK GEN 2.5GHZ VCO 64-LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 2500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>AD9501JN</b> Description: AD9501JN AD DIP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 6300 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>AD9511BCPZ</b> Description: IC CLK BUFFER 2:5 1.2GHZ 48LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p><b>AD9501JP</b> Description: AD9501JP AD PLCC Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 1100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>AD9512BCPZ-REEL7</b> Description: IC CLK BUFFER 2:5 1.2GHZ 48LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 4700 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>AD9517-4ABCPZ-RL7</b> Description: IC CLOCK GEN 1.8GHZ VCO 48LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p><b>AD9516-0BCPZ</b> Description: IC CLOCK GEN 2.8GHZ VCO 64-LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 2500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>AD9515BCPZ</b> Description: IC CLK BUFFER 1:2 1.6GHZ 32LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 4700 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>AD9514BCPZ-REEL7</b> Description: IC CLK BUFFER 1:3 1.6GHZ 32LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 200 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p><b>AD9518-0ABCPZ</b> Description: IC CLOCK GEN 6CH 2.8GHZ 48LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>AD9517-2ABCPZ</b> Description: IC CLOCK GEN 2.2GHZ VCO 48LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>AD9518-1BCPZ</b> Description: AD9518-1BCPZ AD NA Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p><b>AD9510BCPZ</b> Description: IC CLK BUFFER 2:8 1.2GHZ 64LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 600 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>AD9514BCPZ</b> Description: IC CLK BUFFER 1:3 1.6GHZ 32LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>AD9513BCPZ</b> Description: IC CLK BUFFER 1:3 800MHZ 32LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 3400 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p><b>AD9518-3ABCPZ</b> Description: IC CLOCK GEN 6CH 2GHZ 48LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 1000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>AD9512BCPZ</b> Description: IC CLK BUFFER 2:5 1.2GHZ 48LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 400 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>AD9518-1ABCPZ</b> Description: IC CLOCK GEN 6CH 2.65GHZ 48LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 800 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p><b>AD9501</b> Description: AD9501 AD DIP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>AD9510BCPZ-REEL7</b> Description: IC CLK BUFFER 2:8 1.2GHZ 64LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 300 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>AD9516-4BCPZ</b> Description: IC CLOCK GEN 1.6GHZ VCO 64-LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 900 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p><b>AD9518-2ABCPZ-RL7</b> Description: IC CLOCK GEN 6CH 2.2GHZ 48LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 800 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>AD9502CM</b> Description: AD9502CM AD DIP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>AD9516-3BCPZ-REEL7</b> Description: IC CLOCK PLL/VCO 2GHZ 64LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 800 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p><b>AD9508BCPZ-REEL7</b> Description: IC CLK BUFF 1:4 1.65GHZ 24LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 2000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>AD9516-3BCPZ</b> Description: IC CLOCK PLL/VCO 2GHZ 64LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 2500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p><b>AD9511BCPZ-REEL7</b> Description: IC CLK BUFFER 2:5 1.2GHZ 48LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 1000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>



**IC Components Limited**  
WWW.IC-COMPONENTS.COM

Email: [Info@IC-Components.com](mailto:Info@IC-Components.com)  
TEL: 00 852 - 30501935  
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong