



TISPA79R241DR-S

Manufacturer Part Number:	TISPA79R241DR-S
Manufacturer / Brand	BOURNS
Part of Description:	TISPA79R241DR-S BOURNS SOP8
Datasheets:	
Lead Free Status / RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	New original, 2500 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

TISPA79R241DR-S 100% New Original 2500pcs in Stock, Find TISPA79R241DR-S Price, Stock, datasheet at IC Components Ltd Online, buy TISPA79R241DR-S Bourns, Inc. with warrantied. 100% guarantee confidence. RFQ TISPA79R241DR-S: Info@IC-Components.com

The specifications of TISPA79R241DR-S

Part Number	TISPA79R241DR-S	Manufacturer / Brand	BOURNS
Package	SOP8	Condition	New Original Stock
Warranty	100% Perfect Functions	Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union	Shipping by	DHL / Fedex / UPS
Port	HongKong	RFQ Email	Info@ic-components.com
Stock Quantity	2500 pcs Stock	Category	Integrated Circuits (ICs) > Specialized ICs
Description	TISPA79R241DR-S BOURNS SOP8	Lead Free Status / RoHS Status	Lead free / RoHS Compliant

Keywords related to TISPA79R241DR-S

Bourns, Inc. TISPA79R241DR-S	TISPA79R241DR-S part	TISPA79R241DR-S Price	TISPA79R241DR-S Distributor
TISPA79R241DR-S Technical	TISPA79R241DR-S Stock	TISPA79R241DR-S Inventory	TISPA79R241DR-S Supplier
TISPA79R241DR-S Online Order	TISPA79R241DR-S Inquiry	TISPA79R241DR-S Image	TISPA79R241DR-S Picture
TISPA79R241DR-S pdf	TISPA79R241DR-S datasheet	TISPA79R241DR-S data sheet	TISPA79R241DR-S pdf datasheet
Download TISPA79R241DR-S datasheet	Bourns, Inc. Manufacturer	Bourns, Inc. TISPA79R241DR-S	Bourns Inc. TISPA79R241DR-S
J.W. Miller / Bourns TISPA79R241DR-S			

You May Be Also Be interested In:

<p>TISP8201DMR-S Description: TISP8201DMR-S BOURNS SOP8 Manufacturers: Bourns, Inc. In Stock: New original, 2100 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p>TISPPBL2P Description: TISPPBL2P BOURNS DIP-4 Manufacturers: Bourns, Inc. In Stock: New original, 3200 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p> <p>TISP83121 Description: TISP83121 BBOURNS SOP8 Manufacturers: BBOURNS In Stock: New original, 5400 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>
<p>IMAGE NOT AVAILABLE</p> <p>TISPPBL2DR Description: TISPPBL2DR TI SOP-8 Manufacturers: TI In Stock: New original, 24700 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p> <p>TISP8201M Description: TISP8201M BBOURNS SOP8 Manufacturers: BBOURNS In Stock: New original, 1900 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p>TISP8201MD-S Description: TISP8201MD-S BOURNS SOP8 Manufacturers: Bourns, Inc. In Stock: New original, 500 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>
<p>IMAGE NOT AVAILABLE</p> <p>TISPPBL2SDR Description: TISPPBL2SDR TI SOP-8 Manufacturers: TI In Stock: New original, 4800 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p>TISPBLS Description: TISPBLS BOURNS SOP8 Manufacturers: Bourns, Inc. In Stock: New original, 200 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p>TISPPBL2SE Description: TISPPBL2SE BOURNS DIP-4 Manufacturers: Bourns, Inc. In Stock: New original, 2200 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>
<p>TISP8210MDR-S Description: SURGE PROT THYRIST NEG V SLIC Manufacturers: Bourns, Inc. In Stock: New original, 20000 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p> <p>TISP8250 Description: TISP8250 BBOURNS SOP8 Manufacturers: BBOURNS In Stock: New original, 100 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p> <p>TISP9110L Description: TISP9110L T SMD8 Manufacturers: T In Stock: New original, 3400 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>
<p>IMAGE NOT AVAILABLE</p> <p>TISPPBL1P Description: TISPPBL1P POWER DIP-8 Manufacturers: POWER In Stock: New original, 3200 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p>TISP83121DR-S Description: PROTECTOR OVER VOLTAGE 100V Manufacturers: Bourns, Inc. In Stock: New original, 77500 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p> <p>TISPA79R241DR Description: TISPA79R241DR TI SOP8 Manufacturers: TI In Stock: New original, 7500 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>
<p>TISP83121DR Description: TISP83121DR BOURNS SOP8 Manufacturers: Bourns, Inc. In Stock: New original, 9800 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p>TISP8210MDR-5 Description: TISP8210MDR-5 BOURNS SOP-8 Manufacturers: Bourns, Inc. In Stock: New original, 2500 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p>TISPL758LF3DR Description: TISPL758LF3DR BOURNS SOP8 Manufacturers: Bourns, Inc. In Stock: New original, 2200 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>
<p>TISP8200MDR Description: TISP8200MDR BOURNS SOP-8 Manufacturers: Bourns, Inc. In Stock: New original, 3200 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p>TISP8201MDR Description: TISP8201MDR BOURNS SOP8 Manufacturers: Bourns, Inc. In Stock: New original, 2500 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p>TISP8250DR-S Description: THYRISTOR 250V 30A Manufacturers: Bourns, Inc. In Stock: New original, 5000 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>
<p>TISP8201MDR-S Description: THYRISTOR 120V 45A 8SOIC Manufacturers: Bourns, Inc. In Stock: New original, 37500 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p> <p>TISPL758LF3D Description: TISPL758LF3D POWER SOP8L Manufacturers: POWER In Stock: New original, 600 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p>TISP8201HDMR-S Description: SLIC PROTECTOR 100 AMP Manufacturers: Bourns, Inc. In Stock: New original, 1500 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>
<p>TISP8211MDR Description: TISP8211MDR BOURNS SOP8 Manufacturers: Bourns, Inc. In Stock: New original, 37500 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p>TISP8200MDR-S Description: THYRISTOR 120V 45A 8SOIC Manufacturers: Bourns, Inc. In Stock: New original, 2000 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p>TISP9110MSDMR-S Description: TISP9110MSDMR-S BOURNS SOP8 Manufacturers: Bourns, Inc. In Stock: New original, 1500 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>
<p>IMAGE NOT AVAILABLE</p> <p>TISPPBL1DR Description: TISPPBL1DR POWER SOP8 Manufacturers: POWER In Stock: New original, 3500 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p>TISP9110LDMR-S Description: SURGE PROT THYRIST NEG/POS SLIC Manufacturers: Bourns, Inc. In Stock: New original, 30000 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p>TISP8211MDR-S Description: SURGE PROT THYRIST POS V SLIC Manufacturers: Bourns, Inc. In Stock: New original, 27500 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>



IC Components Limited
WWW.IC-COMPONENTS.COM

Email: Info@IC-Components.com

TEL: 00 852 - 30501935

FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong