GET A QUOTE



IMAGE NOT AVAILABLE

CDCV304PWRG4

Ship From:

Shipment Way:

Manufacturer Part Number: Manufacturer / Brand Part of Description: Datasheets: Lead Free Status / RoHS Status: Stock Condition:

CDCV304PWRG4 N/A

IC CLK BUFFER 1:4 200MHZ 8TSSOP

🕟 🏒 Lead free / RoHS Compliant New original, 13000 pcs Stock Available.

Hong Kong DHL/Fedex/TNT/UPS

CDCV304PWRG4 100% New Original 13000pcs in Stock, Find CDCV304PWRG4 Price, Stock, datasheet at IC Components Ltd Online, buy CDCV304PWRG4 with warrantied. 100% guarantee confidence. RFQ CDCV304PWRG4: Info@IC-Components.com

The specifications of CDCV304PWRG4

Part Number	CDCV304PWRG4	Manufacturer / Brand	N/A
Voltage - Supply	2.3 V ~ 3.6 V	Туре	Fanout Buffer (Distribution)
Supplier Device Package	8-TSSOP	Series	-
Ratio - Input:Output	1:4	Packaging	Cut Tape (CT)
Package / Case	8-TSSOP (0.173", 4.40mm Width)	Output	LVTTL
Other Names	296-35899-1	Operating Temperature	-40°C ∼ 85°C
Number of Circuits	1	Mounting Type	Surface Mount
Moisture Sensitivity Level (MSL)	1 (Unlimited)	Input	LVTTL
Frequency - Max	200MHz	Differential - Input:Output	No/No
Detailed Description	Clock Fanout Buffer (Distribution) IC 1:4 200MHz 8-TSSOP (0.173", 4.40n Width)	nm Base Part Number	CDCV304
Stock Quantity	13000 pcs Stock	Category	Integrated Circuits (ICs) > Clock/Timing - Clock Buffers, Drivers
Description	IC CLK BUFFER 1:4 200MHZ 8TSSOP	Lead Free Status / RoHS Status	Lead free / RoHS Compliant

Keywords realted to CDCV304PWRG4

CDCV304PWRG4	CDCV304PWRG4 part	CDCV304PWRG4 Price	CDCV304PWRG4 Distributor
CDCV304PWRG4 Technical	CDCV304PWRG4 Stock	CDCV304PWRG4 Inventory	CDCV304PWRG4 Supplier
CDCV304PWRG4 Online Order	CDCV304PWRG4 Inquiry	CDCV304PWRG4 Image	CDCV304PWRG4 Picture
CDCV304PWRG4 pdf	CDCV304PWRG4 datasheet	CDCV304PWRG4 data sheet	CDCV304PWRG4 pdf datasheet
Download CDCV304PWRG4 datasheet	Manufacturer		

You May Be Also Be interested In:



IMAGE NOT

AVAILABLE

Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A

CDCV855PW

Manufacturers: N/A

CDCU877GQLT

RFQ Quote:

In Stock: New original, 2746 pcs Stock Available.

Description: IC 1:4 DDR PLL CLK-DRVR 28-TSSOP

In Stock: New original, 2784 pcs Stock Available.

Quote:

RFQ

IMAGE NOT AVAILABLE

IMAGE NOT

AVAILABLE

IMAGE NOT

AVAILABLE

Manufacturers: N/A In Stock: New original, 2800 pcs Stock Available.

CDCV304PWG4

Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP

Quote:

RFQ

CDCV857ADGGR Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP

Manufacturers: N/A

In Stock: New original, 18800 pcs Stock Available. Quote: RFQ

CDCU877RHAR

Description: IC PLL CLOCK DRIVER 1.8V 40VQFN Manufacturers: N/A

In Stock: New original, 2735 pcs Stock Available.

Quote:

IMAGE NOT AVAILABLE

IMAGE NOT

AVAILABLE

IMAGE NOT

AVAILABLE

CDCUN1208LPRHBT

Manufacturers: N/A In Stock: New original, 2792 pcs Stock Available.

CDCU877AZQLT

Manufacturers: N/A

CDCV850DGGR

Manufacturers: N/A

Description: IC PLL CLOCK DRIVER 1.8V 52-BGA

In Stock: New original, 2645 pcs Stock Available.

Description: IC CLK BUFFER 2:8 400MHZ 32QFN

Description: IC PLL CLOCK DRVR 2.5V 48-TSSOP

In Stock: New original, 2855 pcs Stock Available.

Quote:

Quote:

Quote:

RFQ

RFQ

RFQ

IMAGE NOT AVAILABLE

IMAGE NOT

AVAILABLE

In Stock: New original, 5000 pcs Stock Available.

CDCU877ZQLR

Manufacturers: N/A

CDCV304PWR-TR

Manufacturers: □

Description: TI TSSOP-8

Quote: RFQ

Description: IC PLL CLOCK DRIVER 1.8V 52-BGA

In Stock: New original, 6000 pcs Stock Available.

Quote:

CDCV857 IMAGE NOT Description: CDCV857 TI TSSOP48 **AVAILABLE**

IMAGE NOT

AVAILABLE

Manufacturers: TI

In Stock: New original, 2690 pcs Stock Available. Quote:

Manufacturers: N/A In Stock: New original, 6600 pcs Stock Available.

Quote:

Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP

RFQ

RFQ

RFQ

IMAGE NOT AVAILABLE

CDCV304TPWREP

Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 2690 pcs Stock Available. Quote: RFQ

IMAGE NOT AVAILABLE

Manufacturers: N/A **In Stock:** New original, 2876 pcs Stock Available.

CDCUA877ZQLR

CDCV857AGQLR

RFQ Quote:

Description: IC CLK-DRVR PLL 2.5V 56-BGA

Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 17000 pcs Stock Available.

Quote: RFQ

Manufacturers: TI

CDCV304PW

In Stock: New original, 2690 pcs Stock Available.

Description: CDCV855-13CT TI TSSOP

RFQ Quote:

IMAGE NOT

AVAILABLE

IMAGE NOT

AVAILABLE

Manufacturers: N/A In Stock: New original, 2816 pcs Stock Available.

CDCV857ADGGRG4

RFQ Quote:

Description: IC PLL CLOCK DRIVER 1.8V 52-BGA

Description: IC SSTL-II PLL CLK-DRVR 48TSSOP

IMAGE NOT AVAILABLE

IMAGE NOT

AVAILABLE

In Stock: New original, 2823 pcs Stock Available.

CDCU877RHAT

Description: IC PLL CLOCK DRIVER 1.8V 40VQFN

Quote:

RFQ

IMAGE NOT

AVAILABLE

IMAGE NOT

AVAILABLE

Manufacturers: N/A

CDCV855-13CT

CDCU877GQLR

Description: IC PLL CLOCK DRIVER 1.8V 52-BGA

In Stock: New original, 2749 pcs Stock Available.

Quote:

Quote:

RFQ

In Stock: New original, 2858 pcs Stock Available.

CDCUA877ZQLT

Manufacturers: N/A

Quote: RFQ



Manufacturers: N/A

CDCV850IDGGR **Description:** TI TSSOP

Manufacturers: TI

In Stock: New original, 2669 pcs Stock Available.

Quote: RFQ

IMAGE NOT

AVAILABLE

CDCV855IPWR

Description: IC PLL CLOCK DRVR 2.5V 28TSSOP

Manufacturers: N/A In Stock: New original, 2772 pcs Stock Available.

IMAGE NOT

AVAILABLE

IMAGE NOT

AVAILABLE

In Stock: New original, 2821 pcs Stock Available.

CDCV857ADGG

Manufacturers: N/A

Manufacturers: N/A

CDCV855PWR

RFQ Quote:

Description: IC 1:4 DDR PLL CLK-DRVR 28-TSSOP

Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP In Stock: New original, 2606 pcs Stock Available.

RFQ

RFQ

RFQ

Quote:

Quote:

Quote:



CDCU877ZQLT **Description:** IC PLL CLOCK DRIVER 1.8V 52-BGA

Manufacturers: N/A In Stock: New original, 2805 pcs Stock Available.

RFQ Quote:

IMAGE NOT

AVAILABLE

IMAGE NOT

AVAILABLE

Manufacturers: N/A

CDCV850DGGRG4

In Stock: New original, 2650 pcs Stock Available.

Description: IC PLL CLOCK DRVR 2.5V 48TSSOP

RFQ Quote:



IMAGE NOT

AVAILABLE

IMAGE NOT

AVAILABLE

CDCV855PWRG4

Description: IC PLL CLOCK DRVR 2.5V 28TSSOP Manufacturers: N/A

In Stock: New original, 2640 pcs Stock Available.

Description: CDCV855 TI TSSOP28

IMAGE NOT AVAILABLE

Description: CDCV304 TEXAS TSP08

CDCV304

Manufacturers: TEXAS In Stock: New original, 2736 pcs Stock Available.

Quote: RFQ

Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP Manufacturers: N/A

CDCV304PWR

In Stock: New original, 56000 pcs Stock Available.

RFQ Quote:

Manufacturers: ∏

In Stock: New original, 2819 pcs Stock Available.

CDCV855



Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong

IC Components Ltd is Distributor of IC and Capacitors Electronic Components @ 2018 IC-Components.com All right Reserved.