



**TP-103-PIN**

Manufacturer Part Number:	TP-103-PIN
Manufacturer / Brand:	Aeroflex (MACOM Technology Solutions)
Part of Description:	BALUN 500KHZ-1GHZ 50/200 6FLTPAK
Datasheets:	<a href="#">TP-103-PIN.pdf</a>
Lead Free Status / RoHS Status:	Contains lead / RoHS non-compliant
Stock Condition:	New original, 100 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

TP-103-PIN 100% New Original 100pcs in Stock, Find TP-103-PIN Price, Stock, datasheet at IC Components Ltd Online, buy TP-103-PIN Aeroflex (MACOM Technology Solutions) with warranted. 100% guarantee confidence. RFQ TP-103-PIN: [Info@IC-Components.com](mailto:Info@IC-Components.com)

The specifications of TP-103-PIN

Part Number	TP-103-PIN	Manufacturer / Brand	Aeroflex (MACOM Technology Solutions)
Series	-	Moisture Sensitivity Level (MSL)	1 (Unlimited)
Package / Case	6-FlatPack	Packaging	Bulk
Mounting Type	Surface Mount	Detailed Description	RF Balun 500kHz ~ 1GHz 50 / 200 Ohm 6-FlatPack
Frequency Range	500kHz ~ 1GHz	Impedance - Unbalanced/Balanced	50 / 200 Ohm
Phase Difference	-	Insertion Loss (Max)	0.6dB
Return Loss (Min)	-	Other Names	1465-1122
Stock Quantity	100 pcs Stock	Category	RF/IF and RFID > Balun
Description	BALUN 500KHZ-1GHZ 50/200 6FLTPAK	Lead Free Status / RoHS Status	Contains lead / RoHS non-compliant

Keywords related to TP-103-PIN

<a href="#">Aeroflex (MACOM Technology Solutions) TP-103-PIN</a>	<a href="#">TP-103-PIN part</a>	<a href="#">TP-103-PIN Price</a>	<a href="#">TP-103-PIN Distributor</a>
<a href="#">TP-103-PIN Technical</a>	<a href="#">TP-103-PIN Stock</a>	<a href="#">TP-103-PIN Inventory</a>	<a href="#">TP-103-PIN Supplier</a>
<a href="#">TP-103-PIN Online Order</a>	<a href="#">TP-103-PIN Inquiry</a>	<a href="#">TP-103-PIN Image</a>	<a href="#">TP-103-PIN Picture</a>
<a href="#">TP-103-PIN pdf</a>	<a href="#">TP-103-PIN datasheet</a>	<a href="#">TP-103-PIN data sheet</a>	<a href="#">TP-103-PIN pdf datasheet</a>
<a href="#">Download TP-103-PIN datasheet</a>	<a href="#">Aeroflex (MACOM Technology Solutions) Manufacturer</a>	<a href="#">Aeroflex (MACOM Technology Solutions) TP-103-PIN</a>	<a href="#">Aeroflex Circuit Technology TP-103-PIN</a>
<a href="#">Aeroflex TP-103-PIN</a>	<a href="#">Aeroflex (MACOM Technology Solutions) TP-103-PIN</a>	<a href="#">Aeroflex Metelics, Division of MACOM TP-103-PIN</a>	<a href="#">M/A-Com Technology Solutions TP-103-PIN</a>
<a href="#">Metelics (MACOM Technology Solutions) TP-103-PIN</a>	<a href="#">MACOM Technology Solutions TP-103-PIN</a>		

You May Be Also Be interested In:

<p><b>DXP18BN5014TL</b> Description: BALUN 50MHZ-870MHZ 50/200 0603 Manufacturers: Murata Electronics In Stock: New original, 32000 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>HHM1726P1</b> Description: BALUN 880MHZ-960MHZ 50/100 0603 Manufacturers: TDK Corporation In Stock: New original, 9900 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>HHM1907B1</b> Description: BALUN 4.9GHZ-5.95GHZ 50/50 0402 Manufacturers: TDK Corporation In Stock: New original, 89000 pcs Stock Available. Quote: <a href="#">RFQ</a></p>
<p><b>ATB2012-50011-T000</b> Description: BALUN 40MHZ-860MHZ 50/50 0805 Manufacturers: TDK Corporation In Stock: New original, 74000 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>B4859A53</b> Description: BALUN 4.8GHZ-5.9GHZ 50/100 0603 Manufacturers: Anaren In Stock: New original, 3800 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>B0430J50100AHF</b> Description: BALUN 400MHZ-3000MHZ 50/100 0805 Manufacturers: Anaren In Stock: New original, 1400 pcs Stock Available. Quote: <a href="#">RFQ</a></p>
<p><b>LDB182G4510C-110</b> Description: BALUN 2.4GHZ-2.5GHZ 50/100 0603 Manufacturers: Murata Electronics In Stock: New original, 28000 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>RFBLN2012090BM5T25</b> Description: BALUN 800MHZ-1.9GHZ 50/200 10SMD Manufacturers: Walsin Technology In Stock: New original, 15300 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>LDB212G4020C-001</b> Description: BALUN 2.3GHZ-2.5GHZ 50/200 0805 Manufacturers: Murata Electronics In Stock: New original, 4000 pcs Stock Available. Quote: <a href="#">RFQ</a></p>
<p><b>2450BL15B100E</b> Description: BALUN 2.4GHZ-2.5GHZ 50/100 0805 Manufacturers: Johanson Technology In Stock: New original, 13000 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>HHM1515B2</b> Description: BALUN 880MHZ-960MHZ 50/200 0805 Manufacturers: TDK Corporation In Stock: New original, 2000 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>2595FB39A0050E</b> Description: BALUN DUAL 50/50 1008 6 PC PAD Manufacturers: Johanson Technology In Stock: New original, 13500 pcs Stock Available. Quote: <a href="#">RFQ</a></p>
<p><b>HHM1523B3</b> Description: BALUN 824MHZ-894MHZ 50/100 0805 Manufacturers: TDK Corporation In Stock: New original, 4000 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>RFBLN2012090A1T</b> Description: BALUN 2.4GHZ-2.5GHZ 50/100 6SMD Manufacturers: Walsin Technology In Stock: New original, 106000 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>HHM1525</b> Description: BALUN 1.71GHZ-1.99GHZ 50/50 0805 Manufacturers: TDK Corporation In Stock: New original, 92300 pcs Stock Available. Quote: <a href="#">RFQ</a></p>
<p><b>CX2045LNLTT</b> Description: BALUN 3MHZ-300MHZ 5SMD Manufacturers: Pulse Electronics Corporation In Stock: New original, 100 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p>IMAGE NOT AVAILABLE</p> <p><b>TP-107-02-1-T</b> Description: TP-107-02-1-T COMPONE SMT Manufacturers: COMPONE In Stock: New original, 1000 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>2450FB15L0001E</b> Description: BALUN DUAL 50/50 1008 6 PC PAD Manufacturers: Johanson Technology In Stock: New original, 13400 pcs Stock Available. Quote: <a href="#">RFQ</a></p>
<p><b>MABA-009594-CF18A0</b> Description: BALUN 3MHZ-300MHZ 5SMD Manufacturers: Aeroflex (MACOM Technology Solutions) In Stock: New original, 4500 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>LFB182G45BG2D280</b> Description: BALUN 2.4GHZ-2.5GHZ 6SMD Manufacturers: Murata Electronics In Stock: New original, 12800 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>LDB212G4005C-001</b> Description: BALUN 2.3GHZ-2.5GHZ 50/50 0805 Manufacturers: Murata Electronics In Stock: New original, 52000 pcs Stock Available. Quote: <a href="#">RFQ</a></p>
<p><b>HHM1521</b> Description: BALUN 2.4GHZ-2.5GHZ 50/200 0805 Manufacturers: TDK Corporation In Stock: New original, 21500 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>HHM1562B</b> Description: BALUN 5.15-5.875GHZ 50/100 0805 Manufacturers: TDK Corporation In Stock: New original, 9900 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>BD0810J50200AHF</b> Description: BALUN 800MHZ-1GHZ 50/200 0805 Manufacturers: Anaren In Stock: New original, 100 pcs Stock Available. Quote: <a href="#">RFQ</a></p>
<p><b>2500BL14M100T</b> Description: BALUN 2.3GHZ-2.7GHZ 50/100 0603 Manufacturers: Johanson Technology In Stock: New original, 11000 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>3700BL15B100E</b> Description: BALUN 3.4GHZ-4GHZ 50/100 0805 Manufacturers: Johanson Technology In Stock: New original, 3200 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>F1212C245033-T</b> Description: BALUN 2.4GHZ-2.5GHZ 0805 Manufacturers: Taiyo Yuden In Stock: New original, 2700 pcs Stock Available. Quote: <a href="#">RFQ</a></p>
<p><b>LDB182G4520C-110</b> Description: BALUN 2.4GHZ-2.5GHZ 50/200 0603 Manufacturers: Murata Electronics In Stock: New original, 100100 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>HHM1902B1</b> Description: BALUN 2.4GHZ-2.5GHZ 50/50 0402 Manufacturers: TDK Corporation In Stock: New original, 89000 pcs Stock Available. Quote: <a href="#">RFQ</a></p>	<p><b>HHM1710D1</b> Description: BALUN 2.4GHZ-2.5GHZ 50/50 0603 Manufacturers: TDK Corporation In Stock: New original, 68300 pcs Stock Available. Quote: <a href="#">RFQ</a></p>



**IC Components Limited**  
WWW.IC-COMPONENTS.COM

Email: [Info@IC-Components.com](mailto:Info@IC-Components.com)  
TEL: 00 852 - 30501935  
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong