



CDCV304PWR

Manufacturer Part Number:	CDCV304PWR
Manufacturer / Brand	N/A
Part of Description:	IC CLK BUFFER 1:4 200MHZ 8TSSOP
Datasheets:	
Lead Free Status / RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	New original, 56000 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

CDCV304PWR 100% New Original 56000pcs in Stock, Find CDCV304PWR Price, Stock, datasheet at IC Components Ltd Online, buy CDCV304PWR with warrantied. 100% guarantee confidence. RFQ CDCV304PWR: Info@IC-Components.com

The specifications of CDCV304PWR

Part Number	CDCV304PWR	Manufacturer / Brand	N/A
Voltage - Supply	2.3 V ~ 3.6 V	Type	Fanout Buffer (Distribution)
Supplier Device Package	8-TSSOP	Series	-
Ratio - Input:Output	1:4	Packaging	Tape & Reel (TR)
Package / Case	8-TSSOP (0.173", 4.40mm Width)	Output	LVTTTL
Other Names	296-9436-2	Operating Temperature	-40°C ~ 85°C
Number of Circuits	1	Mounting Type	Surface Mount
Moisture Sensitivity Level (MSL)	1 (Unlimited)	Input	LVTTTL
Frequency - Max	200MHz	Differential - Input:Output	No/No
Detailed Description	Clock Fanout Buffer (Distribution) IC 1:4 200MHz 8-TSSOP (0.173", 4.40mm Width)	Base Part Number	CDCV304
Stock Quantity	56000 pcs Stock	Category	Integrated Circuits (ICs) > Clock/Timing - Clock Buffers, Drivers
Description	IC CLK BUFFER 1:4 200MHZ 8TSSOP	Lead Free Status / RoHS Status	Lead free / RoHS Compliant

Keywords realted to CDCV304PWR

CDCV304PWR	CDCV304PWR part	CDCV304PWR Price	CDCV304PWR Distributor
CDCV304PWR Technical	CDCV304PWR Stock	CDCV304PWR Inventory	CDCV304PWR Supplier
CDCV304PWR Online Order	CDCV304PWR Inquiry	CDCV304PWR Image	CDCV304PWR Picture
CDCV304PWR pdf	CDCV304PWR datasheet	CDCV304PWR data sheet	CDCV304PWR pdf datasheet
Download CDCV304PWR datasheet	Manufacturer		

You May Be Also Be interested In:

<p>IMAGE NOT AVAILABLE</p>	<p>CDCV850DGGRG4 Description: IC PLL CLOCK DRVR 2.5V 48TSSOP Manufacturers: N/A In Stock: New original, 2650 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p>	<p>CDCV855PWGRG4 Description: IC PLL CLOCK DRVR 2.5V 28TSSOP Manufacturers: N/A In Stock: New original, 2640 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p>	<p>CDCV857 Description: CDCV857 TI TSSOP48 Manufacturers: TI In Stock: New original, 2690 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p>IMAGE NOT AVAILABLE</p>	<p>CDCU877RHAT Description: IC PLL CLOCK DRIVER 1.8V 40VQFN Manufacturers: N/A In Stock: New original, 2823 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p>	<p>CDCV850IDGGR Description: TI TSSOP Manufacturers: TI In Stock: New original, 2669 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p>	<p>CDCUN1208LPRHBT Description: IC CLK BUJFER 2:8 400MHZ 32QFN Manufacturers: N/A In Stock: New original, 2792 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p>IMAGE NOT AVAILABLE</p>	<p>CDCU877AZQLT Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2645 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p>	<p>CDCV855PW Description: IC 1:4 DDR PLL CLK-DRVR 28-TSSOP Manufacturers: N/A In Stock: New original, 2784 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p>	<p>CDCU877ARHARG4 Description: IC PLL CLOCK DRIVER 1.8V 40VQFN Manufacturers: N/A In Stock: New original, 2656 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p>IMAGE NOT AVAILABLE</p>	<p>CDCV8551PWR Description: IC PLL CLOCK DRVR 2.5V 28TSSOP Manufacturers: N/A In Stock: New original, 2772 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p>	<p>CDCV857ADGGR Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP Manufacturers: N/A In Stock: New original, 18800 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p>	<p>CDCV855PWR Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2821 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p>IMAGE NOT AVAILABLE</p>	<p>CDCU877RHAR Description: IC PLL CLOCK DRIVER 1.8V 40VQFN Manufacturers: N/A In Stock: New original, 2735 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p>	<p>CDCUA877ZQLT Description: IC SSSL-II PLL CLK-DRVR 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2858 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p>	<p>CDCU877AZQLR Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2788 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p>IMAGE NOT AVAILABLE</p>	<p>CDCUA877ZQLR Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 17000 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p>	<p>CDCV304PWR-TR Description: TI TSSOP-8 Manufacturers: TI In Stock: New original, 6000 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p>	<p>CDCV304PWG4 Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 2800 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p>IMAGE NOT AVAILABLE</p>	<p>CDCV850DGGR Description: IC PLL CLOCK DRVR 2.5V 48-TSSOP Manufacturers: N/A In Stock: New original, 2855 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p>	<p>CDCV304PW Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 6600 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p>	<p>CDCV855 Description: CDCV855 TI TSSOP28 Manufacturers: TI In Stock: New original, 2819 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p>IMAGE NOT AVAILABLE</p>	<p>CDCU877GQLR Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2749 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p>	<p>CDCV304PWGRG4 Description: IC CLK BUJFER 1:4 200MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 13000 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p>	<p>CDCU877ZQLR Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 5000 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p>IMAGE NOT AVAILABLE</p>	<p>CDCV857ADGG Description: IC SSTL-II PLL CLK-DRVR 48-TSSOP Manufacturers: N/A In Stock: New original, 2606 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p>	<p>CDCV855-13CT Description: CDCV855-13CT TI TSSOP Manufacturers: TI In Stock: New original, 2690 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p>	<p>CDCU877ZQLT Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2805 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>
<p>IMAGE NOT AVAILABLE</p>	<p>CDCV304TPWREP Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 2690 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p>	<p>CDCU877GQLT Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2746 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p>	<p>CDCV304 Description: CDCV304 TEXAS TSP08 Manufacturers: TEXAS In Stock: New original, 2736 pcs Stock Available. Quote: <input type="text"/> <input type="button" value="RFQ"/></p>



IC Components Limited
WWW.IC-COMPONENTS.COM

Email: Info@IC-Components.com
 TEL: 00 852 - 30501935
 FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong