



**LB1861M-TLM-H**

Manufacturer Part Number:	LB1861M-TLM-H
Manufacturer / Brand	AMI Semiconductor / ON Semiconductor
Part of Description:	IC MOTOR DRIVER PAR 14MFP
Datasheets:	<a href="#">LB1861M-TLM-H.pdf</a>
Lead Free Status / RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	New original, 2000 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

LB1861M-TLM-H 100% New Original 2000pcs in Stock, Find LB1861M-TLM-H Price, Stock, datasheet at IC Components Ltd Online, buy LB1861M-TLM-H AMI Semiconductor / ON Semiconductor with warrantied, 100% guarantee confidence. RFQ LB1861M-TLM-H: [Info@IC-Components.com](mailto:Info@IC-Components.com)































The specifications of LB1861M-TLM-H

Part Number	LB1861M-TLM-H	Manufacturer / Brand	AMI Semiconductor / ON Semiconductor
Series	-	Moisture Sensitivity Level (MSL)	3 (168 Hours)
Base Part Number	LB1861	Package / Case	14-LSOP (0.173",4.40mm Width)
Packaging	Tape & Reel (TR)	Mounting Type	Surface Mount
Supplier Device Package	14-SOIC / 14MFP	Operating Temperature	-30°C ~ 80°C (TA)
Detailed Description	Half Bridge (2) Driver DC Motors, General Purpose Bipolar 14-SOIC / 14MFP	Technology	Bipolar
Features	-	Interface	Logic
Applications	DC Motors, General Purpose	Voltage - Supply	6.4 V ~ 7 V
Current - Output / Channel	1.5A	Current - Peak Output	-
Output Configuration	Half Bridge (2)	Fault Protection	Over Temperature
Load Type	Inductive	Rds On (Typ)	-
Voltage - Load	12V, 24V	Stock Quantity	2000 pcs Stock
Category	<a href="#">Integrated Circuits (ICs) &gt; PMIC - Full, Half-Bridge Drivers</a>	Description	IC MOTOR DRIVER PAR 14MFP
Lead Free Status / RoHS Status	Lead free / RoHS Compliant		

Keywords related to LB1861M-TLM-H

AMI Semiconductor / ON Semiconductor LB1861M-TLM-H	LB1861M-TLM-H part	LB1861M-TLM-H Price	LB1861M-TLM-H Distributor
	LB1861M-TLM-H Technical	LB1861M-TLM-H Stock	LB1861M-TLM-H Inventory
LB1861M-TLM-H Supplier	LB1861M-TLM-H Online Order	LB1861M-TLM-H Inquiry	LB1861M-TLM-H Image
LB1861M-TLM-H Picture	LB1861M-TLM-H pdf	LB1861M-TLM-H datasheet	LB1861M-TLM-H data sheet
LB1861M-TLM-H pdf datasheet	Download LB1861M-TLM-H datasheet	AMI Semiconductor / ON Semiconductor Manufacturer	AMI Semiconductor / ON Semiconductor LB1861M-TLM-H
ON Semiconductor LB1861M-TLM-H	Aptina / ON Semiconductor LB1861M-TLM-H	Catalyst Semiconductor / ON Semiconductor	PulseCore Semiconductor / ON Semiconductor
		LB1861M-TLM-H	LB1861M-TLM-H
Sanyo Semiconductor / ON Semiconductor LB1861M-TLM-H			

You May Be Also Be interested In:

 <b>LB1848M</b> Description: LB1848M SANYO SOP Manufacturers: SANYO In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ	 <b>LB1848M-MPB-H</b> Description: LB1848M-MPB-H SANYO SOP10 Manufacturers: SANYO In Stock: New original, 1300 pcs Stock Available. Quote: <input type="text"/> RFQ	 <b>LB1862M-DELTA-TE-L</b> Description: LB1862M-DELTA-TE-L SANYO SOP-10 Manufacturers: SANYO In Stock: New original, 400 pcs Stock Available. Quote: <input type="text"/> RFQ
 <b>LB1860M-E</b> Description: LB1860M-E SANYO SOP14 Manufacturers: SANYO In Stock: New original, 200 pcs Stock Available. Quote: <input type="text"/> RFQ	 <b>LB1862M-NMB-TLM3-E</b> Description: LB1862M-NMB-TLM3-E SANYO SOP Manufacturers: SANYO In Stock: New original, 9000 pcs Stock Available. Quote: <input type="text"/> RFQ	 <b>LB1860M-TE-L</b> Description: LB1860M-TE-L SANYO SOP-14 Manufacturers: SANYO In Stock: New original, 32500 pcs Stock Available. Quote: <input type="text"/> RFQ
 <b>LB1860</b> Description: LB1860 SANYO SOP14 Manufacturers: SANYO In Stock: New original, 29700 pcs Stock Available. Quote: <input type="text"/> RFQ	 <b>LB1848M-TRM-E</b> Description: LB1848M-TRM-E SANYO MFP10S Manufacturers: SANYO In Stock: New original, 1000 pcs Stock Available. Quote: <input type="text"/> RFQ	 <b>LB1860M-ND-TLM-E</b> Description: LB1860M-ND-TLM-E SANYO SOP-14 Manufacturers: SANYO In Stock: New original, 3000 pcs Stock Available. Quote: <input type="text"/> RFQ
 <b>LB1863M-TE-L</b> Description: LB1863M-TE-L SANYO SOP14 Manufacturers: SANYO In Stock: New original, 1000 pcs Stock Available. Quote: <input type="text"/> RFQ	 <b>LB1863M-TLM-H</b> Description: IC MOTOR DRIVER ON/OFF 14MFP Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 1400 pcs Stock Available. Quote: <input type="text"/> RFQ	 <b>LB1862M-TLM-E</b> Description: LB1862M-TLM-E SANYO SOP10 Manufacturers: SANYO In Stock: New original, 2600 pcs Stock Available. Quote: <input type="text"/> RFQ
 <b>LB1861M-TLM-E</b> Description: IC BRIDGE DRIVER PAR MFP-14S Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 6000 pcs Stock Available. Quote: <input type="text"/> RFQ	 <b>LB1862M-TLM-H</b> Description: LB1862M-TLM-H SANYO SOP10 Manufacturers: SANYO In Stock: New original, 1300 pcs Stock Available. Quote: <input type="text"/> RFQ	 <b>LB1861M-TE-L</b> Description: LB1861M-TE-L SANYO SMD Manufacturers: SANYO In Stock: New original, 30000 pcs Stock Available. Quote: <input type="text"/> RFQ
 <b>LB1867M</b> Description: LB1867M SANYO SOP14 Manufacturers: SANYO In Stock: New original, 300 pcs Stock Available. Quote: <input type="text"/> RFQ	 <b>LB1862M-MPB-H</b> Description: LB1862M-MPB-H SANYO SOP10 Manufacturers: SANYO In Stock: New original, 200 pcs Stock Available. Quote: <input type="text"/> RFQ	 <b>LB1862MC-AH</b> Description: IC MOTOR DRIVER ON/OFF 10MFP Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 2000 pcs Stock Available. Quote: <input type="text"/> RFQ
 <b>LB1861M</b> Description: LB1861M SANYO SOP14 Manufacturers: SANYO In Stock: New original, 1000 pcs Stock Available. Quote: <input type="text"/> RFQ	 <b>LB1860M-TLM-E</b> Description: IC MOTOR DRIVER PAR 14MFP Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 1000 pcs Stock Available. Quote: <input type="text"/> RFQ	 <b>LB1862</b> Description: LB1862 SANYO DIP-10 Manufacturers: SANYO In Stock: New original, 200 pcs Stock Available. Quote: <input type="text"/> RFQ
 <b>LB1863M-DELTA-TLM-H</b> Description: LB1863M-DELTA-TLM-H SANYO SOP14 Manufacturers: SANYO In Stock: New original, 2000 pcs Stock Available. Quote: <input type="text"/> RFQ	 <b>LB1848M-TE-R</b> Description: LB1848M-TE-R SANYO SOP10 Manufacturers: SANYO In Stock: New original, 2100 pcs Stock Available. Quote: <input type="text"/> RFQ	 <b>LB1861M-MPB-H</b> Description: IC BRIDGE DRIVER PAR MFP-14S Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 300 pcs Stock Available. Quote: <input type="text"/> RFQ
 <b>LB1860M-TLM-H</b> Description: IC MOTOR DRIVER PAR 14MFP Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 50000 pcs Stock Available. Quote: <input type="text"/> RFQ	 <b>LB1867</b> Description: LB1867 SANYO SOP14 Manufacturers: SANYO In Stock: New original, 18300 pcs Stock Available. Quote: <input type="text"/> RFQ	 <b>LB1862M</b> Description: LB1862M ON SOP10 Manufacturers: AMI Semiconductor / ON Semiconductor In Stock: New original, 700 pcs Stock Available. Quote: <input type="text"/> RFQ
 <b>LB1863M</b> Description: LB1863M SANYO SOP-14 Manufacturers: SANYO In Stock: New original, 400 pcs Stock Available. Quote: <input type="text"/> RFQ	 <b>LB1862M-TE-L</b> Description: LB1862M-TE-L SANYO SOP-10 Manufacturers: SANYO In Stock: New original, 6000 pcs Stock Available. Quote: <input type="text"/> RFQ	 <b>LB1860M-TE</b> Description: LB1860M-TE SANYO SOP14 Manufacturers: SANYO In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ



**IC Components Limited**  
WWW.IC-COMPONENTS.COM

Email: [Info@IC-Components.com](mailto:Info@IC-Components.com)  
TEL: 00 852 - 30501935  
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong