



954119DFLFT

Manufacturer Part Number:	954119DFLFT
Manufacturer / Brand	IDT (Integrated Device Technology)
Part of Description:	IC TIMING CTRL HUB P4 56-SSOP
Datasheets:	954119DFLFT.pdf
Lead Free Status / RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	New original, 2898 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

954119DFLFT 100% New Original 2898pcs in Stock, Find 954119DFLFT Price, Stock, datasheet at IC Components Ltd Online, buy 954119DFLFT IDT (Integrated Device Technology) with warrantied. 100% guarantee confidence. RFQ 954119DFLFT: Info@IC-Components.com

The specifications of 954119DFLFT

Part Number	954119DFLFT	Manufacturer / Brand	IDT (Integrated Device Technology)
Voltage - Supply	3.135 V ~ 3.465 V	Supplier Device Package	56-SSOP
Series	TCH™	Ratio - Input:Output	1:22
Packaging	Tape & Reel (TR)	Package / Case	56-BSSOP (0.295", 7.50mm Width)
PLL	Yes	Output	Clock
Other Names	ICS954119DFLFT ICS954119DFLFT-ND	Operating Temperature	0°C ~ 70°C
Number of Circuits	1	Mounting Type	Surface Mount
Moisture Sensitivity Level (MSL)	1 (Unlimited)	Main Purpose	Intel CPU, PCI Express (PCIe), Timing Control Hub™
Input	Crystal	Frequency - Max	400MHz
Differential - Input:Output	No/Yes	Base Part Number	ICS954119
Stock Quantity	2898 pcs Stock	Category	Integrated Circuits (ICs) > Clock/Timing - Application Specific
Description	IC TIMING CTRL HUB P4 56-SSOP	Lead Free Status / RoHS Status	Lead free / RoHS Compliant

Keywords realted to 954119DFLFT

IDT (Integrated Device Technology) 954119DFLFT	954119DFLFT part	954119DFLFT Price	954119DFLFT Distributor
954119DFLFT Technical	954119DFLFT Stock	954119DFLFT Inventory	954119DFLFT Supplier
954119DFLFT Online Order	954119DFLFT Inquiry	954119DFLFT Image	954119DFLFT Picture
954119DFLFT pdf	954119DFLFT datasheet	954119DFLFT data sheet	954119DFLFT pdf datasheet
Download 954119DFLFT datasheet	IDT (Integrated Device Technology) Manufacturer	IDT (Integrated Device Technology) 954119DFLFT	IDT 954119DFLFT
IDT (Integrated Device Technology) 954119DFLFT	IDT, Integrated Device Technology Inc 954119DFLFT	Integrated Device Technology (IDT) 954119DFLFT	

You May Be Also Be interested In:

<p>IMAGE NOT AVAILABLE</p> <p>CDCU877GQLT Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2746 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>954226ag Description: Manufacturers: ICS In Stock: New original, 2787 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p></p> <p>954101DFLF Description: IC TIMING CTRL HUB P4 56-SSOP Manufacturers: IDT (Integrated Device Technology) In Stock: New original, 2761 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>954110BF Description: 954110BF ICS SSOP Manufacturers: ICS In Stock: New original, 2717 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p></p> <p>954128AFLFT Description: 954128AFLFT IDT SSOP56 Manufacturers: IDT In Stock: New original, 2640 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p></p> <p>954206AGLFT Description: IC TIMING CTRL HUB P4 56-TSSOP Manufacturers: IDT (Integrated Device Technology) In Stock: New original, 2748 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p></p> <p>954206BGLFT Description: IDT TSSOP56 Manufacturers: IDT In Stock: New original, 3272 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>954105BF Description: 954105BF ICS SSOP Manufacturers: ICS In Stock: New original, 2744 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p></p> <p>954226AGLF Description: IC TIMING CTRL HUB P4 56-TSSOP Manufacturers: IDT (Integrated Device Technology) In Stock: New original, 2748 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p></p> <p>954226AGLFT Description: IC TIMING CTRL HUB P4 56-TSSOP Manufacturers: IDT (Integrated Device Technology) In Stock: New original, 2774 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>954305CKLF Description: 954305CKLF ICS IC Manufacturers: ICS In Stock: New original, 2664 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>954105BF ICS954105BF Description: 954105BF ICS954105BF ICS SSOP Manufacturers: ICS In Stock: New original, 2623 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p></p> <p>954101DFLFT Description: IC CTRL HUB PROGR TIMING 56-SSOP Manufacturers: IDT (Integrated Device Technology) In Stock: New original, 2894 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>954108CFLFT-INO Description: 954108CFLFT-INO ICS SSOP Manufacturers: ICS In Stock: New original, 2650 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p></p> <p>954226AKLF Description: IC TIMING CTRL HUB P4 56-VFQFPN Manufacturers: IDT (Integrated Device Technology) In Stock: New original, 2836 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>954511BFLFT Description: 954511BFLFT ICS SSOP-56 Manufacturers: ICS In Stock: New original, 2898 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>954119DFLF Description: ICS SSOP-56 Manufacturers: ICS In Stock: New original, 2620 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p></p> <p>954550CGLF-T Description: 954550CGLF-T IDT TSSOP Manufacturers: IDT In Stock: New original, 2702 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>9542 Description: 9542 EXB SOP Manufacturers: EXB In Stock: New original, 2712 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>954215AG Description: 954215AG ICS TSSOP-56 Manufacturers: ICS In Stock: New original, 2748 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p></p> <p>954201BGLFT Description: ICS Manufacturers: ICS In Stock: New original, 5000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p></p> <p>9LPR5525AGLFT Description: IC CK505 VREG/RES 56TSSOP Manufacturers: IDT (Integrated Device Technology) In Stock: New original, 7000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>954119DFLF ICS954119DFLF Description: ICS SSOP-56 0621+ Manufacturers: ICS In Stock: New original, 2738 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p></p> <p>954141CGLFT Description: 954141CGLFT IDT TSSOP Manufacturers: IDT In Stock: New original, 2614 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p></p> <p>954302AKLF Description: 954302AKLF IDT N Manufacturers: IDT In Stock: New original, 2690 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p></p> <p>954141CGLF Description: 954141CGLF IDT TSSOP Manufacturers: IDT In Stock: New original, 2687 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p></p> <p>954141CFLF Description: IC TIMING CTRL HUB P4 56-SSOP Manufacturers: IDT (Integrated Device Technology) In Stock: New original, 2718 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
<p>IMAGE NOT AVAILABLE</p> <p>954204AGLF Description: 954204AGLF ICS SSOP56 Manufacturers: ICS In Stock: New original, 2817 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p>IMAGE NOT AVAILABLE</p> <p>954305BKLF Description: 954305BKLF ICS IC Manufacturers: ICS In Stock: New original, 2607 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	<p></p> <p>MPC940LFAR2 Description: IC CLOCK DISTRIBUTION 1:18 32LQFP Manufacturers: NXP Semiconductors / Freescale In Stock: New original, 2860 pcs Stock Available. Quote: <input type="text"/> RFQ</p>



IC Components Limited
WWW.IC-COMPONENTS.COM

Email: Info@IC-Components.com
TEL: 00 852 - 30501935
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong