



AD9515BCPZ

Manufacturer Part Number:	AD9515BCPZ
Manufacturer / Brand	ADI (Analog Devices, Inc.)
Part of Description:	IC CLK BUFFER 1:2 1.6GHZ 32LFCSP
Datasheets:	AD9515BCPZ.pdf
Lead Free Status / RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	New original, 100 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

AD9515BCPZ 100% New Original 100pcs in Stock, Find AD9515BCPZ Price, Stock, datasheet at IC Components Ltd Online, buy AD9515BCPZ ADI (Analog Devices, Inc.) with warrantied. 100% guarantee confidence. RFQ AD9515BCPZ: Info@IC-Components.com































The specifications of AD9515BCPZ

Part Number	AD9515BCPZ	Manufacturer / Brand	ADI (Analog Devices, Inc.)
Series	-	Moisture Sensitivity Level (MSL)	3 (168 Hours)
Base Part Number	AD9515	Package / Case	32-VFQFN Exposed Pad, CSP
Packaging	Tray	Mounting Type	Surface Mount
Supplier Device Package	32-LFCSP-VQ (5x5)	Operating Temperature	-40°C ~ 85°C
Detailed Description	Clock Fanout Buffer (Distribution), Divider IC 1:2 1.6GHz 32-VFQFN Exposed Pad, CSP	Type	Fanout Buffer (Distribution), Divider
Frequency - Max	1.6GHz	Number of Circuits	1
Voltage - Supply	3.135 V ~ 3.465 V	Output	CMOS, LVDS, LVPECL
Input	Clock	Ratio - Input:Output	1:2
Differential - Input:Output	Yes/Yes	Stock Quantity	100 pcs Stock
Category	Integrated Circuits (ICs) > Clock/Timing - Clock Buffers, Drivers	Description	IC CLK BUFFER 1:2 1.6GHZ 32LFCSP
Lead Free Status / RoHS Status	Lead free / RoHS Compliant		

Keywords related to AD9515BCPZ

ADI (Analog Devices, Inc.) AD9515BCPZ	AD9515BCPZ part	AD9515BCPZ Price	AD9515BCPZ Distributor
AD9515BCPZ Technical	AD9515BCPZ Stock	AD9515BCPZ Inventory	AD9515BCPZ Supplier
AD9515BCPZ Online Order	AD9515BCPZ Inquiry	AD9515BCPZ Image	AD9515BCPZ Picture
AD9515BCPZ.pdf	AD9515BCPZ datasheet	AD9515BCPZ data sheet	AD9515BCPZ pdf datasheet
Download AD9515BCPZ datasheet	ADI (Analog Devices, Inc.) Manufacturer	ADI (Analog Devices, Inc.) AD9515BCPZ	AD AD9515BCPZ
ADI (Analog Devices, Inc.) AD9515BCPZ	Analog Devices Inc. AD9515BCPZ	Analog Devices, Inc. AD9515BCPZ	

You May Be Also Be interested In:

 <p>AD9511BCPZ Description: IC CLK BUFFER 2:5 1.2GHZ 48LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>AD9516-4BCPZ Description: IC CLOCK GEN 1.6GHZ VCO 64-LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 900 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>AD9518-1ABCPZ Description: IC CLOCK GEN 6CH 2.65GHZ 48LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 800 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>AD9514BCPZ-REEL7 Description: IC CLK BUFFER 1:3 1.6GHZ 32LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 2500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>AD9502CM Description: AD9502CM AD DIP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>AD9516-1BCPZ-REEL7 Description: IC CLOCK GEN 2.5GHZ VCO 64-LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 200 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>AD9510BCPZ-REEL7 Description: IC CLK BUFFER 2:8 1.2GHZ 64LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 300 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>AD9500BQ Description: AD9500BQ AD DIP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 300 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>AD9513BCPZ Description: IC CLK BUFFER 1:3 800MHZ 32LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 1300 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>AD9516-3BCPZ Description: IC CLOCK PLL/VCO 2GHZ 64LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 300 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>AD9511BCPZ-REEL7 Description: IC CLK BUFFER 2:5 1.2GHZ 48LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 1000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>AD9515BCPZ-REEL7 Description: IC CLK BUFFER 1:2 1.6GHZ 32LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 1300 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>AD9518-0ABCPZ Description: IC CLOCK GEN 6CH 2.8GHZ 48LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>AD9501 Description: AD9501 AD DIP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>AD9516-3BCPZ-REEL7 Description: IC CLOCK PLL/VCO 2GHZ 64LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 800 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>AD9516-2BCPZ Description: IC CLOCK PLL/VCO 2.2GHZ 64LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>AD9512BCPZ-REEL7 Description: IC CLK BUFFER 2:5 1.2GHZ 48LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 4700 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>AD9518-2ABCPZ Description: IC CLOCK GEN 6CH 2.2GHZ 48LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>AD9512BCPZ Description: IC CLK BUFFER 2:5 1.2GHZ 48LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 400 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>AD9517-2ABCPZ Description: IC CLOCK GEN 2.2GHZ VCO 48LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>AD9501JP Description: AD9501JP AD PLCC Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 1100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>AD9516-1BCPZ Description: IC CLOCK GEN 2.5GHZ VCO 64-LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 2500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>AD9514BCPZ Description: IC CLK BUFFER 1:3 1.6GHZ 32LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>AD9516-0BCPZ Description: IC CLOCK GEN 2.8GHZ VCO 64-LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 700 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>AD9518-1BCPZ Description: AD9518-1BCPZ AD NA Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 100 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>AD9510BCPZ Description: IC CLK BUFFER 2:8 1.2GHZ 64LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 600 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>AD9518-2ABCPZ-RL7 Description: IC CLOCK GEN 6CH 2.2GHZ 48LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 800 pcs Stock Available. Quote: <input type="text"/> RFQ</p>
 <p>AD9517-4ABCPZ-RL7 Description: IC CLOCK GEN 1.8GHZ VCO 48LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 500 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>AD9501JN Description: AD9501JN AD DIP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 6300 pcs Stock Available. Quote: <input type="text"/> RFQ</p>	 <p>AD9508BCPZ-REEL7 Description: IC CLK BUFF 1:4 1.65GHZ 24LFCSP Manufacturers: ADI (Analog Devices, Inc.) In Stock: New original, 2000 pcs Stock Available. Quote: <input type="text"/> RFQ</p>



IC Components Limited
WWW.IC-COMPONENTS.COM

Email: Info@IC-Components.com
TEL: 00 852 - 30501935
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong