



DXP18BN5014TL

Manufacturer Part Number:	DXP18BN5014TL
Manufacturer / Brand	Murata Electronics
Part of Description:	BALUN 50MHZ-870MHZ 50/200 0603
Datasheets:	DXP18BN5014TL.pdf
Lead Free Status / RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	New original, 32000 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

DXP18BN5014TL 100% New Original 32000pcs in Stock, Find DXP18BN5014TL Price, Stock, datasheet at IC Components Ltd Online, buy DXP18BN5014TL Murata Electronics with warrantied. 100% guarantee confidence. RFQ DXP18BN5014TL: Info@IC-Components.com































The specifications of DXP18BN5014TL

Part Number	DXP18BN5014TL	Manufacturer / Brand	Murata Electronics
Series	-	Return Loss (Min)	-
Phase Difference	-	Packaging	Original-Reel®
Package / Case	0603 (1608 Metric)	Other Names	490-6039-6
Mounting Type	Surface Mount	Moisture Sensitivity Level (MSL)	1 (Unlimited)
Insertion Loss (Max)	1.5dB	Impedance - Unbalanced/Balanced	50 / 200 Ohm
Frequency Range	50MHz ~ 870MHz	Detailed Description	RF Balun 50MHz ~ 870MHz 50 / 200 Ohm 0603 (1608 Metric)
Stock Quantity	32000 pcs Stock	Category	RF/IF and RFID > Balun
Description	BALUN 50MHZ-870MHZ 50/200 0603	Lead Free Status / RoHS Status	Lead free / RoHS Compliant

Keywords realted to DXP18BN5014TL

Murata Electronics DXP18BN5014TL	DXP18BN5014TL part	DXP18BN5014TL Price	DXP18BN5014TL Distributor
DXP18BN5014TL Technical	DXP18BN5014TL Stock	DXP18BN5014TL Inventory	DXP18BN5014TL Supplier
DXP18BN5014TL Online Order	DXP18BN5014TL Inquiry	DXP18BN5014TL Image	DXP18BN5014TL Picture
DXP18BN5014TL pdf	DXP18BN5014TL datasheet	DXP18BN5014TL data sheet	DXP18BN5014TL pdf datasheet
Download DXP18BN5014TL datasheet	Murata Electronics Manufacturer	Murata Electronics DXP18BN5014TL	MURATA DXP18BN5014TL
Murata Electronics North America DXP18BN5014TL	TOKO / Murata DXP18BN5014TL		

You May Be Also Be interested In:

 <p>CX2041NLT Description: Manufacturers: Pulse Electronics Corporation In Stock: New original, 2749 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	 <p>MABA-009210-CT1760 Description: BALUN 50MHZ-1.2GHZ 1:1 45MD Manufacturers: Aeroflex (MACOM Technology Solutions) In Stock: New original, 2860 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	 <p>DXP18BN5014HL Description: BALUN 470MHZ-790MHZ 50/200 0603 Manufacturers: Murata Electronics In Stock: New original, 3600 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>
 <p>HHM1906A1 Description: BALUN 4.9GHZ-5.95GHZ 50/75 0402 Manufacturers: TDK Corporation In Stock: New original, 10000 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	 <p>FI168T578717-T Description: BALUN 5.725-5.85GHZ 50/100 0603 Manufacturers: Taiyo Yuden In Stock: New original, 18000 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	 <p>MABA-007871-CT1A40 Description: TRANSFORMER 1:1 5-3000 MHZ Manufacturers: M/A-Com Technology Solutions In Stock: New original, 9300 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>
 <p>HHM1589B1 Description: BALUN 470MHZ-710MHZ 65MD Manufacturers: TDK Corporation In Stock: New original, 12000 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	 <p>BALF-NRG-01D3 Description: BALUN 2.4GHZ-2.5GHZ 50/50 4WFBGA Manufacturers: STMicroelectronics In Stock: New original, 14900 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	 <p>BD2425J50100AHF Description: BALUN 2.4GHZ-2.5GHZ 50/100 0805 Manufacturers: Anaren In Stock: New original, 3100 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>
 <p>MABA-007532-CF18A0 Description: BALUN 5MHZ-200MHZ 1:1 Manufacturers: Aeroflex (MACOM Technology Solutions) In Stock: New original, 5000 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	 <p>HHM1562B Description: BALUN 5.15-5.875GHZ 50/100 0805 Manufacturers: TDK Corporation In Stock: New original, 9900 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	 <p>DXP18CN7510T Description: DXP18CN7510T MURATA SMD Manufacturers: MURATA In Stock: New original, 2674 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>
 <p>BAL-NRF01D3 Description: BALUN 2.4GHZ-2.54GHZ 5WFBGA Manufacturers: STMicroelectronics In Stock: New original, 2747 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	 <p>HHM1715E1 Description: BALUN 3.3GHZ-3.9GHZ 50/100 0603 Manufacturers: TDK Corporation In Stock: New original, 9900 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	 <p>HHM1534 Description: BALUN DUAL 50/200 0805 Manufacturers: TDK Corporation In Stock: New original, 2674 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>
 <p>5400BL15B100E Description: BALUN 4.9GHZ-5.9GHZ 50/100 0805 Manufacturers: Johanson Technology In Stock: New original, 2694 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	 <p>RFXF8553-TR13 Description: SMT TRANSFORMER 500MHZ-2.5GHZ Manufacturers: RFMD In Stock: New original, 3900 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	 <p>DXP252690DT-5031A3 Description: TDK SMD Manufacturers: TDK In Stock: New original, 2800 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>
 <p>DXP18CN7510TL Description: RF DIR COUPLER 50MHZ-870MHZ 0603 Manufacturers: Murata Electronics In Stock: New original, 4800 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	 <p>BAL-CW1250D3 Description: BALUN 2.4GHZ-2.5GHZ 5UFBGA FCBGA Manufacturers: STMicroelectronics In Stock: New original, 5000 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	 <p>HHM1732B1 Description: BALUN 4.9GHZ-5.95GHZ 50/100 0603 Manufacturers: TDK Corporation In Stock: New original, 12000 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>
 <p>DXP2ABN7514TL Description: BALUN 50MHZ-870MHZ 75/300 0804 Manufacturers: Murata Electronics In Stock: New original, 3900 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	 <p>2595FB16A0100E Description: BALUN 2.3GHZ-2.69GHZ 50/100 0806 Manufacturers: Johanson Technology In Stock: New original, 8100 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p>  <p>DXP18BN5014T Description: DXP18BN5014T MURATA SMD Manufacturers: MURATA In Stock: New original, 2752 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>
 <p>HHM1711E1 Description: BALUN 2.3GHZ-2.7GHZ 50/100 0603 Manufacturers: TDK Corporation In Stock: New original, 12000 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	 <p>HHM1517 Description: BALUN 2.4GHZ-2.5GHZ 50/50 0805 Manufacturers: TDK Corporation In Stock: New original, 124000 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	 <p>HHM1570B1 Description: BALUN 4.9GHZ-5.95GHZ 50/100 0805 Manufacturers: TDK Corporation In Stock: New original, 3700 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>
 <p>LFB182G45BG5D920 Description: BALUN 2.4GHZ-2.5GHZ 65MD Manufacturers: Murata Electronics In Stock: New original, 10800 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	 <p>RFBLN2012090BM5T25 Description: BALUN 800MHZ-1.9GHZ 50/200 10SMD Manufacturers: Walsin Technology In Stock: New original, 15300 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	 <p>HHM1903A1 Description: BALUN 2.4GHZ-2.5GHZ 50/100 0402 Manufacturers: TDK Corporation In Stock: New original, 21000 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>



IC Components Limited
WWW.IC-COMPONENTS.COM

Email: Info@IC-Components.com
TEL: 00 852 - 30501935
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong