



X9315WMI-2.7T2

Shipment Way:

Manufacturer Part Number: Manufacturer / Brand Part of Description: Datasheets: Lead Free Status / RoHS Status: **Stock Condition: Ship From:**

X9315WMI-2.7T2

Hong Kong

DHL/Fedex/TNT/UPS

IC XDCP 32-TAP 10K 3WIRE 8-MSOP X9315WMI-2.7T2.pdf 🐚 ي Contains lead / RoHS non-compliant

New original, 3000 pcs Stock Available.

GET A QUOTE

X9315WMI-2.7T2 100% New Original 3000pcs in Stock, Find X9315WMI-2.7T2 Price, Stock, datasheet at IC Components Ltd Online, buy X9315WMI-2.7T2 Intersil with warrantied. 100% guarantee confidence. RFQ X9315WMI-2.7T2: Info@IC-Components.com

The specifications of X9315WMI-2.7T2

Part Number	X9315WMI-2.7T2	Manufacturer / Brand	Intersil
Series	XDCP™	Moisture Sensitivity Level (MSL)	3 (168 Hours)
Base Part Number	X9315	Package / Case	8-TSSOP, 8-MSOP (0.118", 3.00mm Width)
Packaging	Tape & Reel (TR)	Supplier Device Package	8-MSOP
Operating Temperature	-40°C ~ 85°C	Detailed Description	Digital Potentiometer 10k Ohm 1 Circuit 32 Taps Up/Down (U/D, INC, CS) Interface 8-MSOP
Features	-	Interface	Up/Down (U/D, INC, CS)
Configuration	Potentiometer	Tolerance	±20%
Number of Circuits	1	Voltage - Supply	2.7 V ~ 5.5 V
Memory Type	Non-Volatile	Resistance (Ohms)	10k
Taper	Linear	Number of Taps	32
Temperature Coefficient (Typ)	±300 ppm/°C	Resistance - Wiper (Ohms) (Typ)	400
Stock Quantity	3000 pcs Stock	Category	Integrated Circuits (ICs) > Data Acquisition - Digital Potentiometers
Description	IC XDCP 32-TAP 10K 3WIRE 8-MSOP	Lead Free Status / RoHS Status	Contains lead / RoHS non-compliant

Keywords realted to X9315WMI-2.7T2

Intersil X9315WMI-2.7T2	X9315WMI-2.7T2 part	X9315WMI-2.7T2 Price	X9315WMI-2.7T2 Distributor
X9315WMI-2.7T2 Technical	X9315WMI-2.7T2 Stock	X9315WMI-2.7T2 Inventory	X9315WMI-2.7T2 Supplier
X9315WMI-2.7T2 Online Order	X9315WMI-2.7T2 Inquiry	X9315WMI-2.7T2 Image	X9315WMI-2.7T2 Picture
X9315WMI-2.7T2 pdf	X9315WMI-2.7T2 datasheet	X9315WMI-2.7T2 data sheet	X9315WMI-2.7T2 pdf datasheet
Download X9315WMI-2.7T2 datasheet	Intersil Manufacturer	Intersil X9315WMI-2.7T2	

X9315WMI-2.7

You May Be Also Be interested In:

X9315UPI



IMAGE NOT

AVAILABLE

IMAGE NOT

AVAILABLE

Description: IC XDCP 32-TAP 50K 3WIRE 8-DIP Manufacturers: Intersil

Manufacturers: XICOR

X93154UU8IZ-3T1

Manufacturers: Intersil

Description: X9315W XICOR SOP

Manufacturers: XICOR

X9315W

X9315WMIZ

Manufacturers: Intersil

X93156UM8IZ-2.7

Manufacturers: Intersil

In Stock: New original, 4900 pcs Stock Available. RFQ Quote:

Description: X9315WMI-2.7T XICOR MSOP8

In Stock: New original, 8800 pcs Stock Available.

Description: IC POT DGTL LP LN 50K OHM 8-TDFN

In Stock: New original, 1100 pcs Stock Available.

In Stock: New original, 100 pcs Stock Available.

Description: IC XDCP 32-TAP 10K 3WIRE 8-MSOP

In Stock: New original, 4600 pcs Stock Available.

X9315WMI-2.7T



Quote:

Quote:

Quote:

Quote:

Quote:

RFQ

RFQ

RFQ

RFQ

RFQ



IMAGE NOT

AVAILABLE

Manufacturers: Intersil In Stock: New original, 1000 pcs Stock Available. RFQ Quote:

X9315WMI-27TI **Description:** X9315WMI-27TI XICOR MSOP-8

RFQ

RFQ

RFQ

Quote:





X9315UMI-2.7T1 **Description:** IC XDCP 32-TAP 50K 3WIRE 8-MSOP Manufacturers: Intersil

In Stock: New original, 6900 pcs Stock Available. Quote: RFQ



Manufacturers: Intersil In Stock: New original, 11500 pcs Stock Available.

Description: IC XDCP 32-TAP 50K 3WIRE 8-MSOP

Quote:

Quote:



Manufacturers: Intersil In Stock: New original, 100 pcs Stock Available.



intersil

X9315WP

Description: IC DIGITAL POT 10K 32TP 8DIP Manufacturers: Intersil

Description: X9315UF-2.7T1 INTERSIL SOP8

In Stock: New original, 200 pcs Stock Available.

X9315UF-2.7T1

X9315WS-2.7

Manufacturers: Intersil

X9315UM-2.7T1

Manufacturers: Intersil

In Stock: New original, 1900 pcs Stock Available.

RFQ Quote:

RFQ

Description: IC XDCP 32-TAP 10K 3WIRE 8-SOIC Manufacturers: Intersil In Stock: New original, 9900 pcs Stock Available.

X9315WSIZ

X9315WMIZ-2.7

X9315WPIZ

X9315TSZ

X9315WSI

X9315WMIT1

Manufacturers: Intersil

Manufacturers: Intersil

Manufacturers: Intersil

Manufacturers: Intersil

intersil

Manufacturers: Intersil

Description: IC XDCP 32-TAP 10K 3WIRE 8-MSOP

Quote:

Quote:

Quote:

Quote:

Quote:

RFQ

RFQ

RFQ

RFQ

RFQ

RFQ

RFQ

RFQ

RFQ

In Stock: New original, 500 pcs Stock Available.

Description: X9315WPIZ INTERSIL DIP8

In Stock: New original, 5700 pcs Stock Available.

Description: IC XDCP 32-TAP 100K 3WIRE 8-SOIC

In Stock: New original, 100 pcs Stock Available.


Description: IC DIGITAL POT 10K 32TP 8SOIC

In Stock: New original, 200 pcs Stock Available.

Description: IC XDCP 32-TAP 10K 3WIRE 8-MSOP

In Stock: New original, 4600 pcs Stock Available.

Quote:



Manufacturers: Intersil

X9315WMIZT1 Description: IC XDCP 32-TAP 10K 3WIRE 8-MSOP

Description: IC XDCP 32-TAP 50K 3-WIRE 8-MSOP

In Stock: New original, 16500 pcs Stock Available.

In Stock: New original, 4600 pcs Stock Available. RFQ Quote:

X9315UP

Description: IC XDCP 32-TAP 50K 3WIRE 8-DIP Manufacturers: Intersil In Stock: New original, 21800 pcs Stock Available.

Quote: RFQ

X9315WSIZ-2.7T1 **Description:** IC XDCP 32-TAP 10K 3WIRE 8-SOIC Manufacturers: Intersil

RFQ Quote:

Description: IC DIGITAL POT 10K 32TP 8MSOP

Quote:

Description: IC DIGITAL POT 10K 32TP 8SOIC

In Stock: New original, 1700 pcs Stock Available.

Quote:

Manufacturers: Intersil

X9315WS-2.7T1

In Stock: New original, 2100 pcs Stock Available. Quote:

Description: IC XDCP 32-TAP 10K 3WIRE 8-SOIC

X9315WMIZ-2.7T1 Description: IC POT DGTL 10K OHM 8-MSOP Manufacturers: Intersil In Stock: New original, 12500 pcs Stock Available.



In Stock: New original, 100 pcs Stock Available.

Description: IC XDCP 32-TAP 50K 3WIRE 8-MSOP Manufacturers: Intersil In Stock: New original, 1700 pcs Stock Available.

RFQ Quote:



X9315WMI

Description: IC DIGITAL POT 10K 32TP 8MSOP

Quote:

Manufacturers: Intersil In Stock: New original, 4600 pcs Stock Available. Quote:



Manufacturers: Intersil

X9315WM-2.7

In Stock: New original, 2300 pcs Stock Available. Quote: RFQ

X93155UM8IT1 **Description:** IC XDCP 32-TAP 50K 3-WIRE 8-MSOP Manufacturers: Intersil In Stock: New original, 5000 pcs Stock Available.

Quote:

RFQ



X9315WSIZT1 Description: IC XDCP 32-TAP 10K 3WIRE 8-SOIC Manufacturers: Intersil

In Stock: New original, 100 pcs Stock Available. Quote: RFQ

IC Components Limited WWW.IC-COMPONENTS.COM Email: Info@IC-Components.com

TEL: 00 852 - 30501935 FAX: 00 852 - 30501945 Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong

IC Components Ltd is Distributor of IC and Capacitors Electronic Components @ 2018 IC-Components.com All right Reserved.