



## CDCUA877ZQLR

|                                 |  |
|---------------------------------|--|
| Manufacturer Part Number:       | CDCUA877ZQLR                             |
| Manufacturer / Brand:           | N/A                                      |
| Part of Description:            | IC PLL CLOCK DRIVER 1.8V 52-BGA          |
| Datasheets:                     |  |
| Lead Free Status / RoHS Status: | Lead free / RoHS Compliant               |
| Stock Condition:                | New original, 17000 pcs Stock Available. |
| Ship From:                      | Hong Kong                                |
| Shipment Way:                   | DHL/Fedex/TNT/UPS                        |

[GET A QUOTE](#)

**CDCUA877ZQLR** 100% New Original 17000pcs in Stock, Find CDCUA877ZQLR Price, Stock, datasheet at IC Components Ltd Online, buy CDCUA877ZQLR with warrantied. 100% guarantee confidence. RFQ CDCUA877ZQLR: [Info@IC-Components.com](mailto:Info@IC-Components.com)

### The specifications of CDCUA877ZQLR

|                                  |                                 |                                |  |
|----------------------------------|---------------------------------|--------------------------------|--|
| Part Number                      | CDCUA877ZQLR                    | Manufacturer / Brand           | N/A  |
| Voltage - Supply                 | 1.7 V ~ 1.9 V                   | Supplier Device Package        | 52-BGA MICROSTAR JUNIOR (7x4.5)  |
| Series                           | -                               | Ratio - Input:Output           | 1:10   |
| Packaging                        | Tape & Reel (TR)                | Package / Case                 | 52-VFBGA   |
| PLL                              | Yes                             | Output                         | SSTL-18  |
| Other Names                      | 296-26039-2<br>CDCUA877ZQLR-ND  | Operating Temperature          | -40°C ~ 85°C   |
| Number of Circuits               | 1                               | Mounting Type                  | Surface Mount  |
| Moisture Sensitivity Level (MSL) | 2 (1 Year)                      | Main Purpose                   | Memory, DDR2   |
| Input                            | SSTL-18                         | Frequency - Max                | 410MHz   |
| Differential - Input:Output      | Yes/Yes                         | Base Part Number               | CDCUA877   |
| Stock Quantity                   | 17000 pcs Stock                 | Category                       | <a href="#">Integrated Circuits (ICs) &gt; Clock/Timing - Application Specific</a> |
| Description                      | IC PLL CLOCK DRIVER 1.8V 52-BGA | Lead Free Status / RoHS Status | Lead free / RoHS Compliant   |

### Keywords realted to CDCUA877ZQLR

|                                 |                        |                         |                            |
|---------------------------------|------------------------|-------------------------|----------------------------|
| CDCUA877ZQLR                    | CDCUA877ZQLR part      | CDCUA877ZQLR Price      | CDCUA877ZQLR Distributor   |
| CDCUA877ZQLR Technical          | CDCUA877ZQLR Stock     | CDCUA877ZQLR Inventory  | CDCUA877ZQLR Supplier      |
| CDCUA877ZQLR Online Order       | CDCUA877ZQLR Inquiry   | CDCUA877ZQLR Image      | CDCUA877ZQLR Picture       |
| CDCUA877ZQLR pdf                | CDCUA877ZQLR datasheet | CDCUA877ZQLR data sheet | CDCUA877ZQLR pdf datasheet |
| Download CDCUA877ZQLR datasheet | Manufacturer           |                         |                            |

### You May Be Also Be interested In:

|   |   |   |
|---|---|---|
| <p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCS503PWR</b><br/>Description: IC CLK BUFFER 1:1 108MHZ 8TSSOP<br/>Manufacturers: N/A<br/>In Stock: New original, 2834 pcs Stock Available.<br/>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>     | <p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCV304PWRG4</b><br/>Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP<br/>Manufacturers: N/A<br/>In Stock: New original, 13000 pcs Stock Available.<br/>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>  | <p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCV855IPWR</b><br/>Description: IC PLL CLOCK DRVR 2.5V 28TSSOP<br/>Manufacturers: N/A<br/>In Stock: New original, 2772 pcs Stock Available.<br/>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>   |
| <p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCS503TPWRQ1</b><br/>Description: IC CLK BUFFER 1:1 108MHZ 8TSSOP<br/>Manufacturers: N/A<br/>In Stock: New original, 2685 pcs Stock Available.<br/>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>  | <p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCV304PW</b><br/>Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP<br/>Manufacturers: N/A<br/>In Stock: New original, 6600 pcs Stock Available.<br/>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>      | <p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCU877A</b><br/>Description: CDCU877A TI BGA<br/>Manufacturers: TI<br/>In Stock: New original, 2654 pcs Stock Available.<br/>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>                      |
| <p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCU877ZQLR</b><br/>Description: IC PLL CLOCK DRIVER 1.8V 52-BGA<br/>Manufacturers: N/A<br/>In Stock: New original, 5000 pcs Stock Available.<br/>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>    | <p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCV855</b><br/>Description: CDCV855 TI TSSOP28<br/>Manufacturers: TI<br/>In Stock: New original, 2819 pcs Stock Available.<br/>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>                      | <p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCV855-13CT</b><br/>Description: CDCV855-13CT TI TSSOP<br/>Manufacturers: TI<br/>In Stock: New original, 2690 pcs Stock Available.<br/>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>            |
| <p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCV850IDGGR</b><br/>Description: TI TSSOP<br/>Manufacturers: TI<br/>In Stock: New original, 2669 pcs Stock Available.<br/>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>                           | <p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCU877ARHARG4</b><br/>Description: IC PLL CLOCK DRIVER 1.8V 40VQFN<br/>Manufacturers: N/A<br/>In Stock: New original, 2656 pcs Stock Available.<br/>Quote: <input type="text"/> <input type="button" value="RFQ"/></p> | <p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCU877RHAT</b><br/>Description: IC PLL CLOCK DRIVER 1.8V 40VQFN<br/>Manufacturers: N/A<br/>In Stock: New original, 2823 pcs Stock Available.<br/>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>  |
| <p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCV304PWR-TR</b><br/>Description: TI TSSOP-8<br/>Manufacturers: TI<br/>In Stock: New original, 6000 pcs Stock Available.<br/>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>                        | <p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCU877RHAR</b><br/>Description: IC PLL CLOCK DRIVER 1.8V 40VQFN<br/>Manufacturers: N/A<br/>In Stock: New original, 2735 pcs Stock Available.<br/>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>    | <p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCV304</b><br/>Description: CDCV304 TEXAS TSP08<br/>Manufacturers: TEXAS<br/>In Stock: New original, 2736 pcs Stock Available.<br/>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>                |
| <p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCV304TPWREP</b><br/>Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP<br/>Manufacturers: N/A<br/>In Stock: New original, 2690 pcs Stock Available.<br/>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>  | <p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCV304PWR</b><br/>Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP<br/>Manufacturers: N/A<br/>In Stock: New original, 56000 pcs Stock Available.<br/>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>    | <p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCV850DGGR</b><br/>Description: IC PLL CLOCK DRVR 2.5V 48-TSSOP<br/>Manufacturers: N/A<br/>In Stock: New original, 2855 pcs Stock Available.<br/>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>  |
| <p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCUA877ZQLT</b><br/>Description: IC PLL CLOCK DRIVER 1.8V 52-BGA<br/>Manufacturers: N/A<br/>In Stock: New original, 2858 pcs Stock Available.<br/>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>   | <p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCU2A877ZQLR</b><br/>Description: IC PLL CLOCK DRIVER 1.8V 52-BGA<br/>Manufacturers: N/A<br/>In Stock: New original, 23600 pcs Stock Available.<br/>Quote: <input type="text"/> <input type="button" value="RFQ"/></p> | <p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCU877ZQLT</b><br/>Description: IC PLL CLOCK DRIVER 1.8V 52-BGA<br/>Manufacturers: N/A<br/>In Stock: New original, 2805 pcs Stock Available.<br/>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>  |
| <p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCUN1208LPRHBT</b><br/>Description: IC CLK BUFFER 2:8 400MHZ 32QFN<br/>Manufacturers: N/A<br/>In Stock: New original, 2792 pcs Stock Available.<br/>Quote: <input type="text"/> <input type="button" value="RFQ"/></p> | <p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCU877AZQLT</b><br/>Description: IC PLL CLOCK DRIVER 1.8V 52-BGA<br/>Manufacturers: N/A<br/>In Stock: New original, 2645 pcs Stock Available.<br/>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>   | <p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCV850DGGRG4</b><br/>Description: IC PLL CLOCK DRVR 2.5V 48TSSOP<br/>Manufacturers: N/A<br/>In Stock: New original, 2650 pcs Stock Available.<br/>Quote: <input type="text"/> <input type="button" value="RFQ"/></p> |
| <p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCU877GQLT</b><br/>Description: IC PLL CLOCK DRIVER 1.8V 52-BGA<br/>Manufacturers: N/A<br/>In Stock: New original, 2746 pcs Stock Available.<br/>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>    | <p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCV304PWG4</b><br/>Description: IC CLK BUFFER 1:4 200MHZ 8TSSOP<br/>Manufacturers: N/A<br/>In Stock: New original, 2800 pcs Stock Available.<br/>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>    | <p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCU877AGQLR</b><br/>Description: IC PLL CLOCK DRIVER 1.8V 52-BGA<br/>Manufacturers: N/A<br/>In Stock: New original, 2609 pcs Stock Available.<br/>Quote: <input type="text"/> <input type="button" value="RFQ"/></p> |
| <p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCU877GQLR</b><br/>Description: IC PLL CLOCK DRIVER 1.8V 52-BGA<br/>Manufacturers: N/A<br/>In Stock: New original, 2749 pcs Stock Available.<br/>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>    | <p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCU877AZQLR</b><br/>Description: IC PLL CLOCK DRIVER 1.8V 52-BGA<br/>Manufacturers: N/A<br/>In Stock: New original, 2788 pcs Stock Available.<br/>Quote: <input type="text"/> <input type="button" value="RFQ"/></p>   | <p><b>IMAGE NOT AVAILABLE</b></p> <p><b>CDCU877ARHAR</b><br/>Description: IC PLL CLOCK DRIVER 1.8V 40VQFN<br/>Manufacturers: N/A<br/>In Stock: New original, 2749 pcs Stock Available.<br/>Quote: <input type="text"/> <input type="button" value="RFQ"/></p> |



**IC Components Limited**  
WWW.IC-COMPONENTS.COM

Email: [Info@IC-Components.com](mailto:Info@IC-Components.com)  
TEL: 00 852 - 30501935  
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong