



CDCU2A877ZQLR

Manufacturer Part Number:	CDCU2A877ZQLR
Manufacturer / Brand	N/A
Part of Description:	IC PLL CLOCK DRIVER 1.8V 52-BGA
Datasheets:	
Lead Free Status / RoHS Status:	Lead free / RoHS Compliant
Stock Condition:	New original, 23600 pcs Stock Available.
Ship From:	Hong Kong
Shipment Way:	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

CDCU2A877ZQLR 100% New Original 23600pcs in Stock, Find CDCU2A877ZQLR Price, Stock, datasheet at IC Components Ltd Online, buy CDCU2A877ZQLR with warrantied. 100% guarantee confidence. RFQ CDCU2A877ZQLR: Info@IC-Components.com

The specifications of CDCU2A877ZQLR

Part Number	CDCU2A877ZQLR	Manufacturer / Brand	N/A
Voltage - Supply	1.7 V ~ 1.9 V	Supplier Device Package	52-BGA MICROSTAR JUNIOR (7x4.5)
Series	-	Ratio - Input:Output	1:10
Packaging	Tape & Reel (TR)	Package / Case	52-VFBGA
PLL	Yes	Output	SSTL-18
Operating Temperature	0°C ~ 70°C	Number of Circuits	1
Mounting Type	Surface Mount	Moisture Sensitivity Level (MSL)	2 (1 Year)
Main Purpose	Memory, DDR2	Input	SSTL-18
Frequency - Max	410MHz	Differential - Input:Output	Yes/Yes
Base Part Number	CDCU2A877	Stock Quantity	23600 pcs Stock
Category	Integrated Circuits (ICs) > Clock/Timing - Application Specific	Description	IC PLL CLOCK DRIVER 1.8V 52-BGA
Lead Free Status / RoHS Status	Lead free / RoHS Compliant		

Keywords realted to CDCU2A877ZQLR

CDCU2A877ZQLR	CDCU2A877ZQLR part	CDCU2A877ZQLR Price	CDCU2A877ZQLR Distributor
CDCU2A877ZQLR Technical	CDCU2A877ZQLR Stock	CDCU2A877ZQLR Inventory	CDCU2A877ZQLR Supplier
CDCU2A877ZQLR Online Order	CDCU2A877ZQLR Inquiry	CDCU2A877ZQLR Image	CDCU2A877ZQLR Picture
CDCU2A877ZQLR pdf	CDCU2A877ZQLR datasheet	CDCU2A877ZQLR data sheet	CDCU2A877ZQLR pdf datasheet
Download CDCU2A877ZQLR datasheet	Manufacturer		

You May Be Also Be interested In:

<p>CDCS503PWR Description: IC CLK BUFFER 1:1 108MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 2834 pcs Stock Available. Quote: RFQ</p>	<p>CDCR83DBQ Description: IC DIRECT RAMBUS CLK GEN 24-QSOP Manufacturers: N/A In Stock: New original, 5000 pcs Stock Available. Quote: RFQ</p>	<p>CDCU877AZQLT Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2645 pcs Stock Available. Quote: RFQ</p>
<p>CDCR81DBQR Description: IC DIRECT RAMBUS CLK GEN 24-QSOP Manufacturers: N/A In Stock: New original, 11400 pcs Stock Available. Quote: RFQ</p>	<p>CDCU877RHAR Description: IC PLL CLOCK DRIVER 1.8V 40VQFN Manufacturers: N/A In Stock: New original, 2735 pcs Stock Available. Quote: RFQ</p>	<p>CDCS501PWR Description: IC CLOCK GEN/BUFFER SSC 8TSSOP Manufacturers: N/A In Stock: New original, 3200 pcs Stock Available. Quote: RFQ</p>
<p>CDCR83ADBQ Description: Manufacturers: N/A In Stock: New original, 2728 pcs Stock Available. Quote: RFQ</p>	<p>CDCR62005RGZT Description: CDCR62005RGZT TI QFN48 Manufacturers: TI In Stock: New original, 2834 pcs Stock Available. Quote: RFQ</p>	<p>CDCU877ZQLR Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 5000 pcs Stock Available. Quote: RFQ</p>
<p>CDCS503TPWRQ1 Description: IC CLK BUFFER 1:1 108MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 2685 pcs Stock Available. Quote: RFQ</p>	<p>CDCU877ARHAR Description: IC PLL CLOCK DRIVER 1.8V 40VQFN Manufacturers: N/A In Stock: New original, 2749 pcs Stock Available. Quote: RFQ</p>	<p>CDCR83ADBQRG4 Description: IC DIRECT RAMBUS CLK GEN 24-QSOP Manufacturers: N/A In Stock: New original, 2500 pcs Stock Available. Quote: RFQ</p>
<p>CDCS503PW Description: IC CLK BUFFER 1:1 108MHZ 8TSSOP Manufacturers: N/A In Stock: New original, 2783 pcs Stock Available. Quote: RFQ</p>	<p>CDCR81 Description: CDCR81 TI SSOP Manufacturers: TI In Stock: New original, 4900 pcs Stock Available. Quote: RFQ</p>	<p>CDCR83ADBQR Description: IC DIRECT RAMBUS CLK GEN 24-QSOP Manufacturers: N/A In Stock: New original, 17500 pcs Stock Available. Quote: RFQ</p>
<p>CDCU877ZQLT Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2858 pcs Stock Available. Quote: RFQ</p>	<p>CDCU877AZQLR Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2788 pcs Stock Available. Quote: RFQ</p>	<p>CDCU877ARHARG4 Description: IC PLL CLOCK DRIVER 1.8V 40VQFN Manufacturers: N/A In Stock: New original, 2656 pcs Stock Available. Quote: RFQ</p>
<p>CDCS502PWR Description: IC OSC CLOCK GENERATOR 8-TSSOP Manufacturers: N/A In Stock: New original, 2770 pcs Stock Available. Quote: RFQ</p>	<p>CDCU877RHAT Description: IC PLL CLOCK DRIVER 1.8V 40VQFN Manufacturers: N/A In Stock: New original, 2823 pcs Stock Available. Quote: RFQ</p>	<p>CDCU877AGQLR Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2609 pcs Stock Available. Quote: RFQ</p>
<p>CDCR83DB Description: CDCR83DB TI SSOP Manufacturers: TI In Stock: New original, 2844 pcs Stock Available. Quote: RFQ</p>	<p>CDCUN1208LPRHBT Description: IC CLK BUFFER 2:8 400MHZ 32QFN Manufacturers: N/A In Stock: New original, 2792 pcs Stock Available. Quote: RFQ</p>	<p>CDCU877ZQLT Description: IC CLK BUFFER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2805 pcs Stock Available. Quote: RFQ</p>
<p>CDCU877A Description: CDCU877A TI BGA Manufacturers: TI In Stock: New original, 2654 pcs Stock Available. Quote: RFQ</p>	<p>CDCU877GQLT Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2746 pcs Stock Available. Quote: RFQ</p>	<p>CDCU877ZQLR Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 17000 pcs Stock Available. Quote: RFQ</p>
<p>CDCR83ADBQR G4 Description: CDCR83ADBQR G4 TI SSOP-24 Manufacturers: TI In Stock: New original, 2789 pcs Stock Available. Quote: RFQ</p>	<p>CDCR83DBQR Description: IC DIRECT RAMBUS CLK GEN 24-QSOP Manufacturers: N/A In Stock: New original, 2500 pcs Stock Available. Quote: RFQ</p>	<p>CDCU877GQLR Description: IC PLL CLOCK DRIVER 1.8V 52-BGA Manufacturers: N/A In Stock: New original, 2749 pcs Stock Available. Quote: RFQ</p>



IC Components Limited
WWW.IC-COMPONENTS.COM

Email: Info@IC-Components.com
TEL: 00 852 - 30501935
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong