



## 2595FB16A0100E

<b>Manufacturer Part Number:</b>	2595FB16A0100E
<b>Manufacturer / Brand</b>	Johanson Technology
<b>Part of Description:</b>	BALUN 2.3GHZ~2.69GHZ 50/100 0806
<b>Datasheets:</b>	2595FB16A0100E.pdf
<b>Lead Free Status / RoHS Status:</b>	Lead free / RoHS Compliant
<b>Stock Condition:</b>	New original, 8100 pcs Stock Available.
<b>Ship From:</b>	Hong Kong
<b>Shipment Way:</b>	DHL/Fedex/TNT/UPS

[GET A QUOTE](#)

**2595FB16A0100E** 100% New Original 8100pcs in Stock, Find 2595FB16A0100E Price, Stock, datasheet at IC Components Ltd Online, buy 2595FB16A0100E Johanson Technology with warrantied. 100% guarantee confidence. RFQ 2595FB16A0100E: [Info@IC-Components.com](mailto:Info@IC-Components.com)

### The specifications of 2595FB16A0100E

Part Number	2595FB16A0100E	Manufacturer / Brand	Johanson Technology
Series	-	Return Loss (Min)	9.5dB
Phase Difference	180° ±10°	Packaging	Tape & Reel (TR)
Package / Case	0806 (2015 Metric), 6 PC Pad	Mounting Type	Surface Mount
Moisture Sensitivity Level (MSL)	1 (Unlimited)	Insertion Loss (Max)	2.5dB
Impedance - Unbalanced/Balanced	50 / 100 Ohm	Frequency Range	2.3GHz ~ 2.69GHz
Detailed Description	RF Balun 2.3GHz ~ 2.69GHz 50 / 100 Ohm 0806 (2015 Metric), 6 PC Pad	Stock Quantity	8100 pcs Stock
Category	<a href="#">RF/IF and RFID &gt; Balun</a>	Description	BALUN 2.3GHZ-2.69GHZ 50/100 0806
Lead Free Status / RoHS Status	Lead free / RoHS Compliant		

### Keywords realted to 2595FB16A0100E

Johanson Technology 2595FB16A0100E	2595FB16A0100E part	2595FB16A0100E Price	2595FB16A0100E Distributor
2595FB16A0100E Technical	2595FB16A0100E Stock	2595FB16A0100E Inventory	2595FB16A0100E Supplier
2595FB16A0100E Online Order	2595FB16A0100E Inquiry	2595FB16A0100E Image	2595FB16A0100E Picture
2595FB16A0100E pdf	2595FB16A0100E datasheet	2595FB16A0100E data sheet	2595FB16A0100E pdf datasheet
Download 2595FB16A0100E datasheet	Johanson Technology Manufacturer	Johanson Technology 2595FB16A0100E	Johanson 2595FB16A0100E
Johanson Technology Inc. 2595FB16A0100E			

### You May Be Also Be interested In:

<p><b>5400BL15B050E</b> <b>Description:</b> BALUN 4.9GHZ-5.9GHZ 50/50 0805 <b>Manufacturers:</b> Johanson Technology <b>In Stock:</b> New original, 2765 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p><b>MABA-007159-000000</b> <b>Description:</b> BALUN 4.5MHZ-3GHZ 1:1 6SMD FLAT <b>Manufacturers:</b> Aeroflex (MACOM Technology Solutions) <b>In Stock:</b> New original, 2617 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p><b>BD0810J50150AHF</b> <b>Description:</b> BALUN 800MHZ-1GHZ 50/150 0805 <b>Manufacturers:</b> Anaren <b>In Stock:</b> New original, 24700 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>
<p><b>2593A20</b> <b>Description:</b> <b>Manufacturers:</b> SKYWORKS <b>In Stock:</b> New original, 5000 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p> <p><b>2594HM-ADJ</b> <b>Description:</b> NS SOP8 <b>Manufacturers:</b> NS <b>In Stock:</b> New original, 2868 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p><b>2595FB39A0050E</b> <b>Description:</b> BALUN DUAL 50/50 1008 6 PC PAD <b>Manufacturers:</b> Johanson Technology <b>In Stock:</b> New original, 13500 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>
<p><b>2450BL15B050E</b> <b>Description:</b> BALUN 2.4GHZ-2.5GHZ 50/50 0805 <b>Manufacturers:</b> Johanson Technology <b>In Stock:</b> New original, 5500 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p><b>DXP2ABN7514TL</b> <b>Description:</b> BALUN 50MHZ-870MHZ 75/300 0804 <b>Manufacturers:</b> Murata Electronics <b>In Stock:</b> New original, 3900 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p><b>HHM1733B1</b> <b>Description:</b> BALUN 4.9GHZ-5.95GHZ 50/50 0603 <b>Manufacturers:</b> TDK Corporation <b>In Stock:</b> New original, 16000 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>
<p><b>ETC1-1-13TR</b> <b>Description:</b> BALUN 4.5MHZ-3GHZ 1:1 5SMD <b>Manufacturers:</b> Aeroflex (MACOM Technology Solutions) <b>In Stock:</b> New original, 4300 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p><b>RFBLN1608050AM8T62</b> <b>Description:</b> BALUN 2.4GHZ-2.5GHZ 50/50 6SMD <b>Manufacturers:</b> Walsin Technology <b>In Stock:</b> New original, 2500 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p><b>HHM1726P1</b> <b>Description:</b> BALUN 880MHZ-960MHZ 50/100 0603 <b>Manufacturers:</b> TDK Corporation <b>In Stock:</b> New original, 9900 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>
<p><b>0900BL18B200E</b> <b>Description:</b> JOHANSON SMD <b>Manufacturers:</b> JOHANSON <b>In Stock:</b> New original, 2617 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p><b>MABA-009594-CF18A0</b> <b>Description:</b> BALUN 5MHZ-200MHZ 1:1 6SMD GW <b>Manufacturers:</b> Aeroflex (MACOM Technology Solutions) <b>In Stock:</b> New original, 4500 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p><b>HHM1715E1</b> <b>Description:</b> BALUN 3.3GHZ-3.9GHZ 50/100 0603 <b>Manufacturers:</b> TDK Corporation <b>In Stock:</b> New original, 8000 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>
<p><b>HHM1902B1</b> <b>Description:</b> BALUN 2.4GHZ-2.5GHZ 50/50 0402 <b>Manufacturers:</b> TDK Corporation <b>In Stock:</b> New original, 89000 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p><b>5512BL15B100E</b> <b>Description:</b> BALUN 5.15-5.875GHZ 50/100 0805 <b>Manufacturers:</b> Johanson Technology <b>In Stock:</b> New original, 4000 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p><b>LDB182G4520C-110</b> <b>Description:</b> BALUN 2.4GHZ-2.5GHZ 50/200 0603 <b>Manufacturers:</b> Murata Electronics <b>In Stock:</b> New original, 100100 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>
<p><b>5400BL15B100E</b> <b>Description:</b> BALUN 4.9GHZ-5.9GHZ 50/100 0805 <b>Manufacturers:</b> Johanson Technology <b>In Stock:</b> New original, 2694 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p><b>MABA-007237-ETC410</b> <b>Description:</b> BALUN 1MHZ-350MHZ 1:4 6SMD FLAT <b>Manufacturers:</b> Aeroflex (MACOM Technology Solutions) <b>In Stock:</b> New original, 2854 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p> <p><b>259A9873P4</b> <b>Description:</b> 259A9873P4 TO-11P 99 <b>Manufacturers:</b> TO-11P <b>In Stock:</b> New original, 2810 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>
<p><b>259A9871P3</b> <b>Description:</b> 259A9871P3 INTERSIL ZIP9 <b>Manufacturers:</b> INTERSIL <b>In Stock:</b> New original, 2859 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p><b>HHM1711D1</b> <b>Description:</b> BALUN 2.4GHZ-2.5GHZ 50/100 0603 <b>Manufacturers:</b> TDK Corporation <b>In Stock:</b> New original, 28500 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p><b>CX2045LNLT</b> <b>Description:</b> BALUN 3MHZ-300MHZ 5SMD <b>Manufacturers:</b> Pulse Electronics Corporation <b>In Stock:</b> New original, 2670 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>
<p><b>RFBLN2012090A1T</b> <b>Description:</b> BALUN 2.4GHZ-2.5GHZ 50/100 6SMD <b>Manufacturers:</b> Walsin Technology <b>In Stock:</b> New original, 106000 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p><b>0850BM14E0016T</b> <b>Description:</b> JOHANSON SMD <b>Manufacturers:</b> JOHANSON <b>In Stock:</b> New original, 2633 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p><b>LDM181G9310CC001</b> <b>Description:</b> BALUN 1.71-2.155GHZ 50/100 0603 <b>Manufacturers:</b> Murata Electronics <b>In Stock:</b> New original, 67100 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>
<p>IMAGE NOT AVAILABLE</p> <p><b>259A9872P2</b> <b>Description:</b> 259A9872P2 DIP 99 <b>Manufacturers:</b> DIP <b>In Stock:</b> New original, 2677 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p>IMAGE NOT AVAILABLE</p> <p><b>2597M-3.3</b> <b>Description:</b> 2597M-3.3 NS SOP8 <b>Manufacturers:</b> NS <b>In Stock:</b> New original, 2606 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>	<p><b>2595FB39A0050T</b> <b>Description:</b> 2595FB39A0050T JOHANSON SMD <b>Manufacturers:</b> JOHANSON <b>In Stock:</b> New original, 96000 pcs Stock Available. Quote: <input type="text" value="RFQ"/></p>



**IC Components Limited**  
WWW.IC-COMPONENTS.COM

Email: [Info@IC-Components.com](mailto:Info@IC-Components.com)  
TEL: 00 852 - 30501935  
FAX: 00 852 - 30501945

Address: 6H Block 1, Sherwood Court, Kingswood Villa, Tin Shui Wai, New Territories, Hong Kong